



Publ. number	Issue Date	TC Holder	Type	Subject
2024-0037-E	2024-02-02	AUSTRO ENGINE GMBH	E4	Engine - Main Bearing / Studs - Replacement
ISR-I-57-2021-12-4R1	2024-02-01	GULFSTREAM (GALP)	G200	Wings - Flaps - Fairing Seal Repair
2024-0031	2024-02-01	AIRBUS S.A.S.	A318, A319, A320, A321	[Correction] Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitations Items - Amendment
ISR-I-57-2021-12-3R1	2024-02-01	GULFSTREAM (GALP)	G150	Wings - Flaps - Fairing Seal Repair
2024-0030	2024-01-31	AIRBUS S.A.S.	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment
2024-0032	2024-01-31	AIRBUS S.A.S.	A380	Fuselage - Centre Fuselage Shims on Frames 47 to 53 - Inspection
2024-0033	2024-01-31	DASSAULT AVIATION	Falcon 7X	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0035	2024-01-31	DASSAULT AVIATION	Falcon 900EX	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0036	2024-01-31	DASSAULT AVIATION	Mystère-Falcon 900	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0034	2024-01-31	DASSAULT AVIATION	Falcon 900EX	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0029	2024-01-29	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 7000	Engine Oil - Lubrication / Scavenge Oil Pumps - Installation Criteria
CF-2024-03	2024-01-26	BELL TEXTRON CANADA LTD (BTCL)	505 (Jet Ranger X)	Empennage Structure - Vertical Stabilizer Top End Cap Assembly Cracking
2024-0028-E	2024-01-25	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Tail Rotor - Tail Rotor Blades - Inspection
2024-0027	2024-01-25	AIRBUS S.A.S.	A319, A320, A321	Wings - Bottom Wing Skin Panel 2 - Inspection
BR-2023-07-01	2024-01-25	EMBRAER	EMB-505 (Phenom 300)	[Correction] Equipment / Furnishings - Refreshment Center and Forward Cabinet - Modification
2024-0026	2024-01-24	CFM INTERNATIONAL	LEAP-1A/-1C	Engine - High Pressure Turbine - Rotor Interstage Seal - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2024-0024	2024-01-24	APPLIANCES	ATA 34 NAVIGATION	THOMMEN AIRCRAFT EQUIPMENT AG: Navigation - Digital Air Data Computer - Replacement
2024-0025	2024-01-24	ATR, SABENA TECHNICS BGC	ATR42, ATR72, EASA STC 10069551, EASA STC 2004-2872	Placards and Markings - Cargo Height Limitation - Implementation / Cargo Loading Procedure - Amendment
2024-0022	2024-01-23	AIRBUS S.A.S.	A319, A320, A321	Landing Gear - Nose Landing Gear - Repair Assessment
CF-2024-02	2024-01-23	DIAMOND AIRCRAFT INDUSTRIES	DA 62	Stabilizers - Horizontal Stabilizer - Incorrect Torque Specified for Attachment Bolts
2024-0023	2024-01-23	AIRBUS S.A.S.	A330	Equipment / Furnishings - Galley 4 Aft Bulkhead Cover Panel - Replacement