



Publ. number	Issue Date	TC Holder	Type	Subject
US-2022-06-07	2022-04-29	BOEING	777	Fuselage - Forward Outer Chords of the Pivot Bulkhead - Inspection
2022-0076	2022-04-29	SCHEMPP HIRTH FLUGZEUGBAU	Arcus, Ventus Powered Sailplanes	Aircraft Flight Manual - Amendment
2022-0077-E	2022-04-29	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND	AS 350 / EC 130, AS 355, EC135/635, MBB-BK 117	Rotors Flight Control - Flight Control Flexball Cables - Replacement
2022-0044R1	2022-04-29	SOLO KLEINMOTOREN GmbH	2350	Engine - Modification / Inspection
US-2022-09-13	2022-04-28	PIPER AIRCRAFT INC.	PA-34 (Seneca)	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2022-0075	2022-04-28	AIRBUS S.A.S.	A380	Landing Gear - Body Landing Gear Rear Axle - Replacement
BR-2022-04-01	2022-04-28	EMBRAER S.A.	ERJ 170	Flight Controls - Electrical Harnesses W126 and W127 - Inspection
BR-2022-04-02	2022-04-28	EMBRAER S.A.	ERJ 190	Landing Gear - Shear Pin Lockwires - Inspection / Modification
2022-0074	2022-04-27	CFM INTERNATIONAL	LEAP-1B	Engine - Transfer Gearbox Module Scavenge Screens - Inspection / Modification
US-2022-08-06	2022-04-27	GENERAL ELECTRIC	CF34-8	Engine - Compressor Inlet Guide Vane Outer Shroud Bushing and Vane Spindle Bushing - Inspection / Replacement
2022-0073	2022-04-27	DASSAULT AVIATION	Falcon 7X	Electrical Power - Direct Current Load Distribution / Right-Hand Front Secondary Power Distribution Box Feeder - Inspection / Modification
CF-2022-22	2022-04-26	PRATT & WHITNEY CANADA	PW308	Engine - Combustion Chamber Outer Case - Inadequate Fatigue Life of Forward Flange Bolts
2022-0072	2022-04-26	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Doors - VIP Flap Doors / Emergency Jettisoning System - Placard Installation
2022-0071	2022-04-26	CFM INTERNATIONAL	LEAP-1B	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2022-07-06	2022-04-26	BOEING	747	Instruments - Electronic Flight Instrument System Interface Unit - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
G-2022-0009	2022-04-25	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	SURVITEC GROUP LIMITED - Lifejackets Type 102 Mk 3 and Mk 4, Type 105 Mk 1 - Inspection
CF-2022-21	2022-04-25	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Stabilizers - Horizontal Stabilizer to Vertical Stabilizer Joint - Non-Conforming Saddle Washer (Radius Filler)
CF-2022-23	2022-04-22	AIRBUS CANADA LP	BD-500 (A220 Series)	Equipment / Furnishings - Removal of Inflation Valve Safety Pin from Passenger and Service Door Escape Slides
US-2022-07-07	2022-04-22	BOEING	757	Equipment / Furnishings - Passenger Service Units, Life Vest Panels and Video Panel Lanyard Assemblies - Installation
2016-0004R1	2022-04-22	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine Fuel & Control - Hydro-Mechanical Metering Unit - Inspection
2014-0213R1	2022-04-22	AIRBUS S.A.S.	A380	Fuselage - Section 19 Upper Cross Fitting Upper Beam Inner Cap Joints - Inspection
CF-2022-18	2022-04-21	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
CF-2022-20	2022-04-21	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Fire Protection - Fire Extinguisher - Replacement of the Cargo Bay Fire Extinguisher Container Pressure Switch/Gauge Assembly
US-2022-07-03	2022-04-21	BELL TEXTRON INC. (BTI), BLR AEROSPACE	412, EASA STC 10045079, FAA STC SR09535RC-D	Rotors Flight Control - Collective Lever - Replacement / Life Limitation
2022-0070	2022-04-21	FOKKER SERVICES	F28	Fuselage - Stubwing Bay Area Skin - Inspection
US-2022-07-13	2022-04-20	PRATT & WHITNEY	PW4070, PW4080, PW4090	Engine Oil - Air/Oil Heat Exchanger - Inspection / Replacement
CF-2022-19	2022-04-20	BOMBARDIER	BD-100	Auxiliary Power Unit - Tailcone Upper Firewall Cracking
2022-0069	2022-04-19	AIRBUS HELICOPTERS	AS 355	Tail Rotor Drive - Fan Assembly - Inspection