



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0086	2022-05-13	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Rotors Flight Control - Tail Rotor Actuator - Inspection
CF-2007-10R2	2022-05-13	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Flight Controls - Flaps Failure
G-2022-0010-E	2022-05-13	APPLIANCES	ATA 28 FUEL SYSTEM	CAMERON / ALUGAS - CB2990 Fuel Cylinders - Temporary Withdrawal from Service
BR-2022-05-02	2022-05-13	EMBRAER S.A.	ERJ 170	Wing Tip Connections - Inspection / Airworthiness Limitations - Update
2021-0044R1	2022-05-12	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Electrical Power - Overhead Panel - Inspection
2022-0085	2022-05-12	AIRBUS S.A.S.	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Part 2 - Damage Tolerant Airworthiness Limitation Items - Implementation
2022-0084	2022-05-11	LEONARDO S.p.A. HELICOPTERS	AB212/AB412	Fuselage - Tailboom / Fin Spar Cap - Inspection
2022-0083	2022-05-11	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2022-08-14	2022-05-10	BOEING	747	Fuselage - Crown Stringers - Inspection
2022-0082	2022-05-10	AIRBUS S.A.S.	A318, A319, A320, A321	Time Limits / Maintenance Checks - Safe Life Airworthiness Limitations Section Part 1 - Amendment
2018-0226-CN	2022-05-10	AIRBUS S.A.S.	A330, A340	CANCELLED: Stabilizers - Horizontal Stabilizer Centre Box Top Skin - Inspection / Repair
2022-0080	2022-05-09	AIRBUS S.A.S.	A350	Wings - Centre Wing Box Fasteners - Replacement
2020-0075-CN	2022-05-09	GULFSTREAM AEROSPACE CORPORATION	GVII	CANCELLED: Airplane Flight Manual - Sections Limitations / Procedures - Amendment
US-2022-10-05	2022-05-09	GULFSTREAM AEROSPACE CORPORATION	GVII	Airplane Flight Manual - Sections Limitations and Procedures - Amendment
US-2022-08-12	2022-05-09	BOEING	757	Wings - Wing Skin / Shim - Inspection
US-2022-10-04	2022-05-09	ENGINE ALLIANCE LLC	GP7200	Engine - Stages 7-9 Compressor Rotor Spool - Replacement
2019-0138R1	2022-05-09	AIRBUS S.A.S.	A330, A340	[Correction] Stabilizers - Elevators - Inspection
CF-2022-25	2022-05-05	BOMBARDIER	BD-700	Landing Gear - Introduction of New Brake Accumulator Life Limit
2022-0079-E	2022-05-05	AIRBUS S.A.S.	A350	Aircraft Flight Manual - Section Limitations / Normal Procedures - Amendment / Flight Controls - Master Minimum Equipment List - Amendment
2022-0078	2022-05-04	AIRBUS S.A.S.	A300-600, A310	Fuselage - Door Frames Holes - Inspection
CF-2022-24	2022-05-03	BOMBARDIER	BD-100	Flight Controls - Stabilizer Trim Switch Failure