



Publ. number	Issue Date	TC Holder	Type	Subject
US-2022-10-02	2022-05-25	HONEYWELL INTERNATIONAL INC.	T5311, T5313, T5317	Engine Controls - Reduction Gearbox Assembly - Vibration Tests
2022-0094	2022-05-25	AIRBUS S.A.S.	A380	Pneumatic - Air Conditioning / Engine Bleed Air System - Software Update Airplane Flight Manual / Master Minimum Equipment List - Air Conditioning / Engine Bleed Air System - Amendment Pneumatic - Engine Bleed Air Supply Over-pressure Valve - Replacement Ice and Rain Protection - Anti-ice Control Unit - Replacement
2022-0093	2022-05-25	AIRBUS S.A.S.	A350	Fuselage - Fasteners at Frame 96 Stringer 6 and 7 on Right Hand Side - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0129R1	2022-05-25	ROLLS-ROYCE DEUTSCHLAN D Ltd & Co KG	RB211 TRENT 900	Engine Fuel & Control - Low Pressure Compressor Case Static P30 Air System - Modification
US-2022-06-06	2022-05-24	BOEING	737	Flight Controls - Rudder Pedal Cover Assembly Fasteners - Modification
US-2022-09-18	2022-05-24	BOEING	707, 717, 727, DC-10, DC-8, DC-9, MD-10, MD-11	Aircraft Flight Manual - Limitations / Operating Procedures - Amendment
2022-0092	2022-05-24	WSK PZL-SWIDNIK S.A.	PZL W-3A	Engine - Vibration Levels - Measurement
BR-2022-05-03	2022-05-23	EMBRAER S.A.	ERJ 170	Navigation - Primary Flight Displays - Software Installation
BR-2022-05-04	2022-05-23	EMBRAER S.A.	ERJ 190	Navigation - Primary Flight Displays - Software Installation
US-2022-09-14	2022-05-23	GENERAL ELECTRIC	CF34-8	Air - Operability Bleed Valve - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
US-2022-08-10	2022-05-20	HAMILTON SUNDSTRAN D	54H	Propellers - Blades - Inspection / Replacement
CF-2022-27	2022-05-20	PRATT & WHITNEY CANADA	JT15D	Engine - Compressor Section - Impeller Fracture due to Machining Step
2015-0226R7	2022-05-20	AIRBUS HELICOPTER S, AIRBUS HELICOPTER S DEUTSCHLAN D, BELL TEXTRON CANADA LTD (BTCL), BELL TEXTRON INC. (BTI), LEONARDO S.p.A. HELICOPTER S, MD HELICOPTER S INC (MDHI), SIKORSKY	SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB-BK 117, 429, 430, 212, 214, 412, A109/A119, AB139/AW139, AB212/AB412, MD900, S-61, S-76, S-92	Equipment / Furnishings - Hoist - Test / Replacement
2021-0107R2	2022-05-20	PIPER AIRCRAFT INC.	PA-28 (Archer), PA-28 (Cadet), PA-28 (Cherokee), PA-28 (Warrior), PA-28R (Arrow), PA-32 (Cherokee Six), PA-32R (Lance)	Wings - Lower Main Wing Spar Caps - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0091	2022-05-20	AIRBUS S.A.S.	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 / Certification Maintenance Requirements - Amendment
2022-0090	2022-05-18	AIRBUS S.A.S.	A321	Doors - Airbus Cabin Flex / Overwing Emergency Exit Slide Release Mechanism - Inspection
CF-2022-26	2022-05-18	PRATT & WHITNEY CANADA	PT6E-60	Engine Bleed Air - Bleed-Off Valve Failure to Close
2019-0207R1	2022-05-18	AIRBUS S.A.S.	A350	Doors - Passenger / Crew Door Girt Bar Fitting Assemblies - Inspection
US-2022-08-05	2022-05-17	BOEING	737	Fuselage - Lower Lobe Electronic Equipment Bay Sealant - Inspection
2022-0088	2022-05-17	AIRBUS S.A.S.	A350	Hydraulic Power - Yellow Fire Shut Off Valve Grounding Wiring - Modification



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0089	2022-05-17	AIRBUS S.A.S.	A321	Power Plant - Aft Engine Mount Secondary Load Path - Inspection
2022-0087	2022-05-16	AIRBUS HELICOPTER S	SA 330 / AS 332 / EC 225	Fuel - Engine Fuel Supply Hoses - Inspection / Modification / Re-tightening
2020-0236-CN	2022-05-16	AIRBUS S.A.S.	A318, A319, A320, A321	CANCELLED: Equipment / Furnishings - Emergency Escape Slide / Raft Inflation Reservoir - Pressure Check
CF-2021-22R1	2022-05-16	AIRBUS CANADA LP	BD-500 (A220 Series)	Landing Gear - Main Landing Gear Lower Spindle Pin Corrosion