



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2024-21	2024-06-07	AIRBUS CANADA LP	BD-500 (A220 Series)	Cargo and Accessory Compartments - Environmental Control System Ducts - Flammability Non-Compliance
CF-2024-19	2024-06-07	BOMBARDIER	CL-600 (Challenger)	Flight Controls - Pitch-up on Landing When Using Thrust Reversers in Partial Flap Configurations
CF-2024-20	2024-06-06	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel - Engine Feed Check Valve Failures
2024-0110	2024-06-06	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Rotors Flight Controls - Upper Ball Bearing End of the Main Rotor Servo-Controls - Inspection
2024-0109-CN	2024-06-06	LEONARDO S.p.A. HELICOPTERS	AB206	CANCELLED: Flight Controls - Tail Rotor Control Tube - Inspection / Replacement
2024-0107	2024-06-03	AIRBUS HELICOPTERS DEUTSCHLAND, MECAER AVIATION GROUP SpA	MBB-BK 117, EASA STC 10051018	Equipment / Furnishings - Medical Equipment Support - Inspection
2024-0106	2024-05-31	AIRBUS S.A.S.	A319, A320, A321, A330, A350, A380	Cabin Systems - Antenna Adapter Plate - Inspection
CF-2024-18	2024-05-30	BELL TEXTRON CANADA LTD (BTCL)	407	Rotors Flight Control - Cyclic Stick Tube Cracking
2024-0105	2024-05-30	AIRBUS S.A.S.	A319	Fuselage - Potable and Waste Water Service Panels - Modification
2024-0091R1	2024-05-30	AIRBUS S.A.S.	A319, A320, A321	Aircraft Flight Manual / Section Limitations - Amendment / Auto Flight - New Flight Guidance Standard - Modification
CF-2024-15	2024-05-29	APPLIANCES	ATA 31 INSTRUMENTS, ATA 34 NAVIGATION	NOT ELIGIBLE FOR ADOPTION - EASA POSITION ATTACHED
CF-2024-14	2024-05-29	APPLIANCES	ATA 31 INSTRUMENTS, ATA 34 NAVIGATION	NOT ELIGIBLE FOR ADOPTION - EASA POSITION ATTACHED
US-2024-07-01	2024-05-29	HAMILTON SUNDSTRAND	14SF	Propellers - Auxiliary Motor and Pump - Replacement
BR-2024-05-09R1	2024-05-29	EMBRAER S.A.	ERJ 170	Main Landing Gear Locking-Stay Bracket Assembly - Inspection / Replacement
2023-0111R1	2024-05-28	AIRBUS S.A.S.	A330	Aircraft Flight Manual - Sections Limitations and Normal Procedures - Amendment / Master Minimum Equipment List - Amendment / Pneumatic - High Pressure Valve - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2024-04-03R1	2024-05-27	EMBRAER S.A.	EMB-135, EMB-145	Fuselage - Upper Central Fuselage II, III, and IV Longitudinal Splices - Inspections
BR-2024-04-02R1	2024-05-27	EMBRAER S.A.	EMB-120	Fuselage - Center I Longitudinal Skin Splices Frames 22 and 23 - Inspections