



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0122	2022-06-24	AEROLITE AG, PILATUS AIRCRAFT LTD	EASA STC 10067483, PC-24	Equipment / Furnishings - Stretcher Trolley Installation - Modification
2022-0121	2022-06-23	AIRBUS HELICOPTERS	EC175	Fire Protection - Engine Fire Control Panel - Modification
US-2022-10-11	2022-06-23	BOEING	747	Wings - Fuel Tank Fasteners - Inspection / Maintenance Program Revision
US-2022-10-06	2022-06-23	ROLLS-ROYCE CORPORATION (USA)	250 Series II	Engine - Stage 3-4 Turbine Wheels - Replacement
2022-0120	2022-06-23	AIRBUS S.A.S.	A318, A319, A320, A321	Equipment / Furnishings - 80VU Rack Attachments - Inspection / Repair
CF-2022-33	2022-06-22	BELL TEXTRON CANADA LTD (BTCL)	206	Tail Rotor Drive - Failure of Tail Rotor Drive Shaft with Bonded Adapters
US-2022-11-05	2022-06-22	BOEING	777	Wings - Rear Spar Outboard Flap Support Fasteners and Shims - Inspection / Replacement
2022-0117	2022-06-21	SAFRAN HELICOPTER ENGINES	RTM 322	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2022-0118	2022-06-21	SAFRAN HELICOPTER ENGINES	RTM 322	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2022-11-04	2022-06-21	SIKORSKY	S-92	Horizontal Stabilizer Forward Root / Strut Fittings - Life Limit / Inspection
CF-2022-34	2022-06-21	BOMBARDIER	CL-600 (Challenger), EASA STC 10016019, STC EASA.IM.A.S.02186, TCCA STC SA06-90	Oxygen - Supply System Flexible Oxygen Hose Deterioration Over Time
2022-0116	2022-06-21	AIRBUS S.A.S.	A300	Hydraulic Power - Hydraulic System Reservoirs Pressurization - Functional Check
2022-0119	2022-06-21	AIRBUS S.A.S.	A350	Air Conditioning - Forward Cargo Compartment Bracket Surface Protection - Modification
G-2022-0013	2022-06-20	BAE SYSTEMS (OPERATIONS) LTD	ATP	Oxygen - Crew Oxygen Masks - Overhaul
G-2022-0012	2022-06-20	BAE SYSTEMS (OPERATIONS) LTD	ATP	Indicating / Recording Systems - Flight Data Recording System - Check
US-2022-12-12	2022-06-20	PRATT & WHITNEY	PW4000	Engine - Low Pressure Turbine Stage 5 Air Seal - Replacement
2022-0115	2022-06-20	AIRBUS S.A.S.	A319, A320, A321	Fuselage - Cargo Compartment Fitting Brackets, Tack and Rivet Holes - Inspection / Repair



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0113	2022-06-17	CFM INTERNATIONAL	LEAP-1A/-1C	Engine - Stages 6-10 Compressor Rotor Spools and High Pressure Turbine Rotor Stage 1 Disks - Replacement
US-2022-12-08	2022-06-17	ROBINSON HELICOPTER COMPANY	R22, R44 (Raven)	Flight Controls - Engine Revolutions per Minute (RPM) Indicating System - Inspection / Installation
2022-0112	2022-06-17	AIRBUS S.A.S.	A350	Oxygen - Passenger Oxygen Masks - Replacement
2022-0110	2022-06-15	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	BR700-710	Engine - Low Pressure Compressor Rotor (Fan) Disc - Inspection
2022-0109	2022-06-15	SONACA AIRCRAFT S.A.	S2	Flight Controls - Elevator Long Pushrod - Inspection / Replacement
2022-0111	2022-06-15	AIRBUS S.A.S.	A319, A320, A321	Wings - Overwing Panel / Lug Attachment - Inspection
CF-2022-32	2022-06-14	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Fire Protection - Fire Extinguishing System - Fire Extinguisher Bottle Tests Omitted (Cargo / Engine / Auxiliary Power Unit)