



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0191R1	2022-07-22	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Equipment / Furnishings - Forward Facing Central Seat(s) - Removal
2022-0150	2022-07-21	AIRBUS HELICOPTERS	AS 350 / EC 130	Tail Rotor - Blades - Inspection
2022-0149	2022-07-21	DAHER AEROSPACE	TBM 700	Pilot's Operating Handbook - Emergency Procedures - Amendment / Equipment / Furnishings - Emergency Exit Door Panel - Modification
CF-2022-39	2022-07-19	BOMBARDIER	BD-700	Pneumatic - Discrepant Fastener Used in Pre-Cooler Clamp Installation
US-2022-13-04	2022-07-19	BOEING	757	Fuselage - Fuselage Frame Inner Chord - Inspection
2022-0009R1	2022-07-19	CFM INTERNATIONAL	LEAP-1A/-1C	Engine - High Pressure Turbine Rotor Stage 1 Blade - Inspection
CF-2022-38	2022-07-14	BOMBARDIER	BD-700	Pneumatic - Non-Conforming Bleed Leak Detection System Sensing Elements
2022-0148	2022-07-14	LEONARDO S.p.A. HELICOPTERS	A109/A119	Electrical Power - Starter-Generator Drive Shaft - Inspection
2022-0147	2022-07-14	AIRBUS S.A.S.	A318, A319, A320, A321	Pneumatic - Overheat Detection System Sensing Elements - Inspection
2021-0163-CN	2022-07-14	BELL TEXTRON INC. (BTI)	212, 412	CANCELLED: Fuel / Oil - Check Valves - Inspection / Replacement
CF-2022-37	2022-07-12	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Auto Flight System - Airplane Flight Manual (AFM) Limitations and Abnormal Procedures - Velocity Decay during Low Level ALT CAP in One Engine Inoperative Conditions
BR-2022-06-01	2022-07-12	EMBRAER S.A.	ERJ 190	[Correction] Overwing Emergency Exit Door Lower Beam Splice Fasteners - Inspection / Rework / Replacement
2022-0145	2022-07-12	DASSAULT AVIATION	Falcon 7X	Navigation - EASy Avionics Architecture / Modification Aircraft Flight Manual - Amendment Master Minimum Equipment List - Amendment / Implementation Operational Suitability Manual - Flight Crew - Amendment / Implementation
2022-0146	2022-07-11	SCHLEICHER, ALEXANDER	ASW 15	Wings - Root Ribs - Inspection
2022-0144	2022-07-11	DASSAULT AVIATION	Falcon 900EX	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment