



Publ. number	Issue Date	TC Holder	Type	Subject
US-2023-11-11	2023-08-04	BOEING	747	Fuselage - Pressure Bulkhead Stringer Sidewalls / Assemblies - Inspection
2018-0126R1	2023-08-04	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine - Low Pressure Turbine Disc Seal Fins and Interstage Seals - Inspection / Replacement / Modification
2021-0281R1	2023-08-03	AIRBUS S.A.S.	A330	Aircraft Flight Manual / Engine Bleed Air System - Amendment / Pneumatic - Engine Bleed Air System - Maintenance Tasks
US-2023-13-09	2023-08-02	BOEING	767	[Correction] Limit Switch and Position Transmitter Module - Repetitive Inspections
2023-0158	2023-08-02	AIRBUS S.A.S.	A330, A340	Airborne Auxiliary Power - Auxiliary Power Unit Scroll Housing Assembly - Replacement
2023-0156-E	2023-08-02	BRP-ROTAX GmbH & Co KG	912 A, 912 F, 912 S, 912 iSc, 914 F	Engine - Propeller Gearbox / Magnetic Plug - Inspection / Propeller Shaft - Replacement
CF-2023-16R1	2023-08-02	BELL TEXTRON CANADA LTD (BTCL)	505 (Jet Ranger X)	Engine - Fuel and Control - Change of Flight Manual Limitations
CF-2023-57	2023-07-31	AIRBUS CANADA LP	BD-500 (A220 Series)	Equipment/Furnishings - Emergency - Replacement and Relocation of the Wardrobe Personal Locator Beacon
2023-0155	2023-07-31	AIRBUS HELICOPTERS	SA 341/342	Main Rotor - Main Rotor Blade Leading Edge Protection - Inspection
2023-0157	2023-07-31	AIRBUS S.A.S.	A350	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements - Amendment
CF-2023-58	2023-07-31	AIRBUS CANADA LP	BD-500 (A220 Series)	Fire Protection - Fire Extinguishing System (FIREX) - Line Fouling with Hi-Lite Fasteners
2022-0120R2	2023-07-28	AIRBUS S.A.S.	A318, A319, A320, A321	Equipment / Furnishings - 80VU Rack Attachments - Inspection / Repair
2020-0179R1	2023-07-28	EMBRAER S.A.	ERJ 170, ERJ 190	Fuselage - Forward Pressure Bulkhead - Inspection / Repair
CF-2023-59	2023-07-27	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel - Engine Feed Check Valve Failures
2023-0154	2023-07-27	AIRBUS HELICOPTERS	AS 355	Stabilizers - Vertical Upper Fin Assembly - Inspections
BR-2020-01-02R2	2023-07-26	EMBRAER S.A.	ERJ 170, ERJ 190	Nacelles / Pylons - Engine Inboard and Outboard Pylon Lower Link Lugs - Inspection / Repair
2022-0111R1	2023-07-26	AIRBUS S.A.S.	A319, A320, A321	Wings - Overwing Panel / Lug Attachment - Inspection
2023-0153	2023-07-26	AIRBUS S.A.S.	A320, A321	Fuselage - Cargo Door Frame Attachment Drillings - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
2023-0151	2023-07-25	AIRBUS S.A.S.	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitations Items - Amendment
2023-0152	2023-07-25	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	BR700-715	Engine - Low Pressure Compressor Booster Rotor - Inspection
CF-2023-56	2023-07-25	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Equipment/Furnishings - Overhead Storage Compartments - Improvement of the Overhead Bin Harnesses Over the Class Divider
CF-2023-53	2023-07-25	BOMBARDIER	BD-700	Electrical Power - Transformer Rectifier Unit (TRU) Fan Inoperative
CF-2023-55	2023-07-25	BOMBARDIER	CL-600 (Challenger)	Fuel - Fouling Condition between Fuel Scupper Attachment Bolt and Wire Harness