



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2023-08-03	2023-08-31	EMBRAER	EMB-545/-550 (Legacy 500)	Windows - Cockpit Side Windows - Inspection / Replacement
2023-0168	2023-08-31	AIRBUS HELICOPTERS	SA 341/342	Tail Rotor Drive - Transmission Inclined and Horizontal Drive Shaft - Inspection
2023-0167	2023-08-30	AIRBUS S.A.S.	A330, A340	Landing Gear - Main Landing Gear Axles - Inspection
CF-2023-62	2023-08-28	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Navigation - Radio Altimeter System - Introduction of a Radio Frequency Filter to Decrease Risk of Interference from 5G C-Band Wireless Telecommunication Service on the Radio Altimeter System When Operating in the Contiguous United States Airspace
US-2023-13-12	2023-08-28	BOEING	737, 757, 767	Oxygen - Chemical Oxygen Generators - Replacements
2023-0166	2023-08-25	AIRBUS HELICOPTERS	AS 350 / EC 130, EC 120 B, EC175	Equipment / Furnishings - Emergency Floatation System Supply Hose Connection / Retaining Ring - Inspection
GA8-3-Amdt3	2023-08-24	GA8 AIRVAN Pty Ltd (GippsAero)	GA8	Forward Cargo Door Slide - Inspection
CF-2023-61	2023-08-23	BOMBARDIER	BD-700	Exhaust - Thrust Reverser - Disbonded or Missing Pivot Door Seal on Fixed Structure
US-2023-16-07	2023-08-23	INTERNATIONAL AERO ENGINES LLC	PW1100 / PW1400	Engine - High-Pressure Turbine 1st / 2nd Stage Hub - Inspection
2023-0165	2023-08-22	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - Low Pressure Turbine Stage 1 Blade Assemblies - Inspection / Replacement