



Publ. number	Issue Date	TC Holder	Type	Subject
US-2022-17-03	2022-09-16	BOEING	747	Time Limits / Maintenance Checks - Airworthiness Limitations for Fuel Tank Safety - Amendment
US-2022-19-12	2022-09-16	ROBINSON HELICOPTER COMPANY	R44 (Raven), R66	Tail Rotor - Blades - Inspection / Removal
CF-2022-54	2022-09-15	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Fuselage - Forward Engine Support Frame Fuselage Station 1051.30 - Inspection
2022-0191	2022-09-15	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Rotors - Main Gearbox Oil Cooling Fan - Inspection / Replacement / Modification
2022-0190	2022-09-14	AIRBUS S.A.S.	A330	Nacelles / Pylons - Lower Aft Pylon Fairings - Inspection
2022-0188	2022-09-13	AIRBUS S.A.S.	A340	Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment
2022-0186	2022-09-13	AIRBUS S.A.S.	A350	Fuselage - Overhead Storage Compartment Crash Rods - Inspection
2022-0187	2022-09-13	AIRBUS S.A.S.	A330	Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment
2021-0291R1	2022-09-12	AIRBUS S.A.S.	A350	Doors - Passenger Door Stop Screw - Inspection
CF-2022-53	2022-09-08	BOMBARDIER	BD-700	Landing Gear - Brake Control System - Uncommanded Brake Pressure due to Brake Control Unit Failure
US-2022-18-04	2022-09-08	GENERAL ELECTRIC	GE <sub>n</sub> x	Engine Fuel & Control - Fuel Hydraulic Lines - Replacement
US-2022-14-05	2022-09-08	BOEING	777	Flight Controls - Elevators, Rudder, and Rudder Tab - Inspections and Lubrication
2021-0185R2	2022-09-07	APPLIANCES	ATA 26 FIRE PROTECTION	UMLAUT ENGINEERING GmbH - Hand-operated Fire Extinguishers - Inspection / Replacement
US-2022-18-03	2022-09-05	HONDA AIRCRAFT COMPANY LLC	HA-420	Ice and Rain Protection - Airplane Flight Manual and Quick Reference Handbook - Amendment
2022-0185	2022-09-05	AIRBUS S.A.S.	A319, A320, A321	Fuel - Engine Low Pressure Shut Off Valve Electrical Harness Routing - Modification