



Publ. number	Issue Date	TC Holder	Type	Subject
2023-0187	2023-10-27	AIRBUS HELICOPTERS	AS 350 / EC 130	Engine Controls - Microswitches - Inspection / Modification
2023-0186	2023-10-27	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 7000	Air - Intermediate / High Pressure Air Tubes - Inspection
CF-2020-29R1	2023-10-26	BOMBARDIER	BD-700	Flight Controls - Elevator Control System - Vertical Torque Tube Seizure - Sand Contamination of Bearing
US-2023-20-11	2023-10-25	INTERNATIONAL AERO ENGINES LLC	PW1100 / PW1400	Engine - High-Pressure Compressor Rear Hub - Replacement
CF-2023-72	2023-10-20	BOMBARDIER	BD-100	Equipment/Furnishings - Baggage Bay Sidewall Heater Mat - Excessive Heat
2023-0185	2023-10-20	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - Low Pressure Compressor Blades - Inspection / Replacement
2023-0184	2023-10-19	PILATUS AIRCRAFT LTD	PC-12	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2023-0183-E	2023-10-19	BRM AERO s.r.o.	Bristell B23	Powerplant - Engine Mass Ballast - Removal / Modification
CF-2023-69	2023-10-18	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
CF-2023-71	2023-10-18	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Equipment/Furnishings - Storage Compartment - Potential failure of Overhead Bins Attachments
2020-0262R1	2023-10-18	VULCANAIR S.p.A.	P.68	Flight Controls - Stabilator Trim Control Cable - Inspection / Replacement
CF-2023-70	2023-10-18	AIRBUS CANADA LP	BD-500 (A220 Series)	Standard Practices/Structures - Verification of Aircraft Repairs and Damage Assessments
US-2023-16-06	2023-10-17	HAMILTON SUNDSTRAND	14SF	Propellers - Auxiliary Motor and Pump - Replacement
2023-0182-E	2023-10-17	AIRBUS HELICOPTERS	EC175	Equipment / Furnishings - Rescue Hoist - Functional Check / Time Between Overhaul