



Publ. number	Issue Date	TC Holder	Type	Subject
US-2021-22-12	2021-11-12	HONDA AIRCRAFT COMPANY LLC	HA-420	Flight Controls - Flap Control Pushrods - Cleaning / Applying Corrosion Inhibiting Compound
CF-2021-39	2021-11-11	AIRBUS CANADA LP	BD-500 (A220 Series)	Doors - Emergency Exits - Overwing Emergency Exit Door Handle Cover - Opening Force Exceeds Design Limits
2021-0245	2021-11-10	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 800	Engine - Fuel Pump - Replacement / De-Pairing Limitation
US-2021-21-09	2021-11-09	BOEING	737	Fuselage - Aft Pressure Bulkhead - Repetitive Inspections
CF-2021-37	2021-11-09	PRATT & WHITNEY CANADA	PT6A-60	Engine Bleed Air - Bleed-Off Valve (BOV) Failure to Close
CF-2021-36	2021-11-09	BOMBARDIER	BD-700	Navigation - Head-up Display (HUD) and Synthetic Vision System (SVS) Misalignment
2021-0244	2021-11-09	WSK PZL-SWIDNIK S.A.	SW4	Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment
2021-0241	2021-11-08	AIRBUS	A318, A319, A320, A321	Wings - Front Spar Vertical Stringers - Inspection
2021-0243	2021-11-08	M&D FLUGZEUGBAU	JS-MD Single	Landing Gear - Tailwheel Cable - Modification
CF-2021-38	2021-11-08	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Air Conditioning - Ram Air System - Emergency Ram Air Valve (ERAV)
2021-0242	2021-11-08	AIRBUS	A318, A319, A320, A321	Fuselage - Door Stop Fitting Holes at Frame 66/68 - Inspection / Repair
US-2021-23-51	2021-11-05	GENERAL ELECTRIC	CF34-8	Engine / Air - Compressor Variable Geometry Actuator - Inspection
2021-0229	2021-11-05	AIRBUS	A318, A319, A320, A321	Wings - Outer Flaps and Tabs - Identification/ Inspection (Improper Heat Treatment) / Replacement (Wrong Material)
2021-0239	2021-11-05	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gearbox / Particle Detectors - Inspection / Modification / Replacement
2021-0240	2021-11-05	AIRBUS HELICOPTERS	EC175	Rotors Flight Control - Main / Tail Servo Control Systems - Replacement
CF-2021-34	2021-11-04	BELL TEXTRON CANADA LTD (BTCL)	407	Fuselage - Tailboom - Lower Skin Cracking
2021-0237-E	2021-11-04	ATR	ATR42, ATR72	Fire Protection - Engine Fire Handles Snap Wire - Inspection
G-2021-0014	2021-11-04	APPLIANCES	ATA 28 FUEL SYSTEM	CAMERON BALLOONS Ltd - Cylinder Quick Shut-off Valve Mounting Flange - Inspection / Replacement
2021-0110-CN	2021-11-03	PILATUS AIRCRAFT LTD	PC-12	CANCELLED: Landing Gear - Nose Landing Gear Fork Assembly - Inspection / Replacement
2021-0238	2021-11-02	LEONARDO S.p.A. HELICOPTERS	AW169	Fuel - Fuel Tank Vent Lines - Inspection