



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0033R1	2021-12-10	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Hydro-mechanical Metering Unit / Drive Link Splines - Inspection
US-2021-23-13	2021-12-10	APPLIANCES	ATA 34 NAVIGATION	NOT ELIGIBLE FOR ADOPTION - EASA POSITION ATTACHED
2021-0275	2021-12-10	AIRBUS	A350	Flight Controls - Slat Transmission Shafts / Slat Power Control Unit Torque Sensing Units - Inspection / Modification
CF-2021-46	2021-12-10	AIRBUS CANADA LP	BD-500 (A220 Series)	Exhaust - Non-Conforming Thrust Reverser Actuation System Deploy Hoses
US-2021-22-14	2021-12-10	PRATT & WHITNEY	PW4100	Engine - Low-Pressure Turbine - Replacement / Inspection
US-2021-23-12	2021-12-10	APPLIANCES	ATA 31 INSTRUMENT S, ATA 34 NAVIGATION	NOT ELIGIBLE FOR ADOPTION - EASA POSITION ATTACHED
2021-0274-E	2021-12-09	AUSTRO ENGINE GMBH	E4	Engine - High Pressure Pump Driving Gear - Inspection / Replacement
2018-0104R1	2021-12-08	AIRBUS HELICOPTER S	AS 350 / EC 130	Fuselage - Tail Boom / Fenestron Junction Frame - Inspection
2021-0273	2021-12-08	SAAB AB	340	Landing Gear - Main Landing Gear Torque Arm Centre Pin - Replacement
CF-2021-45	2021-12-08	BOMBARDIER	BD-700	Navigation - Radio Altimeter Coaxial Cable Damaged



Publ. number	Issue Date	TC Holder	Type	Subject
2015-0226R6	2021-12-08	AIRBUS HELICOPTER S, AIRBUS HELICOPTER S DEUTSCHLAN D, BELL TEXTRON CANADA LTD (BTCL), BELL TEXTRON INC. (BTI), LEONARDO S.p.A. HELICOPTER S, MD HELICOPTER S INC (MDHI), SIKORSKY	SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB-BK 117, 429, 430, 212, 214, 412, A109/A119, AB139/AW139, AB212/AB412, MD900, S-61, S-76, S-92	Equipment / Furnishings - Hoist - Test / Replacement
US-2021-23-08	2021-12-07	LEARJET, INC.	45	Wings - Center Wing Mid Spar Splice Plate - Repetitive Inspections
US-2021-23-11	2021-12-07	LEARJET, INC.	45	Powerplant System - Fuel Flow Meter Bracket Assembly - Replacement
CF-2021-42	2021-12-07	VIKING AIR LTD	DHC-6 (Twin Otter)	Engine Controls - Binding of Fuel Control Unit Push Rod End Bearings
2021-0272	2021-12-06	DASSAULT AVIATION	Falcon 7X	Aeroplane Flight Manual - Amendment; Oxygen - Crew Oxygen System / O2 Saver Function - Deactivation
2021-0271	2021-12-03	WSK PZL- SWIDNIK S.A.	PZL W-3A	Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment
2021-0270	2021-12-03	WSK PZL- SWIDNIK S.A.	PZL W-3A	Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment
2021-0269	2021-12-03	AIRBUS	A350	Fuselage - Ram Air Turbine Door / Belly Fairing Panels - Replacement
CF-2021-44	2021-12-03	AIRBUS CANADA LP	BD-500 (A220 Series)	Engine - Aircraft Flight Manual - Normal Procedure and Non-Normal Procedures



Publ. number	Issue Date	TC Holder	Type	Subject
G-2021-0012	2021-12-01	CAMERON BALLOONS, LINDSTRAND TECHNOLOGI ES	A Type, A Type Cloudhopper, B Type, C Type, Cameron Special Shape Hot Air Balloons, Gas Balloons, Helium-Hot Air Balloons, Hot Air Balloons, L Type, Lindstrand Special Shape Hot Air Balloons, S Type, Sky Hot Air Balloons, X Type, 203T HiFlyer, Series 1, Series 2, Series R, Series Special Shapes, TGB	NOT ADOPTED - EASA DECISION ATTACHED - SEE EASA AD 2021-0042
US-2021-21-05	2021-12-01	GENERAL ELECTRIC	GENx	Engine Controls - Electronic Engine Control MN4 Microprocessor - Replacement / Minimum Equipment List - Amendment
2020-0249R1	2021-11-30	ATR	ATR42, ATR72	Instruments - Angle of Attack Probe and Multi-Function Computers Electrical Routing - Operational Test / Inspection
2014-0076R3	2021-11-30	AIRBUS HELICOPTER S	AS 350 / EC 130, AS 355	Fuselage - Rear Structure Junction Frame Reinforcement Angles - Inspection
CF-2021-43	2021-11-30	AIRBUS CANADA LP	BD-500 (A220 Series)	Wings - Slat Track Corrosion and Wear
2019-0241R1	2021-11-29	POWERJET S.A.	SaM146	Engine - High Pressure Compressor and High Pressure Turbine Rotating Parts - Life Limit Reduction / Replacement