



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2021-53	2021-12-24	APPLIANCES	ATA 31 INSTRUMENTS, ATA 34 NAVIGATION	NOT ELIGIBLE FOR ADOPTION - EASA POSITION ATTACHED
CF-2021-52	2021-12-24	APPLIANCES	ATA 31 INSTRUMENTS, ATA 34 NAVIGATION	NOT ELIGIBLE FOR ADOPTION - EASA POSITION ATTACHED
2021-0290	2021-12-23	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	[Correction] Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2021-0289-E	2021-12-23	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Rotorcraft Flight Manual / Section 2 and 3 - Amendment
G-2021-0017	2021-12-22	BAE SYSTEMS (OPERATIONS) LTD	Jetstream 3100, Jetstream 3200	Flight Controls - Rudder and Elevator Flight Control Cable Terminals - Inspection
CF-2021-50	2021-12-22	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel - Distribution - Fuel Pressure Switch Missing Lockwire
2021-0291	2021-12-22	AIRBUS	A350	Doors - Passenger Door Stop Screw - Inspection
2021-0285	2021-12-21	AIRBUS	A380	Flight Controls - Aileron Servo Controls - Replacement
2021-0288	2021-12-21	AIRBUS	A300, A300-600	Fuselage - Frame 40 Rear Fitting at Stringer 27 - Inspection
2021-0287	2021-12-21	AIRBUS HELICOPTERS DEUTSCHLAND, MECAER AVIATION GROUP SpA	MBB-BK 117, EASA STC 10039815, EASA STC 10055175	Equipment / Furnishings - Seat Belt Restraint System - Inspection
G-2021-0016	2021-12-21	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Fuselage - Left Hand Nose Landing Gear Well Sidewall & Retraction Jack Attachment - Inspection
2021-0286	2021-12-21	AIRBUS, AIRBUS DEFENCE & SPACE S.A.	A330, EASA STC 10029272, EASA STC 10063084, EASA STC 10064192, EASA STC 10069256	Placards and Markings - Safety Placards for First Centre Row Passenger Seats - Installation



Publ. number	Issue Date	TC Holder	Type	Subject
2015-0226R6	2021-12-20	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND, BELL TEXTRON CANADA LTD (BTCL), BELL TEXTRON INC. (BTI), LEONARDO S.p.A. HELICOPTERS, MD HELICOPTERS INC (MDHI), SIKORSKY	SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB- BK 117, 429, 430, 212, 214, 412, A109/A119, AB139/AW139, AB212/AB412, MD900, S-61, S- 76, S-92	[Correction] Equipment / Furnishings - Hoist - Test / Replacement
2021-0282	2021-12-17	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Tail Rotor - Tail Rotor Head Pitch Change Unit Bearing Spacer - Marking / Check
2021-0280	2021-12-17	AIRBUS	A380	Pneumatic - Pylon / Wing Interface Bleed Duct and Fuel Pipe - Inspection
2021-0281	2021-12-17	AIRBUS	A330	Aircraft Flight Manual / Engine Bleed Air System - Amendment / Pneumatic - Engine Bleed Air System - Maintenance Tasks
2021-0284	2021-12-17	AIRBUS	A380	Engine Fuel & Control - Electronic Engine Control Software - Update
2021-0283-E	2021-12-17	AIRBUS HELICOPTERS	AS 350 / EC 130	Fuselage - Rear Transmission Bearing Support - Inspection
US-2021-24-15	2021-12-16	AIR COMM CORPORATION, BELL TEXTRON CANADA LTD (BTCL)	CAA UK AAN 25273, FAA STC SH2750NM, 206	Tail Rotor Drive - Oil Cooler Blower Shaft Drive Ring Spline Teeth and Mating Area Spline Teeth - Inspection
CF-2021-48	2021-12-16	BOMBARDIER	BD-700	Fire Protection - Missing Final Torque Value for Baggage Compartment Fire Extinguishing Tube Assembly
US-2021-22-11	2021-12-16	MD HELICOPTERS INC (MDHI)	369, 500N, 600N	Rotors Flight Control - Pilot-to-Copilot Tail Rotor Torque Tube - Inspection / Removal
2021-0279	2021-12-15	AIRBUS	A318, A319, A320, A321	Equipment / Furnishings - Doghouse Placard - Installation



Publ. number	Issue Date	TC Holder	Type	Subject
US-2021-26-02	2021-12-15	GULFSTREAM AEROSPACE CORPORATION	GV	Landing Gear System - Airworthiness Limitations Section of the Maintenance Manual - Revision
US-2021-23-51	2021-12-15	GENERAL ELECTRIC	CF34-8	[Final Rule] Engine / Air - Compressor Variable Geometry Actuator - Inspection
2021-0278-E	2021-12-15	STEMME AG	S10, S12	Powerplant - 12AK Clutch - Prohibition of Flights
US-2021-26-01	2021-12-15	BELL TEXTRON CANADA LTD (BTCL), S-TEC CORPORATION	505 (Jet Ranger X), FAA STC SR09758DS	Rotors Flight Control - Tail Rotor Control Cable - Inspection / Removal / Modification
2021-0277	2021-12-14	AIRBUS, AIRBUS DEFENCE & SPACE S.A.	A330, EASA STC 10029272, EASA STC 10063084, EASA STC 10064192, EASA STC 10064600, EASA STC 10069256	Fuselage - Aft Pressure Bulkhead - Inspection / Indicating / Recording Systems - Digital Flight Data Recorder Hood Assembly - Replacement
US-2021-22-23	2021-12-14	BOEING	757	Wings - Lower Aft Wing Skin Bolt Holes - Repetitive Inspections / Repair
G-2021-0014R1-E	2021-12-14	APPLIANCES	ATA 28 FUEL SYSTEM	CAMERON BALLOONS Ltd - Fuel - Cylinder Quick Shut-off Valve Mounting Flange - Inspection / Replacement
CF-2021-47	2021-12-14	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Fuselage - Pressure Floor Skin - Non Destructive Testing Manual CSP A-010 Part 6 Procedure Number 53-41-194
2021-0262	2021-12-13	AIRBUS	A340	Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment
2021-0276	2021-12-13	WSK PZL-SWIDNIK S.A.	PZL W-3A	Powerplant - Electrical Harness - Inspection / Repair / Replacement / Modification
BR-2021-12-01	2021-12-13	EMBRAER	EMB-545/-550 (Legacy 500)	Doors - Ram Air Turbine Compartment Door Seal - Replacement
US-2021-24-01	2021-12-13	PILATUS AIRCRAFT LTD, PILATUS BUSINESS AIRCRAFT Ltd	PC-12, EASA STC 10077020, FAA STC SA00634DE	Fuselage - Strake Attachment Brackets / Fuselage Frame - Inspection