

 INCREMENTAL CHANGE

Release Notification Date: 06/14/2022

SPM 70-00-99 S1219 - CONSUMABLE MATERIALS - SULPHURIC ACID ANODIZING HEXAVALENT CHROMIUM FREE SEALING SOLUTION

DISCLAIMER

The Incremental Changes published by GE Aviation are considered Instructions for Continued Airworthiness. These Incremental Changes, along with the current Manual revision and published Temporary Revisions, constitute the latest Instructions for Continued Airworthiness.

GE Designated: -CONFIDENTIAL-

The information contained in this document is GE proprietary information and is disclosed in confidence. It is the property of GE and shall not be used, disclosed to others or reproduced without the express written consent of GE, including, but without limitation, it is not to be used in the creation, manufacture, development, or derivation of any repairs, modifications, spare parts, designs, or configuration changes or to obtain FAA or any other government or regulatory approval to do so. If consent is given for reproduction in whole or in part, this notice and the notice set forth on each page of this document shall appear in any such reproduction in whole or part.

This technical data is considered subject to the Export Administration Regulations (EAR) pursuant to 15 CFR Parts 730-774. Transfer of this data by any means to a Non-U.S. Person, whether in the United States or abroad, without the proper U.S. Government authorization (e.g., License, exemption, NLR, etc.), is strictly prohibited.

Copyright (2022) General Electric Company, U.S.A.

HIGHLIGHTS

HIGHLIGHT REFERENCE DESCRIPTION OF CHANGE

tk70-00-99-801-818 Technical Change: Added Solution Sheet 1219 for a sulphuric acid anodizing hexavalent chromium free sealing solution.

TASK 70-00-99-801-818

1. Commercial Products.

- A. Socosurf TCS is an alternative solution to hexavalent chromium containing sealants applied after anodizing.

2. Composition.

Subtask 70-00-99-350-009

Consumable Product	No.	Concentration (Initial Mix)
Socosurf TCS	C03-124	31 - 41% V/V

3. Preparation

Subtask 70-00-99-350-010

WARNING: REFER TO THE PRODUCT LABEL AND THE MANUFACTURER'S (MATERIAL) SAFETY DATA SHEET (SDS) FOR INSTRUCTIONS ON THE HAZARDS, STORAGE, SAFE HANDLING AND PROPER USE OF THIS PRODUCT.

WARNING: OPERATOR SHOULD WEAR FACE SHIELD, GLOVES, PROTECTIVE CLOTHING, AND PROTECTIVE SHOES.

- A. Fill the bottom of the tank with demineralized water.
B. Add the required quantity of Socosurf TCS C03-124, top with demineralized water up to the optimal fill level and stir.
C. Prepared solution pH should be between 3.8 and 4 and as follows:
(1) Measure the pH when the bath is at operating temperature (35-45°C (95-113°F)).
D. If the pH is less than 3.8, use ammonia diluted to 5% to increase the pH, and if the pH is more than 4, use sulfuric acid diluted to 5% to decrease the pH.

4. Check.

Subtask 70-00-99-350-011

- A. Determine the concentration of bath parameters as follows:

Checks	Limits	Recommended Intervals
Socosurf TCS	31-41% v/v	Weekly
pH	3.8-4.0	Weekly

B. Follow the manufacturer's control procedures to maintain the solution.

5. Regeneration.

Subtask 70-00-99-350-012

A. If required, follow the manufacturer's regeneration procedures to maintain the solution.

GE Designated: - CONFIDENTIAL Subject to the restrictions on the media