



## MM - HIGHLIGHTS OF REVISION 4

PAGEBLOCK	LOCATION	DESCRIPTION OF CHANGE
05-21-00 MANDATORY ENGINE MAINTENANCE PROGRAM	05-21-00-300-803	Technical Change: Changed the Mandatory Engine Maintenance Program for the CT7-2E1 turboshaft engine model.
72-00-00 FADEC FAULT ISOLATION (CT7-2E1)	72-00-00-810-809	Technical Change: Added Labels 003-15 and 004-15 to the List of FADEC Messages in Table 101 for CT7-2E1 Modified to SB 74-0004. Also added Labels 003-25 and 003-26 to List of Status Word Messages in Table 102 for CT7-2E1 Modified to SB 74-0004.
72-00-00 ENGINE - TEST	72-00-00-760-803	Technical Change: Changed Table 501, Table 502, and Figure 502 to add engine operating limits for CT7-2E1 Modified to SB 74-0004.
72-00-00 ENGINE - TEST	72-00-00-760-803	Technical Change: Added metric equivalents throughout the pageblock where applicable.
72-36-00 COMPRESSOR STATOR ASSEMBLY - REMOVAL AND INSTALLATION	72-36-00-400-801	Technical Change: Changed the torque limits specified to assemble the compressor case fwd and aft flanges in paragraphs 3.B. and 3.C.
72-36-00 COMPRESSOR STATOR ASSEMBLY - REMOVAL AND INSTALLATION	72-36-00-400-801	Technical Change: Changed the WARNINGS throughout the pageblock to update to the latest format.
72-36-00 COMPRESSOR STATOR ASSEMBLY - REMOVAL AND INSTALLATION	72-36-00-400-801	Technical Change: Added metric equivalents throughout the pageblock where applicable.
72-36-00 COMPRESSOR STATOR ASSEMBLY - REMOVAL AND INSTALLATION	72-36-00-400-801	Technical Change: Removed references to REPAIR 002.
72-61-00 ACCESSORY DRIVE GEARBOX ASSEMBLY - INSPECTION	72-61-00-200-801	Technical Change: Changed the inspection of Axis-BB and Axis-G carbon seal mating rings in Table 603.
72-61-00 ACCESSORY DRIVE GEARBOX ASSEMBLY - INSPECTION	72-61-00-200-801	Technical Change: Changed the WARNINGS throughout the pageblock to update to the latest format.
72-61-00 ACCESSORY DRIVE GEARBOX ASSEMBLY - INSPECTION	72-61-00-200-801	Technical Change: Added metric conversions throughout the pageblock where applicable.
72-61-00 ACCESSORY DRIVE GEARBOX ASSEMBLY - LAPPING SEAL MATING RINGS - REPAIR	72-61-00-300-802	Technical Change: Added a new repair page block for lapping seal mating rings.
73-00-00 FUEL SYSTEM - REMOVAL AND INSTALLATION	73-00-00-400-802	Technical Change: Added a new procedure to remove and install the differential pressure switch in paragraph 9.
73-00-00 FUEL SYSTEM - REMOVAL AND INSTALLATION	73-00-00-400-802	Technical Change: Changed paragraphs 2.A.(4) and 2.B.(20) and Figure 401 and Figure 402 to permit the use of safety wire.
73-00-00 FUEL SYSTEM - INSPECTION	73-00-00-200-801	Technical Change: Changed the inspection of the fuel injector assembly inlet fitting for missing or damaged threads in Table 602.
73-00-00 FUEL SYSTEM - INSPECTION	73-00-00-200-801	Technical Change: Changed the inspection of the fuel injector assembly inlet fitting in Table 602 to change the corrective action to use die 0.5625-18 UNJF-3A.
74-00-00 ELECTRICAL SYSTEM - REMOVAL AND INSTALLATION	74-00-00-400-801	Technical Change: Changed the wrench arc applied to the T45 harness connector on the blue harness in paragraph 8.B.(8).
74-00-00 ELECTRICAL SYSTEM - REMOVAL AND INSTALLATION	74-00-00-400-801	Technical Change: Changed the WARNINGS throughout the pageblock to update to the latest format.

MM Highlights

---

74-00-00 ELECTRICAL SYSTEM - REMOVAL AND INSTALLATION	74-00-00-400-801	Technical Change: Added metric equivalents throughout the pageblock where applicable.
--	------------------	--

GE Designated: - CONFIDENTIAL Subject to the restrictions on the media