

 CT7-2E1 SERVICE BULLETIN - 72-0032 R00

Revised: 01
/29/2024

SB 72-0032 R00 ENGINE - A-SUMP OUTPUT SHAFT ASSEMBLY (72-31-00) - NO. 1 AND NO. 2
BEARING HOUSING OIL NOZZLE PORT REWORK

Issued: 01/29
/2024

THIS SERVICE BULLETIN IS FOR LIMITED DISTRIBUTION

**THIS SERVICE BULLETIN DOES NOT
IMPACT ALL OPERATORS AND IS
APPLICABLE TO AFFECTED OPERATORS
ONLY**

GE Designated: -CONFIDENTIAL-

The information contained in this document is GE proprietary information and is disclosed in confidence. It is the property of GE and shall not be used, disclosed to others or reproduced without the express written consent of GE, including, but without limitation, it is not to be used in the creation, manufacture, development, or derivation of any repairs, modifications, spare parts, designs, or configuration changes or to obtain FAA or any other government or regulatory approval to do so. If consent is given for reproduction in whole or in part, this notice and the notice set forth on each page of this document shall appear in any such reproduction in whole or in part.

This technical data is considered subject to the Export Administration Regulations (EAR) pursuant to 15 CFR Parts 730-774. Transfer of this data by any means to a Non-U.S. Person, whether in the United States or abroad, without the proper U.S. Government authorization (e.g., License, exemption, NLR, etc.), is strictly prohibited.

Copyright (2024) General Electric Company, U.S.A.

GE Designated: - CONFIDENTIAL Subject to the restrictions on the media