

GALAXY AEROSPACE (M) SDN. BHD. [1040262-1

Sulte 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Azız Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 | exww.galaxyaerospace.my | enquiry@galaxyaerospace.my



CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. HOURS LDG/CYCLE WORKPACK NO: PHYSICAL CHECK OF THE PART NO. AND SERIAL NO. OF GIMBAL ARM FITTED ON GIMBAL ASSEMBLIES 6399 6737 4467.1 WORK/INSP/DESC: **AIRCRAFT** AIRCRAFT TYPE: AS365N3 24453 AERONET JOB NO.: 2024-4916 1339.3 #1 ENGINE: 1778.3 1230.8 REGISTRATION: M70-02 AJL REF NO .: 00302 #2 ENGINE: 24275 2293.9 BASE/FACILITY: APMM WMSA 2083.6 1709.2 DATE IN:6/2/2024 OUT:6/2/2024 SHEET 1 NG/N1 NF/N2 Raised by and date: Reason for raising: Other requirements/information: PHYSICAL CHECK OF THE PART NUMBER AND SERIAL NUMBER OF GIMBAL ARM HAMIZAH N/A FITTED ON GIMBAL ASSEMBLIES TO CHECK THE APPLICABILITY OF IN NO. 3153-I-33 02/02/2024 REV 1 DATED 2023-12-22 List of scheduled inspection and all work carried out under this workpack including individual reference. Master Signature Schedule DATE TOTAL APP/STAMP/ INSPECTION / WORK WORKSHEET REF NAME SIGNATURE NO COMPLETED STAFF ID M/H GAM M054 DGTA PHYSICAL CHECK OF THE PART NUMBER AND SERIAL NUMBER 1 4916-001 6/2/2024 0.3 OF GIMBAL ARM FITTED ON GIMBAL ASSEMBLIES ABRUU GAM 10KMAM) DGTA Galaxy Aerospace (M) Sdn. Bhd. I hereby certify the following task has been performed and found satisfactory: 1) All the tools and equipment used for maintenance has been removed from aircraft. 2) All the access panels removed for maintenance access has been reinstalled. 3) All the excess spares and materials have been notified to AMO Planner for return plan. 4) FOD check has been done GAM M053 Date & Time: 6/2/2024 DGTA NAME FIRM SIGN & APPROVAL DATE PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND LOKMAH GAM G.A.M 6/2/2024 OEM PUBLICATION/ REVISION: I.H. NO 3153-1-33 REV / DATED 2023 - 12 - 22



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre,
Suitan Abdul Aziz Shan Airport, 47200 Subang, Selanger, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7526
www.galaxyaerospace.my | enquiry∰galaxyaerospace.my |

WORKSHEET

CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: PHYSICAL CHECK OF THE PART NO AND SERIAL NO. OF GIMBAL ARM FITTED ON GIMBAL ASSEMBLIES 6737 **AIRCRAFT** REFER WORKPACK WORK/INSP/DESC: AIRCRAFT TYPE: AS365N3 24453 WORKPACK REF: REGISTRATION: M70-02 #1 ENGINE: REFER WORKPACK M70-02-4916 BASE/FACILITY: APMM WMSA AJL REF NO .: REFER WORKPACK 24275 #2 ENGINE: REFER WORKPACK DATE IN: REFER WORKPACK OUT: REFER SHEET: NG / N1 NF/N2 Reason for raising: Raised by and date: Other requirements/information: PHYSICAL CHECK OF THE PART NUMBER AND SERIAL NUMBER OF GIMBAL ARM HAMIZAH N/A FITTED ON GIMBAL ASSEMBLIES TO CHECK THE APPLICABILITY OF IN NO. 3153-I-33 02/02/2024 REV 1 DATED 2023-12-22. Item Technician * Eng. CRS Description Date PHYSICAL CHECK OF THE PART NUMBER AND SERIAL NUMBER OF GIMBAL ARM FITTED ON GIMBAL ASSEMBLIES TO CHECK THE APPLICABILITY OF IN NO. 3153-I-33 REV 1 DATED 2023-12-22. P/N: 019 05 8-21 GIMBAL ASSEMBLIES 6/2/2024 REFERENCE: IN NO. 3153-I-33 REV 1. TIC-AS365N3-24-0003 NOTES: ATTACH PHOTOS OF THE GIMBAL ARM AND GIMBAL ASSEMBLIES AS REQUIRED IN THE TIC-AS365N3-24-0003 REMARKS: CARRIED OUT, FOUND SATISFACTORY, The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual. The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenace Manual, Airbus AS365N3 Airworthiness 1 Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Sulta 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7236 | Fax: +603 7734 7536 | subang, Selangor, Malaysia. www.galaxyaerospace.my | enquiry®galaxyaerospace.my

PARTS REPORT

CLIENT/OWNER: APMM SUBANG AIR STATION SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 4916-001 PHYSICAL CHECK OF THE PART NO. AND SERIAL NO. OF GIMBAL ARM FITTED ON GIMBAL ASSEMBLIES 6737 REFER WORKPACK **AIRCRAFT** WORK/INSP/DESC: AIRCRAFT TYPE: AS365N3 24453 REFER WORKPACK WORKPACK REF: M70-02-4916 #1 ENGINE: REGISTRATION: M70-02 24275 AJL REF NO: 00302 REFER WORKPACK BASE/FACILITY: APMM WMSA #2 ENGINE: DATE IN: REFER WORKPACK OUT: REFER WORKPACK SHEET: 1 NF/N2 NG/N1 REASON FOR RAISING: Raised by and date: Other requirements/information: PHYSICAL CHECK OF THE PART NUMBER AND SERIAL NUMBER OF GIMBAL ARM HAMIZAH FITTED ON GIMBAL ASSEMBLIES TO CHECK THE APPLICABILITY OF IN NO. 3153-I-33 N/A 02/02/2024 REV 1 DATED 2023-12-22. Serial Number Lifed Item Information Release Item Part No. Description Qty Position Reason TSN/TSO/DUE/TIMEX Reference Off On FIRM SIGN & APPROVAL NAME GAM LOKMAH G. A. M 6/2/2024 M053 DGTA The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual. The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual. The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenace Manual, Airbus AS365N3 Airworthiness 1 Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

Gal	exyAerospace*		TE	CHNICAL INSTI	סווכ	CTION COMPLIA	NIC	Ē	TIC REF NO	0	TIC-AS365N3-24-0003
	The art of the day, if the Tues			CHINICAL INSTI		TION COMPLIA	4140	· Im	DATE ISSU	E	12 JAN 2024
Α. ٦	ECHNICAL PU	BLIC	ATIC	ON (To Fill Up as Nec	essa	ary)					
PUB	LICATION TITLE	AIRB	US H	HELICOPTERS - AS365	INFO	RMATION NOTICE					
		LIGH	TS O	T.L. OF THE GIMBAL	ARMS	S FITTED ON SPECTRO	LAB S	SX5 & SX	K16 SEARCHLI	GHT	S
	DEVANO	IN NO	D. 31	53-I-33					EV DATE		22 DEC 2023
do(Greensen	REV NO	REV	1					K	EV. DATE		
			2	AC TYPE:		AC S/N:		□ EI	NG. TYPE:		□ ENG. S/N:
AF	PPLICABLE TO			AS365N3		6723 6737 6741					
			PR	OPELLER TYPE:	1	PROPELLER S/N:	_	□ A	PU TYPE:	_	☐ APU S/N:
] C	OMPONENT:			+		QUIPMENT:		
DI	STRIBUTIONS	Ø	PER	ATOR MAMO		 ✓ САМО		□ QI	JALITY	С	OTHER:
В. Т	ECHNICAL SER	RVICE	E (Ap	pplicability review pr	ior t	o sentencing as nece	essar	y)			
	TIME LIMIT IMPOSED			ONE TIME INSPECTION		REPETITIVE INSPECTION		OPTIONAL	REQUIREMENT		MODIFICATION REQUIRED
	SPECIAL TOOLS REQUI	RED		INFORMATION ONLY		NOT APPLICABLE	Ø	OTHER:		L	
6723 REA	SON: REV. 1 ADD	OF E	C725	BLE TO AIRCRAFT TYI	TION						NAME SIGNATURE & DATE
				ICAL CHECK PART NU L ASSEMBLIES INCLUE		R AND SERIAL NUMBEI PHOTO	R FO	R EACH	GIMBAL		
ACT	ION REQUIRED: F	PLANI	NER	TO ISSUE A WORKPAC	K					/	SITI AISHAH MANSOR
SPA	RES / TOOLS: NC	T APP	PLICA	ABLE						(26 JAN 2024

6737 - APPLICABILITY: APPLICABLE TO	AIRCRAF"	TTYPE						,
REASON: REV. 1 ADD OF EC725 AP IN T	HIS INFO	RMATION NOTICE						
COMPLIANCE: REQUEST PHYSICAL CHI ARM WHICH FITTED TO GIMBAL ASSEM			RIAL N	NUMBER FOR EA	CH G	IMBAL		
ACTION REQUIRED: PLANNER TO ISSUE	E A WORK	KPACK						
SPARES / TOOLS: NOT APPLICABLE								
6741 - APPLICABILITY: APPLICABLE TO	AIRCRAF	TTYPE						
REASON: REV. 1 ADD OF EC725 AP IN T	HIS INFO	RMATION NOTICE						
COMPLIANCE: REQUEST PHYSICAL CHI ARM WHICH FITTED TO GIMBAL ASSEM			RIAL I	NUMBER FOR EA	CH G	IMBAL		
ACTION REQUIRED: PLANNER TO ISSUE	E A WORK	(PACK						
SPARES / TOOLS: NOT APPLICABLE								
C. CONTINUING AIRWORTHINESS	MANAGE	MENT (CAM) MAN	NAG	ER / DEPUTY				
MAINTENANCE SCHEDULE AMENT.	PUBLICATION	AMENDMENT	Ø	PRE-PLANNED WORKSH	EET			COMPONENT SEND OFF FOR COMPLIANCE
REMARKS:								NAME SIGNATURE & DATE
CAMO PLANNER TO ISSUE WORKPAC UPON WORKPACK COMPLETION.	K FOR P/I	N APPLICABILITY AN	ND RE	EVERT THE TIC				ZATY NADHIRA MOHAMED ZUHARI 26 JAN 2024
D. CAMO PLANNER								
☐ ENTRY TO MAINT, FORECAST		PREPARE WORK PACK	AGE			PLAN EM	BODIN	ENT
SPARE ORDER		MANPOWER QUALIFICA	ATION			TOOLING		
REMARKS: WORKPACK RAISED. TIC TO BE UPDA	ATED AFT	ER WORKPACK CLC	OSED					SIGNATURE & DATE
								NUR HAMIZAH SYAMSUL BAHRI 5 FEB 2024

	TIC COMPL	IANCE CHECKLIST BY CAM MANAGER (Tick and Fill up as neces	ssary)
COMPL	LIANCE	REMARKS:	NAME SIGNATURE & DATE
YES	NO		SIGNATORE & BATE
TIC	APPROVAL BY	DESIGN ACCEPTANCE REPRESENTATIVE (DAR) (Tick and Fill up	as necessary)
COMPL		DESIGN ACCEPTANCE REPRESENTATIVE (DAR) (Tick and Fill up	NAME
COMPL	LIANCE		NAME




No. 3153-I-33

Information Notice

SUBJECT: LIGHTS

O.T.L. of the Gimbal Arms fitted on Spectrolab SX5 & SX16 searchlights



AIRCRAFT	Version(s)						
CONCERNED	Civil	Military					
AS355	N, NP						
AS365	N2, N3						
EC225	LP						
EC725		AP					
AS332	C, C1, L, L1, L2	B, B1, F1, M, M1					
AS532		A2, U2, AC, AL, SC, UE, UL					

Rev. 1: addition of EC725 AP

Equipment manufacturer SPECTROLAB issued Service Bulletin #SL0899-01A in CMM 33-45-96, which defines an OTL for the Gimbal Arms that are fitted on the Gimbal assemblies of the SX5 & SX16 searchlights.

These OTLs (7 years for Aluminum Gimbal Arms and 10 years for Steel Gimbal Arms) have been introduced in the maintenance programs (PRE & MSM) of the helicopters listed above.

The Manufacturer Part Numbers of the Gimbal Arms concerned by this OTL are as follows:

- 1. For the SX5 searchlight:
 - a. MP/N 030041: Aluminum Gimbal Arm fitted on all Gimbal assemblies.
- 2. For the SX16 searchlight:
 - a. MP/N 019058: Aluminum Gimbal Arm fitted on Gimbal assemblies MP/N 019059-4, -5, -10, -104, -105,
 - b. MP/N 019058-21: IFCO Aluminum Gimbal Arm fitted on Gimbal assemblies MP/N 019059-11, -111, -140.
 - c. MP/N 022929: Steel Gimbal Arm fitted on Gimbal assemblies MP/N 022955-21, -121, -130.
 - MP/N 022929-11: IFCO Steel Gimbal Arm fitted on Gimbal assemblies MP/N 022955-22, -122, -140.
 - e. MP/N 022929-81: Steel Gimbal Arm fitted on Gimbal assembly MP/N 022955-51.
 - f. MP/N 021715: Long Arm Aluminum Gimbal Arm fitted on Gimbal assemblies MP/N 021716-21, -31, -121, -131.









