TOOL SERVICE BULLETIN

NO: PT-622R1

Service Tool: PWC34652 Rev. C

Description: Adapter

Effectivity: PT6A-52, PT6A-60A, PT6A-60AG, PT6A-61, PT6A-62, PT6A-65B,

PT6A-65R, PT6A-65AG, PT6A-65AR, PT6A-64, PT6A-66, PT6A-66A, PT6A-66B, PT6A-66D, PT6A-67, PT6A-67A, PT6A-67AF, PT6A-67AG, PT6A-67B, PT6A-67D, PT6A-67F, PT6A-67P, PT6A-67R, PT6A-67T, PT6A-68, PT6A-68B, PT6A-68C, PT6C-67C, PT6C-67C1, PT6C-67D

Subject: Tool Obsolete

Reason:

Problem: Older technology snap fit type balancing adaptors.

Cause: Hydraulic type balancing adaptors introduced.

Solution: Obsolete, replaced by PWC50097.

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to: VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

TOOL SERVICE BULLETIN

Instruction: Not applicable

Compliance: Recommended

Tool Usage: Overhaul

Tool Disposition: You can use the old tool but the old tool is not supported or procurable.

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Jul 24/2008 Revised: Aug 30/2023 **PWC34652** Page 2 of 3

TOOL SERVICE BULLETIN

NO: PT-622R1

TSB Revision Notes			
TSB	DATE	Tool Rev No.	CHANGES
PT-622	09/2023	1	Effectivity Revised to Inculd PT6C-67C, PT6C-67C1 and PT6C-67D

ICN-00198-G000133822-001-01

Figure 1

P&WC Proprietary Information. Subject to the restrictions on the first page.

lssued: Jul 24/2008 Revised: Aug 30/2023 **PWC34652** Page 3 of 3