

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-706R2

Service Tool: PWC70907 Rev. C

Description: Stand Assembly

Effectivity: PT6A-6, PT6A-6A, PT6A-6B, PT6A-20, PT6A-20A, PT6A-20B, PT6A-11, PT6A-11AG, PT6A-15AG, PT6A-110, PT6A-112, PT6A-121, PT6A-21, PT6A-27, PT6A-28, PT6A-25, PT6A-25A, PT6A-25C, PT6A-34, PT6A-34AG, PT6A-34B, PT6A-35, PT6A-36, PT6A-114, PT6A-114A, PT6A-116, PT6A-135, PT6A-135A, PT6A-140, PT6A-38, PT6A-41, PT6A-42, PT6A-42A, PT6A-45A, PT6A-45B, PT6A-45R, PT6A-50, PT6A-52, PT6A-60A, PT6A-60AG, PT6A-61, PT6A-62, PT6A-64, PT6A-65AG, PT6A-65AR, PT6A-65B, PT6A-65R, PT6A-65SC, PT6A-66, PT6A-66B, PT6A-66A, PT6A-66D, PT6A-67, PT6A-67A, PT6A-67AF, PT6A-67AG, PT6A-67R, PT6A-67T, PT6A-67B, PT6A-67D, PT6A-67P, PT6A-67F, PT6A-68, PT6A-68B, PT6A-68C, PT6A-68D, PT6A-68T, PT6B-67A, PT6C-67C, PT6C-67D, PT6E-66XT, PT6E-67XP, PT6T-3, PT6T-3B, PT6T-3BE, PT6T-3BF, PT6T-3BG, PT6T-3D, PT6T-3DE, PT6T-3DF, PT6T-6, PT6T-6B, PT6T-9

Subject: Tool Obsolete

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to:
VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

Issued: Feb 15/2011
Revised: Jul 12/2024

PWC70907
Page 1 of 3

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-706R2

Reason:

Problem: Tool identification and marking not to latest requirements.

Cause: CE certification requirement (Community European).

Solution: Obsolete, replaced by PWC71835.

Instruction: Not Applicable.

Compliance: Optional

Tool Usage: Overhaul, Heavy Maintenance

Tool Disposition: Usable but no longer supported/procurable.

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Feb 15/2011
Revised: Jul 12/2024

PWC70907
Page 2 of 3

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-706R2

TSB REVISION NOTES			
TSB	DATE	Tool Rev No.	Changes
PWC70907 Rev. C	07/2024	2	Added effectivity: PT6A-140, PT6A-65SC, PT6A-68D, PT6A-68T PT6B-67A, PT6C-67C, PT6C-67D, PT6E-66XT PT6E-67XP

ICN-00198-G000142257-001-01

Figure 1

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Feb 15/2011
Revised: Jul 12/2024

PWC70907
Page 3 of 3