

SB139-526 REV A SUMMARY

1) AMPI SCHEDULED MAINTENANCE CHECK 63-20 (REF. DM 39-A-63-20-03-00A-310A-A):

No	Item	Task	Condition / limit Standard	Condition / limit Phased	Condition / limit Progressive	Reference (DMC)
63-20	MGB oil cooling fan [62]	Do a FC to check freedom of rotation of the fan impeller (bearing roughness). Clean the MGB oil cooler and fan, and check the nuts slip mark	900	900	900	39-A-63-20-03-00A-310A-A

NOTE:

62 Tasks applicable only to MGB oil cooling fan P/N 3G6320V03853.

2) AMPI TIME LIMITS CO63-06 (REF. DM 39-A-05-12-00-00A-028E-P):

Ref	Component	Part number	Overhaul interval
CO63-06	Main gearbox oil cooling fan	3G6320V03853	1200

3) History of the SB139-526 compliance:

AC REG	SB139-526 PART I & II COMPLIANCE	STATUS
M72-01	PART I	CLOSED – REFER M72-01/G20/095-001 DATE : 05/06/2020 @ HOURS: 3418.8 FH
M72-01	PART II	REPETITIVE - LAST COMPLIANCE REFER M72-01-4221-001 DATE : 18/08/2023 @ HOURS: 4690.1 FH
M72-02	PART I	CLOSED - REFER M72-02/G20/038-002 DATE : 29/01/2020 @ HOURS: 2714.3 FH
M72-02	PART II	REPETITIVE - LAST COMPLIANCE REFER M72-02-2928-001 DATE : 26/08/2022 @ HOURS : 3953.6 FH
M72-03	PART I	CLOSED – REFER M72-03/G19/067-001 DATE : 27/08/2019 @ HOURS : 3077.1 FH
M72-03	PART II	REPETITIVE - LAST COMPLIANCE REFER M72-03/G20/071-001 DATE : 1/4/2020 @ HOURS : 2195.0 FH