

**SUMMARY RECORD OF REVISION 30 RFM MMEA AW139 FLEET**

NO	SUBJECT	APPLICABLE						REMARKS
		YES			NO			
		01	02	03	01	02	03	
1	SECTION 5 PAGES: 5-2 AND 5-3, 5-9 AND 5-10, 5-12 THRU 5-18, 5-20	/	/	/				APPLICABLE TO MMEA AW139 FLEET. TO UPDATE THE RFM.
2	SECTION 5 SUPP. 99 PAGE: S99-3				/	/	/	NOT APPLICABLE TO MMEA AW139 FLEET DUE CABIN COMPARTMENT PARTIAL EXTENSION WITH BAGGAGE BARRIER NET P/N 4G5338F00111 APPLICABLE TO EFFECTIVITY: PLUS, REFER IPD 39-B-25-54-00-00A-034A-K. FOR INFO ONLY.
3	SECTION 5 SUPP. 103 PAGE: S103-6				/	/	/	NOT APPLICABLE TO MMEA AW139 FLEET DUE NOT FITTED CABIN STOWAGE BOXES (TALL STOWAGE BOX P/N 8G5010A24532, MEDIUM STOWAGE BOX P/N 8G5010A24732, LOW STOWAGE BOX P/N 8G5010A33432). FOR INFO ONLY.
4	SECTION 5 SUPP. 104 PAGE: S104-i THRU S104-iv, S104-1 THRU S104-8				/	/	/	NOT APPLICABLE TO MMEA AW139 FLEET DUE TO NOT FITTED VIP SEAT INSTALLATIONS P/N 4G2520F29011 AND P/N 4G2520F28911. FOR INFO ONLY.
5	SECTION 5 SUPP. 93 PAGE: S93-i, S93-1.				/	/	/	NEW MGB IMPROVED LUBRICATION SYSTEM P/N 4G6320F00511 INCLUDED IN NEW REV RFM BUT NOT APPLICABLE TO MMEA AW139 FLEET DUE TO NOT FITTED. FOR INFO ONLY.

6	SECTION 5 SUPP. 105 PAGE: S105-i thru S105-iv, S105-1 thru S105-16.				/	/	/	NOT APPLICABLE TO MMEA AW139 FLEET DUE CABIN TUNNEL EXTENSION STN 7200 P/N 4G5338F00211 P/N 4G5338F00311 APPLICABLE TO EFFECTIVITY: PLUS, REFER IPD 39-A-53-38-00-040-941A-A. FOR INFO ONLY.
7	SECTION 1 PAGE: 1-32	/	/	/				AUTHORIZED HYDRAULIC FLUIDS HAS BEEN UPDATED. APPLICABLE TO MMEA AW139 FLEET AND TO UPDATE THE RFM.
8	SECTION 5 SUPP. 60 PAGE: S60-5				/	/	/	NEW PROCEDURES UPDATES ON MINIMUM FLIGHT CREW. NOT APPLICABLE TO MMEA AW139 FLEET DUE AIRCRAFT NOT EQUIPPED WITH SAME TYPE OF NVGS (GREEN PHOSPHOR OR WHITE PHOSPHOR SCREEN. FOR INFO ONLY.
9	SECTION 2 PAGES: 2-6, 2-9	/	/	/				PRE-FLIGHT CHECK - AREA N°2 (FUSELAGE - RIGHT HAND SIDE) HAS BEEN UPDATED ON: 1) PILOT COCKPIT DOOR INSPECTION – APPLICABLE TO AW139 MMEA FLEET, TO REVISE AMP. 2) BAGGAGE DOOR – NOT APPLICABLE DUE AW139 MMEA FLEET NOT FITTED WITH BAGGAGE DOOR EXTENSION KIT (P/N 4G5230F00111). FOR INFO ONLY.
10	SECTION 5 SUPP. 9 PAGES: S9-iii, S9-5 AND S9-6, S9-10, S9-23 AND S9-24	/	/	/				DITCHING CONFIGURATIONS PROCEDURES UPDATES. APPLICABLE DUE AIRCRAFT FITTED WITH KIT EFS AND LIFERAFT P/N 3G9560F00111/113 (AERO SEKUR). TO UPDATE RFM.

11	SECTION 5 SUPP. 12 PAGE: S12-H24	/	/	/				LDP FOR OBSTACLE UNDER LANDING APPROACH PROFILE PROCEDURES UPDATES. APPLICABLE TO AW139 MMEA FLEET DUE AIRCRAFT ALSO APPLICABLE FOR CATEGORY A OPERATIONS. TO UPDATE RFM.
12	SECTION 5 SUPP. 17 PAGES: S17-i, S17-iii, S17-1, S17-2A, S17-5	/	/	/				APPLICABLE TO AW139 MMEA FLEET DUE NEW P/N 4G2350F02811 HAS BEEN ADDED UNDER EXTERNAL AND INTERNAL PUBLIC ADDRESS SYSTEM IN THIS SUPPLEMENT. TO UPDATE RFM.
13	SECTION 5 SUPP. 21 PAGES: S21-14 AND S21-15, S21-19 THRU S21-21, S21-29 THRU S21-34	/	/	/				APPLICABLE TO AW139 MMEA FLEET DUE AIRCRAFT FITTED WITH HONEYWELL WEATHER RADAR SERIES P/N 4G3441F00111. TO UPDATE RFM.
14	SECTION 5 SUPP. 41 PAGE: S41-30				/	/	/	CHANGE OF HOIST PROCEDURE FOR DOUBLE EXTERNAL HOIST OPERATIONS P/N 4G2591F00111. NOT APPLICABLE DUE AW139 MMEA FLEET FITTED WITH KIT SINGLE RESCUE HOIST GOODRICH 4G2591F00211. FOR INFO ONLY.
15	SECTION 5 SUPP. 46 PAGES: S46-5 AND S46-6				/	/	/	AIRCRAFT AW139 MMEA FLEET NOT FITTED WITH RADIO EQUIPMENT CHELTON DF 935-2 AND 935-11 P/N 3G3450F00911, P/N 4G3450F00511 P/N 4G3450F00711. FOR INFO ONLY.
16	SECTION 5 SUPP. 95 PAGES: S95-iii AND S95-iv, S95-7, S95-13 AND S95-14, S95-25				/	/	/	NOT APPLICABLE TO AW139 MMEA FLEET DUE THIS SUPPLEMENT UPDATES ON DITCHING CONFIGURATIONS WITH DART INTEGRATED EMERGENCY FLOTATION AND LIFERAFT KIT (P/N 4G9560F00111 & P/N 4G9560F00211). FOR INFO ONLY.

17	SECTION 5 SUPP. 101 PAGE: S101-2				/	/	/	<p>NOT APPLICABLE TO AW139 MMEA FLEET DUE THIS SUPPLEMENT UPDATES ON PHASE 8 ADDITIONAL FUNCTIONS S/W EB7030191-00113. AW139 MMEA ALL FITTED PRIMUS EPIC PHASE 5.6. FOR INFO ONLY.</p>
18	SECTION 7 PAGES: 7-iv, 7-vii, 7-164	/	/	/				<p>THE LEFT AND RIGHT STORM WINDOWS ARE INTRODUCED WITH THE FOLLOWING KITS:  — P/N4G5630F00311 FOR THE LEFT CABIN DOOR STORM WINDOW  — P/N 4G5630F00411 FOR THE RIGHT CABIN DOOR STORM WINDOW.  NOT APPLICABLE TO AW139 MMEA FLEET DUE ALL AIRCRAFT FITTED WITH KIT CREW SLIDING WINDOW LH P/N 4G5620F00211 AND KIT CREW SLIDING WINDOW RH P/N 4G5620F00311. TO UPDATE RFM.</p>