

AW139 Air vehicle maintenance planning information Chapter 05, Issue 027: 2024-02-14

No.	Data module code	Issue date	Reason for change	Applicability (YES / N/A)			Remarks
				M72-01	M72-02	M72-03	
1	39-A-05-12-00-00A-028E-P	C 2024-02-09	Changed - Added CO25-15, Note 26 and Note 27	N/A	N/A	N/A	For info only due aircraft M72-01 fitted with Left Main Landing Gear P/N 3G3210V00135 (LIEBHERR) and Right Main Landing Gear P/N 3G3210V00235 (LIEBHERR) and Life Raft LH PN 3G2560V00332 (AEROSEKUR) and Life Raft RH PN 3G2560V00432 (AEROSEKUR).
				N/A	N/A	N/A	For info only due aircraft M72-02 fitted with Left Main Landing Gear P/N 3G3210V00135 (LIEBHERR) and Right Main Landing Gear P/N 3G3210V00235 (LIEBHERR) and Life Raft LH PN 3G2560V00332 (AEROSEKUR) and Life Raft RH PN 3G2560V00432 (AEROSEKUR).
				N/A	N/A	N/A	For info only due aircraft M72-03 fitted with Left Main Landing Gear P/N 3G3210V00135 (LIEBHERR) and Right Main Landing Gear P/N 3G3210V00235 (LIEBHERR) and Life Raft LH PN 3G2560V00332 (AEROSEKUR) and Life Raft RH PN 3G2560V00432 (AEROSEKUR).
			Changed - Added CO63-14	N/A	N/A	N/A	For info only due aircraft M72-01 fitted with Fan MGB Cooling PN 3G6320V03853 S/N 00457.
				N/A	N/A	N/A	For info only due aircraft M72-02 fitted with Fan MGB Cooling PN 3G6320V03853 S/N 00457.
				N/A	N/A	N/A	For info only due aircraft M72-03 fitted with Fan MGB Cooling PN 3G6320V03853 S/N 00457.
2	39-A-05-13-00-00A-028E-P	C 2024-02-09	Changed - Added DT25-31	N/A	N/A	N/A	For info only due aircraft M72-01 fitted with Life Raft LH PN 3G2560V00332 and Life Raft RH PN 3G2560V00432
				N/A	N/A	N/A	For info only due aircraft M72-02 fitted with Life Raft LH PN 3G2560V00332 and Life Raft RH PN 3G2560V00432
				N/A	N/A	N/A	For info only due aircraft M72-03 fitted with Life Raft LH PN 3G2560V00332 and Life Raft RH PN 3G2560V00432
			Changed - Updated DT28-01	YES			Aircraft M72-01 fitted with LH/RH tanks foam installation PN 3G2810A00413. Discard time 12 years to be included in Amp, Aeronet and Log Card.
					YES		Aircraft M72-02 fitted with LH/RH tanks foam installation PN 3G2810A00413. Discard time 12 years to be included in Amp, Aeronet and Log Card.
						YES	Aircraft M72-03 fitted with LH/RH tanks foam installation PN 3G2810A00413. Discard time 12 years to be included in Amp, Aeronet and Log Card.
			Changed - Updated DT31-04	N/A	N/A	N/A	For info only due aircraft M72-01 fitted with Underwater Locator Beacon (ULB) Battery Kit S/N 810-2008/K
				N/A	N/A	N/A	For info only due aircraft M72-02 fitted with Underwater Locator Beacon (ULB) Battery Kit S/N 810-2008/K
				N/A	N/A	N/A	For info only due aircraft M72-03 fitted with Underwater Locator Beacon (ULB) Battery Kit S/N 810-2008/K
3	39-A-05-21-00-00A-028E-P	C 2024-02-09	Added Note 70	YES			Task applicable to all kits which install a cargo net to secure cargo
					YES		Task applicable to all kits which install a cargo net to secure cargo
						YES	Task applicable to all kits which install a cargo net to secure cargo
			Added Note 71	N/A	N/A	N/A	Task applicable only to MGB oil cooling fan P/N 3G6320V03854. M72-01 fitted with MGB oil cooling fan P/N 3G6320V03853
				N/A	N/A	N/A	Task applicable only to MGB oil cooling fan P/N 3G6320V03854. M72-02 fitted with MGB oil cooling fan P/N 3G6320V03853
				N/A	N/A	N/A	Task applicable only to MGB oil cooling fan P/N 3G6320V03854. M72-03 fitted with MGB oil cooling fan P/N 3G6320V03853
			Added Note 72	N/A	N/A	N/A	The task must be performed at the specified interval either from new or from the last Overhaul
				N/A	N/A	N/A	The task must be performed at the specified interval either from new or from the last Overhaul
				N/A	N/A	N/A	The task must be performed at the specified interval either from new or from the last Overhaul