

TIC-AW139-23-0008

NOT APPLICABLE TO ALL AW139 APMM FLEET.

galaxy aerospace2.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name... AD/SB ID: 4592

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	NOT APPLICABLE	
	M72-03		-		0	-	-	NOT APPLICABLE	

galaxy aerospace2.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name... AD/SB ID: 4592

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: ATA 53 - UPPER DECK PANEL REINFORCEMENT

Title/Subject: SB NO. 139-639, REV. A

Version No:

Reason For Raising:

URL:

Date: 01 08 2023

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename	
	SB NO. 139-639, REV. A	4592-2111.pdf	