

TIC-AW139-24-0049

NOT APPLICABLE TO ALL MMEA'S AW139 FLEET

**AD/SB ID: 4773** Close Update

General | **Config List** | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: ATA 33 - INSTALLATION OF PULSE LIGHTS ON SPONSONS

Title/Subject: SB NO. 139-481 REV A

Version No:

Reason For Raising:

URL:

Date: 28 05 2024

**AD/SB ID: 4773** Close Update Save & Close

General | Config List | **Aircraft List** | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	NOT APPLICABLE	
	M72-03		-		0	-	-	NOT APPLICABLE	

