

TIC-AW139-24-0055

NOT APPLICABLE TO AW139 MMEA'S FLEET

AD/SB ID: 4776 Close Update

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: ATA 55 - TAIL PLANE ROD ASSY INSTALLATION INSPECTION

Title/Subject: SB NO. 139-778 NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: 12 06 2024

AD/SB ID: 4776 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	NOT APPLICABLE	
	M72-03		-		0	-	-	NOT APPLICABLE	