

TIC-AW139-24-0066

PART I : NOT APPLICABLE TO ALL MMEA'S AW139 FLEET

PART II : ONLY APPLICABLE TO M72-02 (S/N 31315) AND M72-03 (S/N 31316)

PART I

AD/SB ID: 4793 Close Update Save

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 23 - 150 FT AURAL INHIBIT KIT P/N 4G2350F01511, INSTALLATION OF

Title/Subject: SB NO. 139-677 NEW ISSUE - PART I

Version No:

Reason For Raising:

URL:

Date: 30 07 2024

AD/SB ID: 4793 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	NOT APPLICABLE	
	M72-03		-		0	-	-	NOT APPLICABLE	

PART II

AD/SB ID: 4792 Close Update Save & C

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 23 - 150 FT AURAL INHIBIT KIT P/N 4G2350F01511, INSTALLATION OF

Title/Subject: SB NO. 139-677 NEW ISSUE - PART II

Version No:

Reason For Raising:

URL:

Date: 30 07 2024

AD/SB ID: 4792 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	M72-01		-		0	-	-	NOT APPLICABLE	
	M72-02		-		0	-	-	OPTIONAL	
	M72-03		-		0	-	-	OPTIONAL	