

Tail No	Task / Defect Description	Duration	Job No.	Remarks
9M-PTA s/n: FL-587	1			
	2			
	3			
	4			
	5			
	6			
	7			
9M-PTB s/n: FL-593	1			
	2			
	3			
	4			
	5			
	6			
	7			
9M-PTC s/n: FL-598	1			
	2			
	3			
	4			
	5			
	6			
	7			
9M-PTD s/n: FL-680	1	ITEM ROBBED TO SERVICE 9M-PTB		
	2	DUE FOR 1800 FH - ENGINE NUMBER 1 HOT SECTION INSPECTION (HSI)		9M-PTA-16444
	3			
	4			
	5			
	6			
	7			
9M-PTE s/n: FL-683	1			
	2			
	3			
	4			
	5			
	6			
	7			