

| | | | |
|-----------------------|---------|------------------|------------|
| Pesawat: Aircraft: | AS555SN | Tarikh: Date: | 15/10/2023 |
|-----------------------|---------|------------------|------------|

BAHAGIAN 2 - STATUS HARIAN PESAWAT
Part 2 - Daily Aircraft Status
Kedaaan Pesawat pada jam 0800H
Aircraft State at 0800H

Bahagian ini diisi oleh MC
 This parts to be filled by MC

| Pesawat Tail Number | Jam Enjin Eng TSN | Jam Pesawat A/C TSN | Kedaaan Semasa Current Status | | | Penangguhan Kerosakan (Jika ada) Deferred Defect (If any) | | | | Rawalan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | | |
|---|----------------------|------------------------|----------------------------------|------------------------------------|---|--|------------------------|------------------------------------|------------------------------|---|------------------------------|----------------------|----------------------|--------------------|---|-------------|
| | | | Keadaan State | Tarikh Rosak Date Unserviceable | Bulir Kerosakan Details of Unserviceable | Jangka Masa Slap Estimate | Perkara Description | Tarikh Rosak Date Unserviceable | Jangka Masa Slap Estimate | Had Operasi (Jika ada) Operational Limitation | Perkara Description | Tamat Pada Due of | | | Jenis Work | |
| | | | | | | | | | | | | Jam Date | Kalendar Calendar | | Jam Date | Hari Day |
| M502-1 5709 | ENG #1 SN: 2408 | 4172.6 | S | | | | | | | | SCHEDULE INSPECTION | | | | SEAT CONFIGURATION STANDARD SEATS INSTALLED ITEM: FLJR STATUS: REMOVED P/NO.: 10406-06-410 / 10406-06-210 S/NO.: N/A ITEM: MOUNTING GUN STATUS: REMOVED P/NO.: 3628931480 S/NO.: N/A ITEM: FLOATATION GEAR STATUS: REMOVED P/NO.: 218570-0(RH) / 218569-0(LH) S/NO.: N/A ITEM: SPECTROLAB ASSY STATUS: REMOVED P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) S/NO.: N/A ITEM: RESCUE HOIST ASSY STATUS: REMOVED P/NO.: 704A-41-815-056 S/NO.: N/A ITEM: CARGO SWING STATUS: REMOVED P/NO.: 704A-4181-1027 S/NO.: N/A | |
| | | | | | | | | | | | 25 FH INSP. | 4177 | | 4.4 | | |
| | | | | | | | | | | | 30 FH INSP. | 4180 | | 7.4 | | |
| | | | | | | | | | | | 50 FH INSP. | 4220.5 | | 47.9 | | |
| | | | | | | | | | | | 100 FH INSP. (AF) | 4220.5 | | 47.9 | | |
| | | | | | | | | | | | 100 FH INSP. (ENG NO 1) | 4220.5 | | 47.9 | | |
| | | | | | | | | | | | 100 FH INSP. (ENG NO 2) | 4220.5 | | 47.9 | | |
| | | | | | | | | | | | 150 FH INSP. (AF) | 4194.8 | | 22.2 | | |
| | | | | | | | | | | | 150 FH INSP. (ENG NO 1) | 4194.8 | | 22.20 | | |
| | | | | | | | | | | | 150 FH INSP. (ENG NO 2) | 4194.8 | | 22.20 | | |
| | | | | | | | | | | | 300 FH INSP. | 4463.4 | | 290.8 | | |
| | | | | | | | | | | | 500 FH INSP. (AF) | 4620.5 | | 447.9 | | |
| | | | | | | | | | | | 500 FH INSP. (ENG NO 1) | 4206.3 | | 33.7 | | |
| | | | | | | | | | | | 500 FH INSP. (ENG NO 2) | 4620.5 | | 447.9 | | |
| | | | | | | | | | | | 600 FH INSP. (AF) | 4261.1 | | 88.5 | | |
| | | | | | | | | | | | 600 FH INSP. (ENG NO 1) | 4306.3 | | 133.7 | | |
| | | | | | | | | | | | 600 FH INSP. (ENG NO 2) | 4201.8 | | 29.2 | | |
| | | | | | | | | | | | 50 FH/6M INSP. | 4220.5 | 27/12/2023 | 47.9 | | 73 D |
| | | | | | | | | | | | 150 FH//3M INSP. | 4227.4 | 26/12/2023 | 54.8 | | 72 D |
| | | | | | | | | | | | 150 FH//6M INSP. | 4183 | 27/12/2023 | 10.4 | | 73 D |
| | | | | | | | | | | | 150 FH//12M INSP. | 4194.8 | 27/06/2024 | 22.2 | | 256 D |
| | | | | | | | | | | | 500 FH//24M INSP. | 4483.2 | 27/06/2025 | 310.6 | | 621 D |
| | | | | | | | | | | | 600 FH//6M INSP. | 4676.2 | 27/12/2023 | 503.6 | | 73 D |
| | | | | | | | | | | | 600 FH//24M INSP. (AF) | 4201.8 | 16/01/2025 | 29.2 | | 459 D |
| | | | | | | | | | | | 600 FH//24M INSP. (ENG NO 1) | 4261.1 | 16/01/2025 | 1377.9 | | 459 D |
| | | | | | | | | | | | 600 FH//24M INSP. (ENG NO 2) | 4261.1 | 16/01/2025 | 575.7 | | 459 D |
| | | | | | | | | | | | 7 D INSP. | | 16/10/2023 | | | 1 D |
| | | | | | | | | | | | 1 M INSP. | | 04/11/2023 | | | 20 D |
| | | | | | | | | | | | 6 M INSP. | | 27/12/2023 | | | 73 D |
| | | | | | | | | | | | 12 M INSP. | | 11/11/2023 | | | 27 D |
| 24 M INSP. | | 11/11/2023 | | 27 D | | | | | | | | | | | | |
| 30 M INSP. | | 27/12/2025 | | 804 D | | | | | | | | | | | | |
| 48 M INSP. | | 15/11/2024 | | 397 D | | | | | | | | | | | | |
| 60 M INSP. | | 15/11/2025 | | 762 D | | | | | | | | | | | | |
| CORROSION CONTROL PROGRAMME (CCP) | | | | | | | | | | | | | | | | |
| 25 FH - ENG. CLEANING (BOTH ENG) | 4177 | | 4.4 | | | | | | | | | | | | | |
| SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE / PERFORMED ONCE | | | | | | | | | | | | | | | | |
| 10 HRS - AEOO 30/22 | 4174.7 | | 2.1 | | | | | | | | | | | | | |
| COMPONENT | | | | | | | | | | | | | | | | |
| MGB OIL FILTER, PN: FA01315AV | | | 15/11/2022 | -334 D | | | | | | | | | | | | |
| TAIL SERVO, PN: SC5072 | | | 1/1/2023 | -287 D | | | | | | | | | | | | |
| AC LANDING CYCLE | | | | | | | | | | | 11,722 | | | | | |
| FUEL | | | | | | | | | | | TBA | | | | | |
| HOURS FLIGHT OF THE DAY | 2.3 | HOURS CTF OF THE DAY | | 0.0 | WARNING OVERDUE | | | | | | | | | | | |
| CARRY FORWARD | 9.6 | CARRY FORWARD | | 0.0 | | WARNING NEARING DUE | | | | | | | | | | |
| HOURS FLIGHT OF THE MONTH | 11.9 | HOURS CTF OF THE MONTH | | 0.0 | | | | | | | | | | | | |

| | | | |
|-----------------------|---------|------------------|------------|
| Pesawat: Aircraft: | AS555SN | Tarikh: Date: | 15/10/2023 |
|-----------------------|---------|------------------|------------|

Bahagian ini diisi oleh MC
This parts to be filled by MC

BAHAGIAN 2 - STATUS HARIAN PESAWAT
Part 2 - Daily Aircraft Status
Keadaan Pesawat pada jam 0800H
Aircraft State at 0800H

| Pesawat Tail Number | Jam Enjin Eng TSN | Jam Pesawat A/C TSN | Keadaan Semasa Current Status | | | | Penangguhan Kerosakan (Jika ada) Deferred Defect (If any) | | | | Rawatan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | |
|---|----------------------|------------------------|----------------------------------|------------------------------------|---|------------------------------|--|------------------------------------|------------------------------|---|--|-----------------------|----------------------|-----------------|---|-------------|
| | | | Keadaan State | Tarikh Rosak Date Unserviceable | Butir Kerosakan Details of Unserviceable | Jangka Masa Siap Estimate | Perkara Description | Tarikh Rosak Date Unserviceable | Jangka Masa Siap Estimate | Had Operasi (Jika ada) Operational Limitation | Perkara Description | Tamat Pada Date of | | Baki Balance | | |
| | | | | | | | | | | | | Jam Hrs | Kalendar Calendar | Jam Hrs | | Hari Day |
| M502-2 5711 | ENG #1 SN: 2013 | 3802.9 | S | | | | | | | | SCHEDULE INSPECTION | | | | SEAT CONFIGURATION STANDARD SEATS INSTALLED ITEM: FLIR STATUS: REMOVED P/NO.: 10406-06-410 / 10406-06-210 S/NO.: N/A ITEM: MOUNTING GUN STATUS: REMOVED P/NO.: 3628931480 S/NO.: N/A ITEM: FLOATATION GEAR STATUS: REMOVED P/NO.: 218570-0(RH) / 218569-0(LH) S/NO.: N/A ITEM: SPECTROLAB ASSY STATUS: REMOVED P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) S/NO.: N/A ITEM: RESCUE HOIST ASSY STATUS: REMOVED P/NO.: 704A-41-815-056 S/NO.: N/A ITEM: CARGO SWING STATUS: REMOVED P/NO.: 704A-4181-1027 S/NO.: N/A | |
| | | | | | | | | | | | 25 FH INSP. | 3803 | 0.1 | | | |
| | | | | | | | | | | | 30 FH INSP. | 3827.9 | 25 | | | |
| | | | | | | | | | | | 50 FH INSP. | 3811.1 | 8.2 | | | |
| | | | | | | | | | | | 100 FH INSP. (AF) | 3865.3 | 62.4 | | | |
| | | | | | | | | | | | 100 FH INSP. (ENG NO 1) | 3865.3 | 62.4 | | | |
| | | | | | | | | | | | 100 FH INSP. (ENG NO 2) | 3865.3 | 62.4 | | | |
| | | | | | | | | | | | 150 FH INSP. (AF) | 3942.3 | 139.4 | | | |
| | | | | | | | | | | | 150 FH INSP. (ENG NO 1) | 3864.2 | 61.3 | | | |
| | | | | | | | | | | | 150 FH INSP. (ENG NO 2) | 3864.2 | 61.3 | | | |
| | | | | | | | | | | | 300 FH INSP. | 3947.3 | 144.4 | | | |
| | | | | | | | | | | | 500 FH INSP. (AF) | 4146.9 | 344 | | | |
| | | | | | | | | | | | 500 FH INSP. (ENG NO 1) | 4146.9 | 344.0 | | | |
| | | | | | | | | | | | 500 FH INSP. (ENG NO 2) | 4146.9 | 344.0 | | | |
| | | | | | | | | | | | 600 FH INSP. (AF) | 4246.9 | 444.0 | | | |
| | | | | | | | | | | | 600 FH INSP. (ENG NO 1) | 4314.2 | 511.3 | | | |
| | | | | | | | | | | | 600 FH INSP. (ENG NO 2) | 4314.2 | 511.3 | | | |
| | | | | | | | | | | | 50 FH/6M INSP. | 3811.1 | 17/2/2024 | 8.2 | | 125 D |
| | | | | | | | | | | | 150 FH/3M INSP. | 3928 | 12/12/2023 | 125.1 | | 58 D |
| | | | | | | | | | | | 150 FH/6M INSP. | 3838.8 | 14/11/2023 | 35.9 | | 30 D |
| | | | | | | | | | | | 150 FH/12M INSP. | 3942.3 | 14/02/2024 | 139.4 | | 122 D |
| | | | | | | | | | | | 500 FH/24M INSP. | 4010.3 | 19/07/2024 | 207.4 | | 278 D |
| | | | | | | | | | | | 600 FH/6M INSP. | 4312.1 | 17/12/2023 | 509.2 | | 63 D |
| | | | | | | | | | | | 600 FH/24M INSP. (AF) | 4266.9 | 20/03/2025 | 464.0 | | 522 D |
| | | | | | | | | | | | 600 FH/24M INSP. (ENG NO 1) | 4266.9 | 20/03/2025 | 464.0 | | 522 D |
| | | | | | | | | | | | 600 FH/24M INSP. (ENG NO 2) | 4266.9 | 20/03/2025 | 464.0 | | 522 D |
| | | | | | | | | | | | 7 D INSP. | | 19/10/2023 | | | 4 D |
| | | | | | | | | | | | 1 M INSP. | | 17/10/2023 | | | 2 D |
| | | | | | | | | | | | 6 M INSP. | | 14/11/2023 | | | 30 D |
| | | | | | | | | | | | 12 M INSP. | | 20/06/2024 | | | 249 D |
| | | | | | | | | | | | 24 M INSP. | | 21/06/2025 | | | 615 D |
| | | | | | | | | | | | 30 M INSP. | | 17/02/2025 | | | 491 D |
| | | | | | | | | | | | 48 M INSP. | | 20/07/2026 | | | 1009 D |
| | | | | | | | | | | | 60 M INSP. | | 31/12/2027 | | | 1538 D |
| | | | | | | | | | | | CORROSION CONTROL PROGRAMME (CCP) | | | | | |
| AFS - ENG. RINSING & ENG. WASHING (BOTH ENG) | | | | | | | | | | | | | | | | |
| 25 FH - ENG. CLEANING (BOTH ENG) | | | | | | | | | | | 3803 | 0.1 | | | | |
| SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE | | | | | | | | | | | | | | | | |
| 10 HRS - AEOO 30/22 | | | | | | | | | | | 3812.4 | 9.5 | | | | |
| 660 FH INSP EASB 05.00.56 #3 | | | | | | | | | | | 4340.3 | 537.4 | | | | |
| 50 HRS INSP AEO TM 22/05 | | | | | | | | | | | 3811.1 | 8.2 | | | | |
| COMPONENT | | | | | | | | | | | SERVICING / ANNUAL | | TBO / SLL / OTP | | | |
| RDR ANTENNA SLAVING UNIT, PN: 017-01593-0100, SN: T2004 | | | | | | | | | | | | 12/3/2026 | | 879 D | | |

| | | | |
|---------------------------|-----|------------------------|-----|
| HOURS FLIGHT OF THE DAY | 2.1 | HOURS CTF OF THE DAY | 0.0 |
| CARRY FORWARD | 6.6 | CARRY FORWARD | 0.0 |
| HOURS FLIGHT OF THE MONTH | 8.7 | HOURS CTF OF THE MONTH | 0.0 |

| | |
|--|---------------------|
| | WARNING OVERDUE |
| | WARNING NEARING DUE |

AC LANDING CYCLE
10.831
FUEL
TBA

| | | | |
|-----------------------|---------|------------------|------------|
| Pesawat: Aircraft: | AS555SN | Tarikh: Date: | 15/10/2023 |
|-----------------------|---------|------------------|------------|

Bahagian ini diisi oleh MC
This part is to be filled by MC

BAHAGIAN 2 - STATUS HARIAN PESAWAT
Part 2 - Daily Aircraft Status
Keadaan Pesawat pada jam 0800H
Aircraft State at 0800H

| Pesawat Tail Number | Jam Enjin Eng ISN | Jam Pesawat A/C ISN | Keadaan Semasa Current Status | | | Penangguhan Kerosakan (Jika ada) Deferred Defect (If any) | | | | Rawatan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | | | | | |
|---|----------------------|------------------------|----------------------------------|------------------------------------|--|--|------------------------------|--|------------------------------|--|------------------------|--|----------------------|--------------------|--------------------|-----------------|--|--|--|
| | | | Keadaan State | Tarikh Rosak Date Unserviceable | Buli Kerosakan Details of Unserviceable | Jangka Masa Siap Estimate | Perkara Description | Tarikh Rosak Date Unserviceable | Jangka Masa Siap Estimate | Had Operasi (Jika ada) Operational Limitation | Perkara Description | Terminl Pada Due at | | | Baki Balance | | | | |
| | | | | | | | | | | | | Jam Hr | Kalendar Calendar | | Jam Msc | Hari Day | | | |
| M502-3 5714 | ENG #1 SN: 2408 | 3429.3 | NON OP | 28/6/21 | AIRCRAFT EXPERIENCE HARD LANDING AT RMN BASE | TBN | SCHEDULE INSPECTION | | | | | | | | SEAT CONFIGURATION | | | | |
| | | | | | | | 25 FH INSP. | 3449.1 | | 19.8 | | STANDARD SEATS INSTALLED | | | | | | | |
| | | | | | | | 30 FH INSP. | 3436 | | 6.7 | | | | | | | | | |
| | | | | | | | 50 FH INSP. | 3447.5 | | 18.2 | | ITEM: FLIR | | | | | | | |
| | | | | | | | 100 FH INSP. (AF) | 3449.5 | | 20.2 | | STATUS: REMOVED | | | | | | | |
| | | | | | | | 100 FH INSP. (ENG NO 1) | 3601.6 | | 23.1 | | P/NO.: 10406-06-410 / 10406-06-210 | | | | | | | |
| | | | | | | | 100 FH INSP. (ENG NO 2) | 3498.1 | | 23.1 | | S/NO.: N/A | | | | | | | |
| | | | | | | | 150 FH INSP. (AF) | 3434.1 | | 4.8 | | ITEM: MOUNTING GUN | | | | | | | |
| | | | | | | | 150 FH INSP. (ENG NO 1) | 3648.7 | | 70.2 | | STATUS: REMOVED | | | | | | | |
| | | | | | | | 150 FH INSP. (ENG NO 2) | 3545.2 | | 70.2 | | P/NO.: 3628931480 | | | | | | | |
| | | | | | | | 300 FH INSP. | 3647.8 | | 218.5 | | S/NO.: N/A | | | | | | | |
| | | | | | | | 500 FH INSP. (AF) | 3726.6 | | 297.3 | | ITEM: FLOATATION GEAR | | | | | | | |
| | | | | | | | 500 FH INSP. (ENG NO 1) | 3998.7 | | 420.2 | | STATUS: INSTALL | | | | | | | |
| | | | | | | | 500 FH INSP. (ENG NO 2) | 3895.2 | | 420.2 | | P/NO.: 218570-0(RH) / 218569-0(LH) | | | | | | | |
| | | | | | | | 600 FH INSP. (AF) | 3582 | | 152.7 | | S/NO.: 2742 (LH) & 2785 (RH) | | | | | | | |
| | | | | | | | 600 FH INSP. (ENG NO 1) | 4098.7 | | 520.2 | | ITEM: SPECTROLAB ASSY | | | | | | | |
| | | | | | | | 600 FH INSP. (ENG NO 2) | 3995.2 | | 520.2 | | STATUS: REMOVED | | | | | | | |
| | | | | | | | 150 FH//3M INSP. | 3499.5 | 29/06/2021 | 70.2 | -838 D | P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) | | | | | | | |
| | | | | | | | 150 FH//6M INSP. | 3499.5 | 29/09/2021 | 70.2 | -746 D | S/NO.: N/A | | | | | | | |
| | | | | | | | 150 FH//12M INSP. | 3499.5 | 29/03/2022 | 70.2 | -565 D | ITEM: RESCUE HOIST ASSY | | | | | | | |
| | | | | | | | 500 FH//24M INSP. | 3847.8 | 06/01/2022 | 418.5 | -647 D | STATUS: REMOVED | | | | | | | |
| | | | | | | | 600 FH//6M INSP. | 3949.5 | 29/09/2021 | 520.2 | -746 D | P/NO.: 704A-41-815-056 | | | | | | | |
| | | | | | | | 600 FH//24M INSP. (AF) | 3947.8 | 06/01/2022 | 518.5 | -647 D | S/NO.: N/A | | | | | | | |
| | | | | | | | 600 FH//24M INSP. (ENG NO 1) | 4098.7 | 06/04/2023 | 520.2 | -192 D | ITEM: CARGO SWING | | | | | | | |
| | | | | | | | 600 FH//24M INSP. (ENG NO 2) | 3995.2 | 06/04/2023 | 520.2 | -192 D | STATUS: REMOVED | | | | | | | |
| | | | | | | | 7 D INSP. | | 28/06/2021 | | -839 D | P/NO.: 704A-4181-1027 | | | | | | | |
| | | | | | | | 1 M INSP. | | 28/06/2021 | | -839 D | S/NO.: N/A | | | | | | | |
| | | | | | | | 6 M INSP. | | 02/09/2021 | | -773 D | | | | | | | | |
| | | | | | | | 12 M INSP. | | 02/03/2022 | | -592 D | | | | | | | | |
| | | | | | | | 24 M INSP. | | 29/03/2023 | | -200 D | | | | | | | | |
| 30 M INSP. | | 06/01/2022 | | -647 D | | | | | | | | | | | | | | | |
| 48 M INSP. | | 06/01/2024 | | 83 D | | | | | | | | | | | | | | | |
| 60 M INSP. | | 18/04/2026 | | 916 D | | | | | | | | | | | | | | | |
| CORROSION CONTROL PROGRAMME (CCP) | | | | | | | | | | | | | | | | | | | |
| 25 FH - ENG. CLEANING (BOTH ENG) | 3449.1 | | 19.8 | | | | | | | | | | | | | | | | |
| SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE / PERFORMED ONCE | | | | | | | | | | | | | | | | | | | |
| EASB 05.00.56 REV 1 | 3434.1 | | 4.8 | | | | | | | | | | | | | | | | |
| EASB 67.00.33 REV.0 | 3497.8 | | 68.5 | | | | | | | | | | | | | | | | |
| COMPONENT | | | | | | | | | | | | SERVICING / ANNUAL | | | | TBO / SLL / OTP | | | |
| BATTERY [P/N 151CH-1, 6M, POST: RIGHT&LEFT] | | | | | | | | | | | | 2/9/2021 | | | | -773 D | | | |
| AC LANDING CYCLE | | | | | | | | | | | | | | | | | | | |
| 9.251 | | | | | | | | | | | | | | | | | | | |
| FUEL | | | | | | | | | | | | | | | | | | | |
| TBA | | | | | | | | | | | | | | | | | | | |
| HOURS FLIGHT OF THE DAY | | 0.0 | | HOURS CTF OF THE DAY | | 0.0 | | <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <div style="background-color: red; width: 100px; height: 15px; margin-bottom: 5px;"></div> <div style="background-color: yellow; width: 100px; height: 15px;"></div> </div> <div style="width: 45%;"> <p>WARNING OVERDUE</p> <p>WARNING NEARING DUE</p> </div> </div> | | | | | | | | | | | |
| CARRY FORWARD | | 0.0 | | CARRY FORWARD | | 0.0 | | | | | | | | | | | | | |
| HOURS FLIGHT OF THE MONTH | | 0.0 | | HOURS CTF OF THE MONTH | | 0.0 | | | | | | | | | | | | | |

| | | | |
|-----------------------|---------|------------------|------------|
| Pesawat: Aircraft: | AS555SN | Tarikh: Date: | 15/10/2023 |
|-----------------------|---------|------------------|------------|

Bahagian ini diisi oleh MC
This parts to be filled by MC

BAHAGIAN 2 - STATUS HARIAN PESAWAT
Part 2 - Daily Aircraft Status
Keadaan Pesawat pada jam 0800H
Aircraft State at 0800H

| Pesawat Tail Number | Jam Enjin Eng TSN | Jam Pesawat A/C TSN | Keadaan Semasa Current Status | | | Penangguhan Kerosakan (Jika ada) Deferred Defect (If any) | | | | Rawatan Barisan Kedua Second Line Servicing | | | | Catatan Remarks | | | | |
|------------------------|----------------------|------------------------|----------------------------------|------------------------------------|---|--|------------------------|--|------------------------------|--|------------------------|----------------------|-------------------|--------------------|--|----------|--|--|
| | | | Keadaan State | Tarikh Rosak Date Unserviceable | Butiri Kerosakan Details of Unserviceable | Jangka Masa Slap Estimate | Perkara Description | Tarikh Rosak Date Unserviceable | Jangka Masa Slap Estimate | Had Operasi (Jika ada) Operational Limitation | Perkara Description | Tamat Pada Due at | | | Date | | | |
| | | | | | | | | | | | | Jam Hrs | Kalendar Calendar | | Jam Hrs | Hari Day | | |
| M502-5 5717 | ENG #1 SN: 2296 | 3889.4 | NON OP | 31/7/23 | 600 FH // 24 M INSPECTION AND SKIN REPAIR. INSPECTION IN PROGRESS | 3/11/23 | SCHEDULE INSPECTION | | | | | | | | SEAT CONFIGURATION | | | |
| | | | | | | | | | | | | | | | STANDARD SEATS | | | |
| | | | | | | | | | | | | | | | INSTALLED | | | |
| | | | | | | | | | | | | | | | ITEM: FLIR | | | |
| | | | | | | | | | | | | | | | STATUS: REMOVED | | | |
| | | | | | | | | | | | | | | | P/NO.: 10406-06-410 / 10406-06-210 | | | |
| | | | | | | | | | | | | | | | S/NO.: N/A | | | |
| | | | | | | | | | | | | | | | ITEM: MOUNTING GUN | | | |
| | | | | | | | | | | | | | | | STATUS: REMOVED | | | |
| | | | | | | | | | | | | | | | P/NO.: 3428931480 | | | |
| | | | | | | | | | | | | | | | S/NO.: N/A | | | |
| | | | | | | | | | | | | | | | ITEM: FLOATATION GEAR | | | |
| | | | | | | | | | | | | | | | STATUS: REMOVED | | | |
| | | | | | | | | | | | | | | | P/NO.: 218570-0(RH) / 218569-0(LH) | | | |
| | | | | | | | | | | | | | | | S/NO.: N/A | | | |
| | | | | | | | | | | | | | | | ITEM: SPECTROLAB ASSY | | | |
| | | | | | | | | | | | | | | | STATUS: REMOVED | | | |
| | | | | | | | | | | | | | | | P/NO.: 017500-111(GIMBAL) / 30039(CONTROL BOX) | | | |
| | | | | | | | | | | | | | | | S/NO.: N/A | | | |
| | | | | | | | | | | | | | | | ITEM: RESCUE HOIST ASSY | | | |
| | | | | | | | | | | | | | | | STATUS: REMOVED | | | |
| | | | | | | | | | | | | | | | P/NO.: 704A-41-815-056 | | | |
| | | | | | | | | | | | | | | | S/NO.: N/A | | | |
| | | | | | | | | | | | | | | | ITEM: CARGO SWING | | | |
| | | | | | | | | | | | | | | | STATUS: INSTALLED | | | |
| | | | | | | | | | | | | | | | P/NO.: 704A-4181-1027 | | | |
| | | | | | | | | | | | | | | | S/NO.: 1136 | | | |
| | | | | | | | | | | | | | | | 7 D INSP. | | | |
| | | | | | | | | | | | | | | | 31/07/2023 | | | |
| | | | | | | | | | | | | | | | -76 D | | | |
| | | | | | | | | | | | | | | | -74 D | | | |
| | | | | | | | | | | | | | | | 25 D | | | |
| | | | | | | | | | | | | | | | 602 D | | | |
| | | | | | | | | 572 D | | | | | | | | | | |
| | | | | | | | | 113 D | | | | | | | | | | |
| | | | | | | | | 528 D | | | | | | | | | | |
| | | | | | | | | 1081 D | | | | | | | | | | |
| | | | | | | | | CORROSION CONTROL PROGRAMME (CCP) | | | | | | | | | | |
| | | | | | | | | AFS - ENG. RINSING & ENG. WASHING (BOTH ENG) | | | | | | | | | | |
| | | | | | | | | 3900.5 | | | | | | | | | | |
| | | | | | | | | 11.1 | | | | | | | | | | |
| | | | | | | | | SERVICE BULLETIN / AIRWORTHINESS DIRECTIVE | | | | | | | | | | |
| | | | | | | | | 10 HRS - AEEO 30/22 | | | | | | | | | | |
| | | | | | | | | 3885.5 | | | | | | | | | | |
| | | | | | | | | -3.9 | | | | | | | | | | |
| | | | | | | | | COMPONENT | | | | | | | | | | |
| | | | | | | | | SERVICING / ANNUAL | | | | | | | | | | |
| | | | | | | | | TBO / SLL / OTP | | | | | | | | | | |
| | | | | | | | | STARTER GEN (RH), PN-524-062, S/N-1133 (TBO) | | | | | | | | | | |
| | | | | | | | | 12/12/2027 | | | | | | | | | | |
| | | | | | | | | 1519 | | | | | | | | | | |
| | | | | | | | | AC LANDING CYCLE | | | | | | | | | | |
| | | | | | | | | 11,425 | | | | | | | | | | |
| | | | | | | | | FUEL | | | | | | | | | | |
| | | | | | | | | TBA | | | | | | | | | | |

| | | | |
|---------------------------|-----|------------------------|-----|
| HOURS FLIGHT OF THE DAY | 0.0 | HOURS CTF OF THE DAY | 0.0 |
| CARRY FORWARD | 0.0 | CARRY FORWARD | 0.0 |
| HOURS FLIGHT OF THE MONTH | 0.0 | HOURS CTF OF THE MONTH | 0.0 |

| |
|---------------------|
| WARNING OVERDUE |
| WARNING NEARING DUE |

