

# SAFER CARD

**Name:**

**Report No.:** GAM-/SC/24/0058

**Location:** CAMO - APMM BASE

**Date:** 25 Sep 2024

## Report Type:

Unsafe Condition	<input type="checkbox"/>	Tools Equipment
	<input type="checkbox"/>	Equipment
	<input type="checkbox"/>	Dropped Object
	<input type="checkbox"/>	Stored Energy
	<input type="checkbox"/>	Hygiene
	<input type="checkbox"/>	Hazard
	<input checked="" type="checkbox"/>	Electrical
	<input checked="" type="checkbox"/>	Work Environment
	<input type="checkbox"/>	Others (Specify)

## Remarks for specify:

BURN LIGHT BULB

## Brief Description:

INSUFFICIENT LIGHTING IN CAMO ROOM - APMM BASE. ONLY ONE SIDE OPERATIVE.

## Improvement / Suggestion:

CHANGE LIGHT BULB / WIRING

## Process:

<input type="checkbox"/>	HOD
<input type="checkbox"/>	SM
<input checked="" type="checkbox"/>	FILE

## SMS Dept. Remarks:

Safety Department will email the Admin Department to discuss on how to resolve the issues.

## SMS Updated Dept. Remarks:

--