

**AVP-AERO VOO DE PORTUGAL**

Avionics MRO Repair Facility / EASA Repair Station PT.145.039  
 Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal  
 Tel: +351 219 411 208 Fax: +351 219 411 210  
**www.avp.com.pt** email: [avp@avp.com.pt](mailto:avp@avp.com.pt)  
 VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082

**Orçamento N°**

Quote N°

20234161R

Page 1-2

<b>V. Ref./ Your Ref:</b>	RMN-22-595	<b>Data/Date:</b>	20-Apr-23		
<b>Para/To:</b>	GALAXY AEROSPACE (M) SDN BHD				
<b>Ao cuidado/ Attn of.</b>	Izzati Azmi	<b>Assunto/ Subject</b>	orçamento		
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	C16158AA	14 DATA INDICATOR	N/A	2018	Overhaul

<b>A. Avaria Reportada pelo Cliente/</b> Description of Discrepancy Reported by Client	A.1- PAGE 2
<b>B. Descrição da Avaria feita pela AVP/</b> Description of Discrepancy found by AVP	B.1- PAGE 2
<b>C. <del>Teste e Inspeção /</del> <del>Reparação /</del> <del>Revisão Geral/</del> Inspection and Test / Repair / Overhaul</b>	2376.00 €
<b>D. Material substituído/</b> Material Replaced:	Description
	D.1 Material in page 2 0.00 €
	Broker and Custom Fees Included in point C
	<b>Soma</b> 2376.00 €
	Sum
	<b>Desconto</b> 0.00 €
	Discount
	<b>Valor Final</b> 2376.00 €
	Final Value
	<b>IVA 23%</b> 0.00 €
	Taxes
	<b>Valor Final Com Iva</b> 2376.00 €
	Final Value With Taxes
<b>E. Garantia/</b> Warranty:	O valor monetário usado é Euro
1 year from date of Certificate	<b>Currency quoted in Euro</b>
Warranty is against work done and parts replaced	
<b>F. Entrega/</b> Delivery:	
10 days	
Ex works	
<b>G. Observações/</b> Observations:	
Payment – Proforma Invoice	
Quote is valid for 30 days	
The Unit is sent with Certificate of Conformance and Component Condition Report	

<b>Assinatura:</b>	<input type="checkbox"/>	<b>Aprovado por</b>	2376.00 €
Signature		<b>Approved and proceed by:</b>	
	<input type="checkbox"/>	<b>Entregar Como Está/</b>	598.95 €
		<b>Return As Is</b>	



## AVP-AERO VOO DE PORTUGAL

Avionics MRO Repair Facility / EASA Repair Station PT.145.039  
Rua Salvador Allende N° 3 - 2º Piso, 2685-114 Sacavém - Portugal  
Tel: +351 219 411 208 Fax: +351 219 411 210  
[www.avp.com.pt](http://www.avp.com.pt) email: [avp@avp.com.pt](mailto:avp@avp.com.pt)  
VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082

**Orçamento N°**

Quote N°

20234161R

Page 2-2

<b>V. Ref./ Your Ref:</b>	RMN-22-595	<b>Data/Date:</b>	20-Apr-23		
<b>Para/To:</b>	GALAXY AEROSPACE (M) SDN BHD				
<b>Ao cuidado/ Attn of.</b>	Izzati Azmi	<b>Assunto/ Subject</b>	orçamento		
<b>#</b>	<b>Peça número Part Number</b>	<b>Descrição Description</b>	<b>NNA/NSN</b>	<b>NS/SN</b>	<b>Condição Condition</b>
01	C16158AA	14 DATA INDICATOR	N/A	2018	Overhaul

### A.1 Avaria Reportada pelo Cliente/ Description of Discrepancy Reported by Customer

01-T4 INDICATOR #2 ENGINE INOPERATIVE.

### B.1 Avaria detectada pela AVP/ Description of defects found by AVP

- 01- Malfunction is confirmed
- 02- Indicator % A G2 out of values
- 03- Unit have dirt inside

### C.1 Teste de inspeção e de bancada/ Bench test of unit

- 01-Unit requires to be Overhauled
- 02-During test, unit fails
- 03-Unit requires to be dissassembled
- 04-Clean
- 05-Repaired
- 06-Assembled
- 07-Functional test
- 08-Values registered
- 09-Final Inspection to go back to work

### D.1 Material – Details

Part Number	Description	Qty	TAT	Unit Price	Total Price
				<b>Total</b>	<b>0.00 €</b>