

**AVP-AERO VOO DE PORTUGAL**

Avionics MRO Repair Facility / EASA Repair Station PT.145.039
 Rua Salvador Allende N° 3 - 2º Piso, 2685-114 Sacavém - Portugal
 Tel: +351 219 411 208 Fax: +351 219 411 210
www.avp.com.pt email: avp@avp.com.pt
 VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082

Orçamento N°

Quote N°

20234245R

Page 1-2

V. Ref./ Your Ref:	PO MMA-23-693	Data/Date:	3-Aug-23		
Para/To:	GALAXY AEROSPACE (M) SDN BHD				
Ao cuidado/ Attn of.	Izzati Azmi	Assunto/ Subject	Repair Quote		
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	C16158AA	14 DATA INDICATOR	N/A	1036	Repair

A. Avaria Reportada pelo Cliente/ Description of Discrepancy Reported by Client	A.1- PAGE 2
B. Descrição da Avaria feita pela AVP/ Description of Discrepancy found by AVP	B.1- PAGE 2
C. Teste e Inspeção / Reparação / Revisão Geral / Inspection and Test/ Repair /-Overhaul	1980.00 €
D. Material substituído/ Material Replaced:	Description
	D.1 Material in page 2 0.00 €
	Broker and Custom Fees Included in point C
	Soma 1980.00 €
	Sum
	Desconto 0.00 €
	Discount
	Valor Final 1980.00 €
	Final Value
	IVA 23% 0.00 €
	Taxes
	Valor Final Com Iva 1980.00 €
	Final Value With Taxes
E. Garantia/ Warranty:	O valor monetário usado é Euro
12 months from date of Certificate.	Currency quoted in Euros
Warranty is against work done and parts replaced	
F. Entrega/ Delivery:	
Ex works AVP	
5 days after quote approval	
G. Observações/ Observations:	
Payment – Profrma Invoice	
Quote is valid for 90 days	
Unit is sent with Certificate of Conformance and Component Condition Report	

Assinatura: **Aprovado por** 1980.00 €
 Signature **Approved and proceed by:**

Entregar Como Está/ 598.95 €
 Return As Is



AVP-AERO VOO DE PORTUGAL

Avionics MRO Repair Facility / EASA Repair Station PT.145.039
Rua Salvador Allende Nº 3 - 2º Piso, 2685-114 Sacavém - Portugal
Tel: +351 219 411 208 Fax: +351 219 411 210
www.avp.com.pt email: avp@avp.com.pt
VAT: PT503975249 D-U-N-S: 337835826 CAGE/CORG: P3082

Orçamento Nº

Quote Nº

20234245R

Page 2-2

V. Ref./ Your Ref:	PO MMA-23-693	Data/Date:	3-Aug-23		
Para/To:	GALAXY AEROSPACE (M) SDN BHD				
Ao cuidado/ Attn of.	Izzati Azmi	Assunto/ Subject	Repair Quote		
#	Peça número Part Number	Descrição Description	NNA/NSN	NS/SN	Condição Condition
01	C16158AA	14 DATA INDICATOR	N/A	1036	Repair

A.1 Avaria Reportada pelo Cliente/ Description of Discrepancy Reported by Customer

01-.MGB OIL PRESSURE LOW (BELOW THAN 2 BAR).

B.1 Avaria detectada pela AVP/ Description of defects found by AVP

- 01- Unit have a the pointer bended and sticking
- 02- Unit requires to be open repaired and recalibrated.

C.1 Teste de inspeção e de bancada/ Bench test of unit

- 01- Unit requires to be open.
- 02- Disassembled.
- 03- Clean.
- 04- Repair.
- 05- Lubrificated.
- 06- Assembled
- 07- Painted if needed
- 08- Functional Test
- 09- Values Registered
- 10- Final Inspection to go back to work.

D.1 Material – Details

Part Number	Description	Qty	TAT	Unit Price	Total Price
				Total	0.00 €