



406 Dividend Drive
 Peachtree City, Georgia 30269
 Phone (770) 632-1851
 Fax: (770) 632-1852

Repair Estimate

LOG CARD:	YES <input type="checkbox"/>	NO <input type="checkbox"/>
SPECIAL INSTRUCTION:	<input type="checkbox"/>	<input type="checkbox"/>
UNIT MISUSED:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PICTURES:	<input type="checkbox"/>	<input checked="" type="checkbox"/>

DATE:	13-May-2022
PRIME REFERENCE:	051194
CUSTOMER REFERENCE:	RMN-22-306
PART NUMBER:	7813-177-00-12
SERIAL NUMBER:	702
DESCRIPTION:	INDICATOR
WORK REQUESTED:	REPAIRED

EVALUATIONS / FINDINGS:

TESTED UNIT-CORROSION ON BEZEL RING. VERIFIED SPLIT IN NO. 1 & 2 POINTERS.
 OPENED UNIT FOR INSPECTION - BOTH GEAR TRAINS FOR POINTERS 1 & 2 DIRTY. NR POINTER METERS REQUIRES CLEANING AND BALANCING. BEZEL RING NEEDS CLEANING AND PAINTING.

CORRECTIVE ACTIONS TO BE CARRIED OUT:

REPAIR REQUIRED

PARTS REPLACED OR REPAIRED

EXCLUSIONS: CONDITION AFTER COMPLETION:

PART NUMBER	DESCRIPTION	STATUS	QUANTITY	PRICE

FLAT RATE:

TOTAL QUOTE

TOTAL QUOTE OPTION #1

TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)

EVALUATION FEE IF QUOTE DENIED

COMMENTS:

Approval Signature: _____

Name: _____ Date: _____