



Onezack MRO & Technical Supports (SA0514868-P)
No. 12 Jalan Suria W, U5/W Sek U5, Bandar Pinggiran Subang,
40150 SHAH ALAM Selangor Darul Ehsan, Malaysia.
Tel: +603 78325963 Fax: +603 78325963
Email: amranmajlog@gmail.com

QUOTATION

To : Galaxy Aerospace (M) Sdn. Bhd.
Suite 11-14,
Helicopter Center,
Malaysia Malaysia International Aerospace Centre
Sultan Abdul Aziz Shah Airport
47200 Subang
Selangor Darul Ehsan

Quote Ref : OMTS/GA/MRO/QTE/22(R2)/23

Date : 31st Oct 2023

Your Ref No. : GAM-DO-23-203 Item 01

Date : 11th Sep 2023

Attn: Ms Nor Izzati Azmi

PO Ref.: PO-GAM-MMA-23-765

Date : 28th Aug 2023

Re : QUOTATION FOR THE SERVICING & REPAIR OF DAVID CLARK HEADSETS MODEL H10-13H (QTY 01)

We are pleased to submit our servicing quotation and lead delivery time as below for your consideration:

ITEM	PART NO.	DESCRIPTION	QTY (EA)	U/PRICE (RM)	AMOUNT (RM)	REMARKS
	FOR THE SERVICING AND REPAIR OF:					
1.	12507G-45 (H10-13H)	DAVID CLARK AVIATION HEADSETS Yearly Servicing (1.5 mhrs) S/No.: 1. MMEA/SUS/HS-DC/AW139/08	1	153.00	153.00	
2.	2150004	Mandatory Part Replacement: Ear White Cover	1	28.00	28.00	1 Pair
3.		Repair works: Trouble shooting & Repair works (1.0 mhrs)	1	102.00	102.00	
4.		Other Part Replacement:				
	40863G-02	Gel Ear Seal	1	185.00	185.00	1 pair
	15252P-03	Dome Drilled, LH Headset	1	175.00	175.00	
	18028G-52	Communication Cord Kit	1	785.00	785.00	
	40062G-02	Microphone Protector	1	38.00	38.00	
		Sub Total			1,466.00	
		Sales Service Tax	0%		0.00	
		TOTAL			1,466.00	

REMARKS:

1. Certificate Completion of Work (CCOW) will be issued upon completion of work
2. Price and delivery quoted are Ex-work Onezack MRO & Technical Supports
3. Validity is 30 Days
4. Terms: 30 Days
5. Price quoted are in Ringgit Malaysia

We trust our quotation will receive your favourable consideration.

for **ONEZACK MRO & TECHNICAL SUPPORTS**

LT COL AMRAN MUSA (RETIRED)





DISCREPANCY REPORT

OMTSP-A-05B

REFERENCE NO.: **OMTSP-A-05B** Control No.: **OMTS/GA/DR/EW/09/2023**

1. Item: DAVID CLARK AVIATION HEADSET	2. Part No: 12507G-45 (H10-13H)
3. Serial No: MMEA/SUS/HS-DC/AW139/08	4. Customer: GALAXY AEROSPACE (M)
5. Customer Indent Order: GAM/DO/23/203 Item 1 dtd 11 th Sep 2023	6. Work Required: 6 monthly Servicing Work Order No.: OMTS/EW/0067/23

7. Observation:

- a. Physical & Visual Inspection found that Headset Ear White Cover (P/N: 2150004), Mic Protector (P/N: 40062G-02) & Gel Ear Seal (P/N: 40863G-02) are dirty, torn and wear. The Dome Drilled LH (P/N: 15252P-03) is broken.
- b. Functional Test found that the headset unable to communicate and troubleshooting carried out found that the Communication Cord Kit (P/No.: 18028G-52) is defective.
- c. The defective Communication Cord Kit has been replaced and Functional Test found to be serviceable.

8. Finding:

- a. Ear White Cover (P/N: 2150004) - To be replaced (1 pair)
- b. Mic Protector (P/N: 40062G-02) - To be replaced (1 unit)
- c. Gel Ear Seal (P/N: 40863G-02) - To be replaced (1 pair)
- d. Dome Drilled LH (P/N: 15252P-03) - To be replaced (LH- 1 unit))
- e. Communication Cord Kit (P/No. 18028G-52) - To be replaced (1 set)

QAP / Workshop Supervisor:  Date: **31 Oct 2023**



9. Probably Cause: **Wear & Tear, Broken & Defective**
Refer: **N/A**

10 Recommended Action Required: **All Item Para 8A to 8e to be replaced**

11. Customer Notified reference: **N/A**

(To be completed by Respective Branch and the running number from QA Dept)

Branch Manager:  Date: **31 Oct 2023**



12. Action by Customer: 

Customer Representative: **ROSLAN B. ISMAIL** Date: **02/11/2023**
Eng. Dept. - MMEA

14. Action by QA Department:

QA Manager: Date: