

Quote Number: 225072283 Version 1	Part Number: HUMSREPKIT	Validity Period: 07/18/2022 to 07/28/2022
Customer PO: PO-22-5193	Serial In:	Primary Workscope: REPAIR
Sales order: 550941736	UCN/SER:	Notification: 344590222

CUSTOMER INFORMATION

GALAXY AEROSPACE M SDN BHD
SULTAN ABDUL AZIZ SHAH INTL
MALAYSIA INTL AEROSPACE CENTRE
STE 11-14 HELICOPTER CTR
47000 SUBANG

WARRANTY DETAILS

Warranty Result : WARRANTY NOT APPLICABLE
Applicable Warranty Period:
Adjudication:

CID/FOD/Abuse identified? Yes No

REASON FOR REQUOTE

SHOP-FINAL TEST FAILED OR ADDT'L

WORKSCOPE DEVIATION FROM PO REQUEST?

Yes No

Quote is valid for 10 days from the issue date. For best delivery performance, respond within 5 days.

SELECT AN OPTION:

<input type="checkbox"/> REPAIR Estimated ship date will be 47 Days after payment is received	QUOTE TOTALS \$ 7,400.81
	Parts Totals \$ 6,607.87
	Labor Totals \$ 0.00
<input type="checkbox"/> Optional Selection: Please check this box if you approve an exchange in the event an exchange becomes available before the completion of your unit. Exchanges are subject to availability. You will not receive additional details about the exchange unit including SN, Times, Cycles etc.	Inflation Surcharge \$ 792.94
	Taxes \$ 0.00
<input type="checkbox"/> Return As-Is Uncertified	Total \$ 2894.07
<input type="checkbox"/> Scrap On-site	Total \$ 2894.07

APPROVAL & SIGNATURE REQUIRED

Approve online by launching [Aerospace Order Status](#) or send quote response to our [Quotes team](#).

This estimate is based on initial examinations of the unit and includes labor and material required to perform the work indicated, as well as calibration and testing to meet published specifications and to obtain a release tag. Honeywell reserves the right to make an adjustment to this estimate based on actual material and labor costs incurred. You may indicate approval of this estimate by signing below. Please advise immediately if any relevant AD's are required.

Honeywell offers OEM certified aftermarket units with one year warranty through Honeywell Aerospace Trading (HAT). HAT also purchases certain units beyond economical repair (BER). To obtain a replacement unit, purchase additional spare units, or to inquire as to your unit's value, please contact HAT at if in the United States: 1-866-TALK-HAT (1-866-825-5428); or International: 480-293-9751. You can also inquire online at www.aerospacetrading.com.

Approved By: _____ **Date:** _____

Repair and Overhaul Terms, which are available at aerospace.honeywell.com. Notice: If the Quote is rejected, or in the case of no response within five (5) business days from date of issue to Customer, Honeywell may Return-As-Is/uncertified and the minimum Return-As-Is/Evaluation fee may be assessed. If the Quote is approved and received within five (5) business days, Honeywell will proceed with repairing the equipment at the Quoted Price and invoice the Customer accordingly. No fault found units will be invoiced the Return-As-Is/Evaluation fee and returned to the Customer. Unless covered by an agreement in force between Honeywell and Customer, this quote and any services provided hereunder shall be subject to the Honeywell Repair and Overhaul Terms, which are available at aerospace.honeywell.com.

Quote Number: 225072283 Version 1	Part Number: HUMSREPKIT	Validity Period: 07/18/2022 to 07/28/2022
Customer PO: PO-22-5193	Serial In:	Primary Worksopce: REPAIR
Sales order: 550941736	UCN/SER:	Notification: 344590222

ORDER INFORMATION

Material Out: HUMSREPKIT	Incoterms: EXW SELLER'S	TAT Days: 130 Days
Customer P/N:	Payment Terms: Cash with Order	
Alternate SN:	Currency: USD	
Platform: UNK	Exchange Rate:	
Aircraft Tail No: N565GD	GSI Order:	
Model #: UNKNOWN AC	Applicable Tags: REP FAA 8130-3with Dual Release(Various)	

CUSTOMER UNIT INFORMATION

Customer Reason for Return: INSPECTION, REPAIR, AND CALIBRATION
Condition Received:
Reason for Return Code: TEST
Removal Type:
Last 12 Month PO History None

TEARDOWN/EVALUATION FINDINGS

Non-Conformance: N/A - No Code Selected
Primary Failure :
Findings: REJECTION CONFIRMED

PN: 901-14990 SN: 2196 REJECTION CONFIRMED 1. UNIT WAS RETURNED FOR BUTTONS MALFUNCTIONING AND UNIT TOOK TOO LONG TO POWER DOWN. THIS COMPLAINT IS INTERMITTENT. REPLACE PCB CCA AND HOUSING/KEYPAD.

PN: 901-8620 SN: 2785 TEST/RECERTIFY UNIT PASSED ALL BENCH TESTS. TEST/RECERT ONLY.

COMMENTS / RECOMMENDED CORRECTIVE ACTION:

The surcharge below (if any) has been added due to increases in Honeywell's global supply chain costs. For more information please go to Aerospace.honeywell.com

BREAKDOWN

Quote Number: 225072283 **Version 1** **Part Number:** HUMSREPKIT **Validity Period:** 07/18/2022 to 07/28/2022
Customer PO: PO-22-5193 **Serial In:** **Primary Workscope:** REPAIR
Sales order: 550941736 **UCN/SER:** **Notification:** 344590222

HUMSREPKIT REPAIR FOR HUMSREPKIT				
Repair end outline				
Part Number	Description	Qty	List Price	Extended Price
SRVHUMSREPKIT	REPAIR FOR HUMSREPKIT	1.00	\$ FLAT RATE	\$ 7,400.81
LABOR	REPAIR LABOR HOURS	1.10	\$ FLAT RATE	\$ 0.00
Parts				\$ 7,400.81
Labor				\$ 0.00
Sub Total:				\$ 6,607.87

901-14990 REPAIR FOR HUMS					
Repair sub assembly					
Part Number	Description	Qty	List Price	Discount%	Extended Price
SRV901-14990	REPAIR FOR HUMS	1.00	\$	100%	\$ 0.00
560-13578	INSULATOR BATTERY TUBE	2.00	\$ 61.00	100%	\$ 0.00
610-B1D	BATTERY D CELL 1.5V	4.00	\$ 11.65	100%	\$ 0.00
753-13838	LABEL, BATTERY INDICATOR	1.00	\$ 10.16	100%	\$ 0.00
820-13588	ASSY. HOUSING/KEYPAD	1.00	\$ 1,565.63	100%	\$ 0.00
820-14987	ASSY, PCB/GRAPHICS MODULEV2K TURBO	1.00	\$ 9,854.25	100%	\$ 0.00
LABOR	REPAIR LABOR HOURS	3.20	\$	100%	\$ 0.00
Parts					\$ 0.00
Labor					\$ 0.00
Sub Total:					\$ 0.00

901-8620 REPAIR FOR HUMS				
Test / Inspect sub assembly				
Part Number	Description	Qty	List Price	Extended Price
SRV901-8620	REPAIR FOR HUMS	1.00	\$ FLAT RATE	\$ 0.00
LABOR	REPAIR LABOR HOURS	2.00	\$ FLAT RATE	\$ 0.00
Parts				\$ 0.00
Labor				\$ 0.00
Sub Total:				\$ 0.00

QUOTE TOTALS	Parts Totals	Labor Totals	Totals
HUMSREPKIT REPAIR FOR HUMSREPKIT	\$ 6,607.87	\$ 0.00	\$ 6,607.87
901-14990 REPAIR FOR HUMS	\$ 0.00	\$ 0.00	\$ 0.00
901-8620 REPAIR FOR HUMS	\$ 0.00	\$ 0.00	\$ 0.00
Inflation Surcharge			\$ 792.94
Taxes			\$ 0.00
Quote Total			\$ 7,400.81

Quote Number: 225072283	Version 1	Part Number: HUMSREPKIT	Validity Period: 07/18/2022 to 07/28/2022
Customer PO: PO-22-5193		Serial In:	Primary Workscope: REPAIR
Sales order: 550941736		UCN/SER:	Notification: 344590222

SUPPORTING PHOTOGRAPHS



HUMSREPKIT BOX



HUMSREPKIT CONTENTS