

## 406 Dividend Drive Peachtree City, Georgia 30269 Phone (770) 632-1851 Fax: (770) 632-1852

## Repair Estimate

3-May-2022

DATE:

			PRIM	E REFERENCE:	51192	
	YES NO		CUSTOME	R REFERENCE:	RMN-22-311	
LOG CARD:			P/	ART NUMBER:	H140BLM	
SPECIAL INSTRUCTION:			SER	IAL NUMBER:	12829	
UNIT MISUSED:			1	DESCRIPTION:	GYRO HORIZON	
PICTURES:			WORK	REQUESTED:	OVERHAUL	
EVALUATIONS / FINDINGS:						
ROTOR SPINS. VALID AND VALID INTERLOCK OPERATE. LAPMPS 28VDC OPERATE. ROTOR IS GOOD. SYNCHROS OPERATE.						
REDUCTION ASSEMBLY IS ACCEPTABLE. GIMBAL BEARINGS ARE ROUGH AND DENTED.						
CORRECTIVE A CTIONS TO BE CARRIED OUT						
	CORRECTIVE ACTIONS TO BE CARRIED OUT:					
STANDARD OVERHAUL NEE	STANDARD OVERHAUL NEEDED					
PARTS REPLACED OR REPAIRED						
	CONDITION AFTER					
EXCLUSIONS:	CLUSIONS:		CONDITION AFTER COMPLETION:		OVERHAULED	
PART NUMBER	DESCRIPT	ION	STATUS	QUANTITY	PRICE	
PART NOWIDER	DESCRIPT	ION	314103	QUANTITI	PRICE	
		7				
FLAT RATE:		1	COMMENTS:			
FLAT RATE:			COMMENTS:			
FLAT RATE: TOTAL QUOTE	\$3,500.00	]	COMMENTS:			
	\$3,500.00	]	COMMENTS:			
TOTAL QUOTE	\$3,500.00	]	COMMENTS:			
TOTAL QUOTE	\$3,500.00	]	COMMENTS:			
TOTAL QUOTE  TOTAL QUOTE  OPTION #1			COMMENTS:			
TOTAL QUOTE  TOTAL QUOTE OPTION #1  TURN AROUND TIME	\$3,500.00	] ] ] 				
TOTAL QUOTE  TOTAL QUOTE  OPTION #1  TURN AROUND TIME  AFTER APPROVAL:		] ]	COMMENTS:			
TOTAL QUOTE  TOTAL QUOTE OPTION #1  TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)						
TOTAL QUOTE  TOTAL QUOTE  OPTION #1  TURN AROUND TIME  AFTER APPROVAL:		٦			ate:	