

DETAILS O	F (	OCCURRENCE							
Date	:	24/09/2021	Time	:	1240 HRS	Location	:	Bertam	
DETAILS OF AIRCRAFT/COMPONENT									
Aircraft type	:	AW139	Aircraft Regn.	:	9M-BOD	MSN	:	31291	
Component Name	:	N/A	Part Number	:	N/A	MSN	:	N/A	
Total time	:	2942:10	Total Cycles	:	N/A	Total Landing	:	5283	
Reported by									
Name	:	Mohamad Razif	Designation/ Staff No	:	8015	Date	:	24/09/2021	
DESCRIPTI	10	OF INCIDENT/A	CCIDENT/PR	OE	BLEM				
Land	ding	g Gear tire burst.	J		tion 9M-BOD (SN: 31	, .			
2. Obs land Berta land 3. Obs apro	ding erved am ing erven	g Gear tire burst.  vation before and back in Bertam ba base at 0940 hou gear tire burst an  vation post incide	I during incid ase for training ars. During lan d immediate a ent: The aircra n immediately.	en g (A din action aft a	t: The aircraft was flow AQM Currency Checking, the AQM informed on taken by the ground arrived at Bertam Basetail inspection was possible.	wn from Be ). The aircra the marsha nd crew to e se at 1240 b	erta aft alle ens	m base and departed from r RH main ure safe landing. irs, landed on the	
2. Obs land Berta land 3. Obs apro	ding erv am ing erv n a ing	g Gear tire burst.  vation before and back in Bertam ba base at 0940 hou gear tire burst an vation post incide area and shutdowr gear tire burst du	I during incid ase for training ars. During lan d immediate a ent: The aircra n immediately.	en g (A din action aft a	t: The aircraft was flow AQM Currency Checking, the AQM informed on taken by the ground arrived at Bertam Basetail inspection was possible.	wn from Be ). The aircra the marsha nd crew to e se at 1240 b	erta aft alle ens	m base and departed from r RH main ure safe landing. irs, landed on the	

**ATTACHMENTS:** □ Report ⊠ Photo □ Video □ Others, specify:



# **IMMEDIATE CORRECTIVE ACTION BY AMO/CAMO**

- 1. Tire to be replaced. 1 unit of tire was dispatched from GAM Subang on 24/09/2021. (Note: Tire had been replaced on 25/09/2021).
- 2. To perform NDT inspection for wheel hub assembly.
- 3. CVFDR to be downloaded.





ATTACHMENTS: ☐ Report ☒ Photo ☐ Video ☐ Others, specify:
INVESTIGATION BY CRISIS MANAGEMENT TEAM



FOR QAM USE								
Report Category	<ul> <li>✓ Mandatory Occurrence Report (MOR)</li> <li>□ In Service Difficulty Report (ISDR)</li> <li>✓ Internal Occurrence Report (OR)</li> </ul>							
Reportable to authority		Reported to Authority	:					
Reportable to operator		Reported to Operator	:					
Reportable to TC Holder/ STC Holder/ DOA	☐ Yes ☐ No Date	Reported	:					
CORRECTIVE	PREVENTIVE ACTION	N RECOMMENDATION						
Crisis Manager	nent Team Minutes of M	eeting attached:						
REPORT COMP	ILED BY :							
Name:								
Stamp:								



Date:
Review, Accepted and closed by QAM:
Name:
Stamp:
Date: