

# DAMAGED TOOL / EQUIPMENT REPORT


Report No.: TD - 2024-02-283

REPORT INFORMATION		
Date Reported: <p style="text-align: center;">25.1.2024</p>	Date Damaged: <p style="text-align: center;">25.1.2024</p>	Department: <p style="text-align: center;">ENGINEERING</p>
Base: <p style="text-align: center;">MIAT</p>	Category of Tool / Equipment: <p style="text-align: center;">GENERAL TOOL</p>	Name of EIC / Supervisor: <p style="text-align: center;">MUHAMMAD</p>

TOOL / EQUIPMENT INFORMATION		
Description: <p style="text-align: center;">NO. 1 PHILIP BIT</p>	ID Number: <p style="text-align: center;">N/A</p>	Part Number: <p style="text-align: center;"><del>APEX 2</del> 446-2X</p>
Serial Number: <p style="text-align: center;">N/A</p>	Manufacturer / OEM: <p style="text-align: center;">APEX</p>	Location: <p style="text-align: center;">MIAT (STORE)</p>

Damaged Description:  
SCREW BIT TIP'S BROKEN.

\*Please attached picture/photo of damaged tool or equipment (if any).

REPORTED BY:		
Name: <p style="text-align: center;">MUHAMMAD</p>	Signature 	Date <p style="text-align: center;">25.1.2024</p>
Remarks:		

VERIFIED AND ACTION BY:		
Name:	Signature	Date
Remarks:		