



DAMAGED TOOL / EQUIPMENT REPORT

Report No.: TD - 2024 - 02 - 311

REPORT INFORMATION		
Date Reported: 3/4/2023	Date Damaged: 3/4/2023	Department: PGU AW139
Base: PGU SUBANG	Category of Tool / Equipment:	Name of EIC / Supervisor: AINUDIN

TOOL / EQUIPMENT INFORMATION		
Description: SPECIAL TOOLS MR	ID Number: STF 117	Part Number: 366205626631
Serial Number: STF 117	Manufacturer / OEM: LOC FAB	Location: PGU SUBANG
Damaged Description: DAMAGE AND WORN AT GEAR.		
*Please attached picture/photo of damaged tool or equipment (if any).		

REPORTED BY:		
Name: AINUDIN	Signature: 	Date: 4/4/2023
Remarks:		

VERIFIED AND ACTION BY:		
Name: FADZLIE ADAM	Signature: 	Date: 20 APR 2023
Remarks: ITEM WILL BE SENT FOR REPAIR		

MOHD FADZLIE ADAM
 Tools & GSE Supervisor
 Galaxy Aerospace (M) Sdn. Bhd.