

GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Sheet:

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.

Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia

International Aerospace Centre, SAAS Airport,

Subang Malaysia

Attention: Mr. Syafrul Yamani

Engineering Manager

syafrul@galaxyaerospace.my

Work Order Number:	2022-12226
Work Pack Reference:	9M-PMB-12226
Date Issued:	02/08/2022
A/C Registration / SN:	9M-PMB/31726

of

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	RECTIFICATION TAIL BOOM FOUND CORROSION -	NCR/AW/AS/ARS/2021/11/SURV2022/03	(PLEASE ADVISE)
	NCR CAAM		

Remark/Notes:

- 1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] SALANT AEMOSTACE (m) SDIT. SRID.: [104U262-U] Suite 11-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my l nal Aerospace Centre,

WORKPACK

CLIENT/OWNER: ROYAL MALAYSIA SERIAL NO. HOURS LDG/CYCLE WORKPACK NO: 9M-PMB-12226 **POLICE** 31726 WORK/INSP/DESC: CORROSION **AIRCRAFT** AIRCRAFT TYPE: AW139 AERONET JOB NO.: 2022-12226 PCE-KB1830 REGISTRATION: 9M-PMB #1 ENGINE: AJL REF NO.: BASE/FACILITY: WMSA #2 ENGINE: PCE-KB1832 PAGE 01 OF 01 SHEET: DATE IN: OUT: NF/N2 NG/N1 Other requirements/information: Reason for raising: Raised by and date: TAIL BOOM FOUND CORRODED DURING SURVEY AUDIT BY CAAM. RECTIFICATION NII CAMO; Zulkarnaen CARRY OUT I.A.W AW139 IETP - 41TH ISSUE DATED 2022-06-28 UPDATE DATE Ibrahim 2022-07-20 OR LATER APPROVED REVISIONS. 02/08/2022 List of scheduled inspection and all work carried out under this workpack Master Signature Schedule DATE including individual reference INSPECTION COMPLETED NO. INSPECTION / WORK WORKSHEET REF NAME SIGNATURE APP/STAMP 1 RECTIFICATION TAIL BOOM CORRODED 12226-001 NAME PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND SIGN & APPROVAL * OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE *IF DIFFERENT FROM ABOVE. OEM PUBLICATION/REVISION..... FIRM DATE * TICK WHERE APPLICABLE PART M - CAMO ACCEPTANCE STATEMENT NAME SIGN & APPROVAL THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE.



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] GALAXY AEHUSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7526
www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WODKCHEET

١	V	7	U	Г	1 L	10	ЭF		

CLIENT/OWNER: ROYAL MALAYSIA WORKSHEET NO: SERIAL NO. **HOURS** LDG/CYCLE 12226-001 **POLICE** WORK/INSP/DESC: 31726 **AIRCRAFT** REFER WORKPACK **RECTIFICATION TAIL** AIRCRAFT TYPE: AW139 WORKPACK REF: 9M-PMB-12226 PCE-KB1830 REFER WORKPACK #1 ENGINE: REGISTRATION: 9M-PMB AJL REF NO.: REFER WORKPACK PCE-KB1832 REFER WORKPACK BASE/FACILITY: WMSA #2 FNGINE SHEET: DATE IN: REFER WORKPACK 1 OUT: REFER WORKPACK 1 OF NG/N1 NF/N2 Reason for raising: Raised by and date: Other requirements/information: TAIL BOOM FOUND CORRODED DURING SURVEY AUDIT BY CAAM, RECTIFICATION CAMO; Zulkarnaen NIL CARRY OUT I.A.W AW139 IETP - 41TH ISSUE DATED 2022-06-28 UPDATE DATE Ibrahim 2022-07-20 OR LATER APPROVED REVISIONS. 02/08/2022 Technician * Eng. CRS Item Description Date 1 TAIL BOOM CORROSION RECTIFICATION AS PER NO. 3 NCR BY CAAM, CORROSION BUILD-UP ON THE LOWER SURFACE OF THE TAIL BOOM AREA AND SIGN OF TURNING INTO CORROSION POWDER. TO RECTIFY CORROSION AREA AND CARRY OUT PREVENTIVE ACTION. REFERENCE: 39-A-20-84-04-00A-31AA-D NOTE: PLEASE ATTACHED PICTURE OF CORROSION AREA AFTER PREVENTIVE ACTION. REMARKS: *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service ☐ TICK ✓ WHERE APPLICABLE GROUND TORQUE MONITORED PLANNING AIRCRAFT ENGINE LOG OEM/COMP MOD RECORD LABELED & RETURNED INSP RUN FORECAST LOG BOOK LOG CARD



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] nal Aerospace Centre.



SALDAT AEROSTACE (m) SDIT. SRIL: [104U252-U] Suite 11-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my| enquiry@galaxyaerospace.my CLIENT/OWNER: ROYAL MALAYSIA SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 12226-001 POLICE 31726 REFER WORKPACK AIRCRAFT WORK/INSP/DESC: RECTIFICATION TAIL AIRCRAFT TYPE: AW139 PCE-KB1830 REFER WORKPACK WORKPACK REF: 9M-PMB-12226 #1 ENGINE: REGISTRATION: 9M-PMB REFER WORKPACK PCF-KB1832 BASE/FACILITY: WMSA #2 ENGINE: REFER WORKPACK AJL REF NO.: DATE IN: REFER WORKPACK OUT: REFER WORKPACK SHEET: OF NG/N1 NF/N2 Reason for raising: Raised by and date: CAMO; Zulkarnaen Other requirements/information: TAIL BOOM FOUND CORRODED DURING SURVEY AUDIT BY CAAM, RECTIFICATION NIL CARRY OUT I.A.W AW139 IETP - 41TH ISSUE DATED 2022-06-28 UPDATE DATE Ibrahim 2022-07-20 OR LATER APPROVED REVISIONS. 02/08/2022 Serial Number Lifed Item Information Item Part No. Description Qty Position Reason Release Reference TSN/TSO/DUE/TIMEX Off On NAME FIRM SIGN & APPROVAL DATE *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

☐ TICK ✓ WHERE APPLICABLE																	
PARTS LABELED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHTTEST	TORQUE CHK.	ADDITIONAL WORKSHEET		PLANNING FORECAST						PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD RECORD BOOK