







CLIENT/OWNER: MALAYSIAN MARITIME ENFORCEMENT AGENCY	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO:	UW/M72-02/22-085
AIRCRAFT TYPE: AW139	AIRCRAFT	31315	4046.9	4512	WORK/INSP/DESC:	FLIR INSTALLED
REGISTRATION: M72-02	#1 ENGINE:	PCE-KB0740	4046.9	N/A	WORKPACK REF:	N/A
BASE/FACILITY: APMM,WMSA	#2 ENGINE:	PCE-KB0732	4046.9	N/A	AJL REF NO.:	315-002226
DATE IN: 16/11/22	OUT: 16/11/22			NG / N1	NF / N2	SHEET: 1 OF 2





Reason for raising: FLIR TO BE INSTALLED	Raised by and date: YIM 16/11/22	Other requirements/information: N/A
REF W/S: UW/M72-01/22-066		

Item	Description	Technician	* Eng. CRS	Date
1)	FLIR TFW INSTALLED I.A.W AMP-39-A-93-52-01-00A-720A-K. PANEL 213AL INSTALLED I.A.W AMP-39-A-06-41-00-00A-010A-A. LOOSE ARTICLE CHECK CARRIED OUT. FOUND SATISFACTORY.	 GAM M016 DGTA	 GAM M017 DGTA	16/11/22
2)	FLIR CEU INSTALLED I.A.W AMP-39-A-93-52-02-00A-720A-K. PANEL 160CL AND 160LL INSTALLED I.A.W AMP-39-A-06-41-00-00A-010A-A. THING ^{EIE#} LOOSE ARTICLE CHECK CARRIED OUT. FOUND SATISFACTORY.	 GAM M016 DGTA GAM M016 DGTA EIE#	 GAM M017 DGTA	16/11/22
3)	FLIR HCU INSTALLED I.A.W AMP-39-A-93-55-04-00A-720A-A. FOUND SATISFACTORY.	 GAM M016 DGTA	 GAM M017 DGTA	16/11/22
4)	LOOSE ARTICLE CHECK CARRIED OUT. ALL TOOLS RETURNED AND WORKING AREA CLEANED. FOUND SATISFACTORY.	 GAM M016 DGTA	 GAM M017 DGTA	16/11/22
5)	THERMAL IMAGING SYSTEM OPERATIONAL CHECK CARRIED OUT I.A.W AMP-39-A-93-52-00-00A-320A-K. FOUND SATISFACTORY.	 GAM M016 DGTA	 GAM M017 DGTA	16/11/22

- The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual.
- The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenance Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual

The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

REF. NO: R 000911	
ART NO: 3204853-4	SERIAL NO: 3431283
DESCRIPTION: HCU	
TSN: N/A	TSR: N/A
REMOVE FROM AIRCRAFT	
TYPE: AW139	REGISTRATION: M72-01
SERIAL NO: 31307	
AIRFRAME HRS AND CYCLE AT REMOVAL: 4375.5	REMOVAL DATE: 16/11/22
NAME: YIM	
GN & STAMP: 	DATE: 16/11/22
INSTALLED TO AIRCRAFT	
TYPE: AW139	REGISTRATION: M72-02
SERIAL NO: 31315	
AIRFRAME HRS AND CYCLE AT INSTALLATION: 4046.9	INSTALLATION DATE: 16/11/22
NOTE: REF W/S: 4W/M72-01/22-060	
SPECIAL INSTRUCTION:	
NAME: YIM	
GN & STAMP: 	DATE: 16/11/22
*Item removed from serviceable aircraft or component are rendered serviceable and fit for release to service unless found otherwise	

REF. NO: R 000909	
PART NO: 3290003-553	SERIAL NO: 3411283
DESCRIPTION: TFU	
TSN: N/A	TSR: N/A
REMOVE FROM AIRCRAFT	
TYPE: AW139	REGISTRATION: M72-01
SERIAL NO: 31307	
AIRFRAME HRS AND CYCLE AT REMOVAL: 4375.5	REMOVAL DATE: 16/11/22
NAME: YIM	
SIGN & STAMP: 	DATE: 16/11/22
INSTALLED TO AIRCRAFT	
TYPE: AW139	REGISTRATION: M72-02
SERIAL NO: 31315	
AIRFRAME HRS AND CYCLE AT INSTALLATION: 4046.9	INSTALLATION DATE: 16/11/22
NOTE: REF W/S: 4W/M72-01/22-060	
SPECIAL INSTRUCTION:	
NAME: YIM	
SIGN & STAMP: 	DATE: 16/11/22
*Item removed from serviceable aircraft or component are rendered serviceable and fit for release to service unless found otherwise	

CANNIBALIZATION



REF. NO: **R 000910**

ART NO:
3203134-532

SERIAL NO:
3421283

DESCRIPTION: **CEU**

TSN	TSR	TSO
N/A	N/A	N/A

REMOVE FROM AIRCRAFT

TYPE	REGISTRATION	SERIAL NO
AW139	1M72-01	31302

AIRFRAME HRS AND CYCLE AT REMOVAL	REMOVAL DATE
4375.5	16/11/22

AME: **YIM**

GN & STAMP:   DATE: **16/11/22**

INSTALLED TO AIRCRAFT



TYPE	REGISTRATION	SERIAL NO
AW139	1M72-02	31315

AIRFRAME HRS AND CYCLE AT INSTALLATION	INSTALLATION DATE
4046.9	16/11/22

NOTE: **REF W/S: uw/1M72-01/22-060**

SPECIAL INSTRUCTION:

AME: **YIM**

GN & STAMP:   DATE: **16/11/22**

Item removed from serviceable aircraft or component are rendered serviceable and fit for release to service unless found otherwise



CLIENT/OWNER: MALAYSIAN MARITIME ENFORCEMENT AGENCY	SERIAL NO. 31315	HOURS 4046.9	LDG/CYCLE 45/2	WORKSHEET NO: UWM72-02/22-085
AIRCRAFT TYPE: AW139	AIRCRAFT			WORK/INSP/DESC: FLIR INSTALLED
REGISTRATION: M72-02	#1 ENGINE: PCE-KB0740	4046.9	N/A N/A	WORKPACK REF: N/A
BASE/FACILITY: APMM,WMSA	#2 ENGINE: PCE-KB0732	4046.9	N/A N/A	AJL REF NO: 315-02226
DATE IN: 16/11/22 OUT: 16/11/22			NG / N1 NF / N2	SHEET: 1 OF 1

REASON FOR RAISING: FLIR TO BE INSTALLED
 REF W/S : 4W/M72-01/22-066

Raised by and date: Y/M 16/11/22

Other requirements/information: N/A

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
01	3290007-553	TFU	N/A	3411783	01	NOSE	OPS REQ	N/A	EX M72-01
02	3203134-532	CFU	N/A	3421283	01	AFT CABIN	OPS REQ	N/A	EX M72-01
03	3204853-4	HCU	N/A	3431283	01	CABIN	OPS REQ	N/A	EX M72-01

NAME	FIRM	SIGN & APPROVAL	DATE
Y/M	GAM		16/11/22

- The work recorded above has been carried out in accordance with the AW139 Interactive Electronic Technical Publication (IETP), Air-vehicle Maintenance Planning Information (AMPI) - EASA and PT6C-67C Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS555SN Maintenance Manual, Airbus AS555SN Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arrius 1 A Maintenance Manual.
- The work recorded above has been carried out in accordance with Super Lynx Compound Interactive Electronic Technical Publication (CIETP) and CTS800-40N Engine Maintenance Manual.
- The work recorded above has been carried out in accordance with the Airbus AS365N3 Maintenance Manual, Airbus AS365N3 Airworthiness Limitations Section (ALS) and Master Servicing Manual (MSM) and Arriel 2C Maintenance Manual

The work recorded above has been carried out in accordance with the requirements of the Technical Airworthiness Management Manual (TAMM) for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.