

	Audit Report			
	Report No.	IAR-2023/042		
i	Area / Scope	GAM – JBPM BERTAM		
ĺ	Date of audit	31 MAY - 01 JUNE 2023		

A	AUDIT DETAILS			
		Tick where applicable		
1.	Audit Type / Category	☑ Scheduled☐ Surveillance		Vendor Product Variation to approval
		 Specify: Annual audit GAM – JBF	PM Bertam	n, Pulau Pinang.
2.	Audit Reference	 CAD 8601 Maintenance Org 2022 GAM/CAAM/MOE Issue 3 R GAM/EPM/AMO/Issue.2 Rev 145 Audit Checklist GAM/Q- 	ev 1, Date v 3, Dated	Dec 2022
3.	Auditor(s)	Noorsuhada Latef (Lead Aud Yusof Bin Ahmad	ditor)	
4.	Auditee(s)	 Mohamad Razif bin Roslan Rafizal bin Ramli Rose Azreena binti Roslee 		
5.	Location	Hangar Pangkalan Udara JBPM I Kepala Batas, Pulau Pinang.	Bertam, Ja	alan Pinang Tunggal, 13200
В	AUDIT SUMMAR	Y		
1.	General Inform	ation_		
	accordance with	the GAM Audit Plan 2023. The a	audit's ob	to an internal annual audit in jective was to monitor the JBPM uacy for approved line and base
				latest revision of Maintenance Manual (EPM) and AMO Audit
	, ,	ocuments/products, interviews all employed as part of the aud		ditee, and inspection of the ology.

GAM/Q-009 Rev. 2 (07/21) Page 1 of 11



Audit Report				
Report No.	IAR-2023/042			
Area / Scope	GAM – JBPM BERTAM			
Date of audit	31 MAY - 01 JUNE 2023			

maintenance, repair, overnaul

2. Facilities

- a. Currently facilities consist of the 1 (one) approved hangar to carry out AW189 and A109E line maintenance check and AW139 for line and base maintenance check. Refer Figure 1.
- b. Office area accommodate 2 registered PCs, 3 laptops, 1 printer and internet connection for production planner and maintenance personnel to carry out planning. Refer Figure 1.
- c. The hangar cleanliness of the hangar was well maintained with dust and contamination is kept to a minimum.
- d. Holding racks and trestles were available and sufficient for base maintenance. Refer Figure 2.
- e. The ambient lighting was in poor condition during a certain period of daylight. Right side hangar facing forward area designated to perform schedule maintenance was affected by the lighting. Approximate 40% of the hangar overhead bulb was blown and will affect the ambient light during maintenance performed. (NCR 01).
- f. PPE kit consist of earmuffs, raincoat, safety shoes and safety vest are available when needed. Refer Figure 3.
- g. Production waste containers were also available at the hangar. The containers were clearly labelled to differentiate between general and schedule waste. Refer Figure 4.

3. Personnel/Certifying Staff

- a. A total of seven (7) personnel have been assigned to the GAM JBPM Bertam operation, which includes three (3) Approval Holders, three (3) technicians, and one (1) planner.
- b. Below are the details of personnel involved in JBPM Bertam:

No.	Name	Position
1	Mohamad Razif bin Roslan	B1.3 LAE / EIC
2	Rafizal bin Ramli	B2 LAE
3	Sumant A/L Subramaniam	B1.3 LAE
4	Muhammad Saufi bin Mahat	Technician
5	Shaiful Syazwan bin Saleh	Technician
6	Muhamad Zamri bin Awang	Technician
7	Rose Azreena binti Roslee	AMO Planner

GAM/Q-009 Rev. 2 (07/21) Page 2 of 11



maintenance . repair . overhaul

	Audit Report			
	Report No.	IAR-2023/042		
i	Area / Scope	GAM – JBPM BERTAM		
	Date of audit	31 MAY - 01 JUNE 2023		

c. Two (2) Certifying Staff and One (1) technician training record were sampled and found unsatisfactory during the audit. The Auditee (Mr Razif, Mr Sumant, Mr Zamri) didn't attend the latest MOE issue 3 and the latest EPM issue 2. (NCR 02)

4. Equipment, Tools & Materials.

- a. The tool store area was sufficient to accommodate the serviceable spares, quarantine, unserviceable spares, special tools, and calibration tools. During base check, the tool store will store the passenger seats. Several holding racks are available to allocate the tools and spares. Refer Figure 5.
- b. The temperature and humidity were controlled and recorded in daily operation. Refer Figure 5.
- c. 2 Toolbox Snap-on and proto are stationed for daily operation used.
- d. Tool Control register (GAM/E-025 Rev. 1) is available for any booked out of the tools and equipment. Refer Figure 6.
- e. GAM MIAT Tools Store issued and registered the list of tools & GSE for GAM JBPM -Bertam while the EIC shall ensure that the tools and equipment properly controlled and recorded (included general, calibrated, special & GSE list). Reviewed of JBPM, GSE, Calibrated & Special Tools Master List Bertam (GAM/E-016 Rev 01 (01/22) was found satisfactory. Refer picture 6.
- f. The tools and GSE were labelled with serviceable tag and found satisfactory.
- g. One (1) POL cabinet found available. The POL master list was updated accordingly by the personnel in-charge. Refer Figure 7.
- h. Component acceptance (spare parts) was made at Warehouse GAM-HQ operation.

5. Maintenance Data/ Documentation

- a. The publication master listing (GAM/P-2023-14) dated 22 May 2023 was reviewed during the audit, each document in the list was verified in the registered PCs (GAM/IT_ASSET/H130, H128) and laptops (GAM/IT_ASSET/H132, H180, and H390) were found satisfactory.
- b. Daily Maintenance Book was available and reviewed. However, the detailed entries of task completion were too simplified. The Auditee has been briefed to detail the task done in the remark column. Refer to Figure 8. (Observation)
- Toolbox meeting attendance sheet last day entries was not completed. The Auditee has been briefed to improve and update the attendance daily. Refer to Figure 8 for before and after rectification (Observation)
- d. During the audit, aircraft registration 9M-BOC was continuing 1Y schedule inspection, sampled of work pack (9M-BOC-15212) was reviewed, there was minor correction is applied in situ.




	Audit Report
Report No.	IAR-2023/042
Area / Scope	GAM – JBPM BERTAM
Date of audit	31 MAY - 01 JUNE 2023

6.	Conclusion
	There were two (2) minor NCR and no major findings raised during this audit, and two(2) OBSERVATIONS were raised during this audit. The audit was determined to be satisfactory in general.
С	PREPARATION AND APPROVAL
1.	Prepared by
	Signature: Date: 16 JUNE 2023
	Name: NOORSUHADA BINTI LATER Quality Assurance Inspective Galaxy Aerospace (M) Sdn, 資內值, (1040262-D)
2.	Approved by Approved by
	Signature: Date: 16 JUN 2023
	DATO' SHAMSUL KAMAR BIN SAMSUDIN Name: MANAGING DIRECTOR/ACCOUNTABLE MANAGER Galaxy Aerospace (M) Sdn. Bhd. (1040262-D)




maintenance , repair , overhaul

Audit Report				
Report No.	IAR-2023/042			
Area / Scope	GAM – JBPM BERTAM			
Date of audit	31 MAY - 01 JUNE 2023			



JBPM Approved Hangar






Office Area

Figure 1: Facilities



Audit Report				
Report No.	IAR-2023/042			
Area / Scope	GAM – JBPM BERTAM			
Date of audit	31 MAY - 01 JUNE 2023			








Figure 2: Holding rack and trestle




maintenance . repair . overhau

	Audit Report			
Report No.	IAR-2023/042			
Area / Scope	GAM – JBPM BERTAM			
Date of audit	31 MAY - 01 JUNE 2023			





Figure 3: PPE kit








Figure 4: Waste Container




	Audit Report
Report No.	IAR-2023/042
Area / Scope	GAM – JBPM BERTAM
Date of audit	31 MAY 01 JUNE 2023













	-	MAY LOLI						
	A TRACE	100	See was	THE PARTY.			HOUSETY	Secretary.
Ţ.,	47.0	23.4	sor.	4- 1			4.75	رورات
	~*1*		SITE	4	1710		17 %	,22
	53 1 3 to		60%	14	1714		432	
-	27.57	43 2	< Y7.	- 4	2		- Pr	
	77.57	1 2	0 1 7.	4				
	172	1			I	<u> </u>		
-		1	1	1		J		1
	9.710	1	04.0	1 80.	175.0	<u> </u>	147	1 71
	2110	1 22	1 10/4	1 6	1110	32.7	1 200	+-1 37
	0110	1	1.0	1 4	1,940	77.5	66.7	
	0.32	26.2	1.4 %		131	3 2 - 1	1	1 3
	10000	5.3	1.0 7	4	1604	1.3.2		- -
		- 200					1	-
					T		1 52 -2	
	0440	(a) - G	2 - 73	4	174 144	7	155 7	
4.11		1,523.0	6 - 7	1 4	179.	22.9	1.5.4	
100	9.25	21.0	44 '		13.7-	77.5	1 20.0	
(মুক্তু	00 10	21.12			47.10	2 2 2	5.2.2	
333	100 40	12		*	13.3=	2.1		
								\rightarrow
120	Som					_		2 1
1 Dec	A	23.1	647	- 4	1 724	1222.9	1 50	
1782	S. South	- 3-			47.00	1 23 . 6	75-	7 8
II Michiel	ALTERNA .				112.00	1 2 - 2		7 9
S SEE	30 14 December 1			/ L	100			/
11/2	-	52.		· · · · · · · · · · · · · · · · · · ·	1100		4.6	<u> </u>
1200	1000	72.		- 1 - 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1- 1				1
200	MERCHANIS NO.					1		-
			<u>- 1 - 66</u>	7	133	1.22	- 67	
3 S					1786	122.	5 5	£
100		22					4	7
PART	the state of					METER .		
33654	The state of	San I		1	THE RESERVE			
化数	Sec. 19	24.11.412 24.11.412		IN PROPERTY AS I				
	March March 1	222 M						

Figure 5: Tool store


GalaxyAerospace ** maintenance.repair.ovenber 1

Audit Report						
Report No.	JAR-2023/042					
Area / Scope	GAM – JBPM BERTAM					
Date of audit	31 MAY - 01 JUNE 2023					










			т				\neg		*		1.3	≕						,
			1.		٠			===	15	=-	Ŀ	Ξ.	=	7	=	[E	[]	! -
			L	**		****				* > * .	T	-	***	1	200			150
	- Co., c, page 4,	·	£	h A		****		,,,,	411		17			100	ALV.		1.5	
						***	- 411			24/	11	\$	*1.		/ALT			
			1_	****	1.	-		٠.			1::	1 34	***		14:2		u	-
	to fire the state	75.	Ŧ	* *	1	7.		٠.			4	1	244		:		40	_
_	4.74		1	40.0757	1.400				1		1	14	3:3				-	
-	*** *** *** ***		-	25.5	+-									74.00			**	-
			1	-:-								Ξ		0771				-32
_	7p. 4 p. 7		4	-::- -				••				1		25.00			*	₩.
	******		·ł-		4			-		-		Ξ	17.				15	3
: ¬	497167	44-14W	+-			÷				2211		3	177					~
ľ	*********	44.07.411	+		1	7.4		∺		Pat 1				41.5			r«	
Η.			-ì-	~÷÷	·								11.	-1-			×.	ì
			4					· · · ·	1.141-	25.7	144			1	114	-	15	Let.
1==			-		-			===			:=					•		
<u></u>			-				-4-		-	7."	⊫	Ξ.				:= 1		
	******		~ 4				- 44	** .**	- 12	i۰	т	14-	54 11		-			
Ш	11111W-1		₹.			٠.	31	** **	1	İ۳	!			*70		-	=	PAGE 1
• • • •	1784 by W Many	4		~~					1.	-	1	•••	/· w					
	and the second			****		1%	T.	****	1	١	t –		17:E					M-1
_								*,	1	ŧ۳	_					-13		
34.	P 44 - PAPER TALES		-						†÷	-	_		74.44			-	_=	
-			-	_	_					-	_		21-2			4.	-	
	*******					1		to the pear		t-	***		71.41	J L - 0 1 0 - 1 mm		2	2	
l			- •	12		1915	71	** * ; ;	┰	-			14-			77	-1	M.
_	Promi 2 174 4			0114			. 1	** //90*	+;	١.,		.,,	0.5					
			_						1							L:: L		
γ=:	b4							_				-						_
L										-7	25						-1	
١.,											=	. 1	=	<u></u>	- 1		-1	
_	A-18/47/	441		٠. ١	*			_	At we a	12.1	-	4	***	11 mm >			44	23
_		*>	_		$\overline{}$	•			11-00-1	200		ᆎ	114				-	
-			_	5.4	280		_			_					_			
_				_						_	"	41	*1-					
Ŀ.,	hitterna h mar	***		~ -	-	****	~	• 1	arer.	***	- 1	ना	***		PE %	- :	7	Ε:
	. 61 + 10 -		**	****			٠.	- 1		**: 1	-	44	***	7. · ·			;;†	=
	P**********		-				×					-1					÷	AF F
	y	V 100 V			** ***							-1	111	***				
_	*********				7 11							₽	***				=	•
20	450	20.44	-			0.47	_					Ť	***				-	
									'	٠,		-1	***	****		_	ᅄ	-
₧											.,	41	***					

Figure 6: Ground Support equipment




Audit Report					
Report No.	IAR-2023/042				
Area / Scope	GAM – JBPM BERTAM				
Date of audit	31 MAY - 01 JUNE 2023				







maintenance.repair.overhaul


Audit Report						
Report No.	IAR-2023/042					
Area / Scope	GAM – JBPM BERTAM					
Date of audit	31 MAY - 01 JUNE 2023					





Tool Control Register and Daily Maintenance Book





Toolbox Meeting Attendance Sheet Before and After Correction

Figure 8: Form

