






HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
1.	05-21-01 - 25/10/11/000/000/000 EQUIPMENTS AND FURNISHINGS - Pilot and copilot seats - Seat buckets and attachments. Visual check. GVI MOD: - Condition: - 350A77-0068-01 (-) AMM 25-21-00, 6-1	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>Handwritten signature</i>		15/8/23
2.	05-21-01 - 29/10/10/501/000/000 HYDRAULIC POWER - Single hydraulic generation system - Servocontrol. Check of the electrical system part. DI MOD: - <i>POST-MOD</i> Condition: - AMM 29-10-00, 5-1	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>Handwritten signature</i> 8012		17/08/2023
The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.			<i>Handwritten signature</i>		17/8/23

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JAGATHESAN	<i>Handwritten signature</i> 	17/08/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
3.	05-21-01 - 53/10/00/000/000/080 FUSELAGE - Transmission deck. Check. CLN GVI MOD: [PRE MOD 073362 // PRE MOD 073342] & POST AMM 53-10-00, 8-14 Condition: - AMM 53-10-00, 6-1	Satisfactory / Unsatisfactory . (Rectification Ref.....) NOT APPLICABLE DUE TO POST MOD 073362 & 073342	-	-	-
4.	05-21-01 - 53/10/00/000/000/120 FUSELAGE - Longitudinal bulkheads. Visual check. GVI MOD: PRE MOD 074349 Condition: - AMM 53-10-00, 6-2	Satisfactory / Unsatisfactory . (Rectification Ref.....)	JAA 8043	 16/8/23	16/8/23
The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.			A	 16/8/23	16/8/23

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JAGATHESON		16/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
5.	05-21-01 - 53/10/01/000/000/000 FUSELAGE - Tail rotor drive shaft bearing bracket mounts. Visual check of the bearing bracket mounts. GVI MOD: - Condition: - AMM 53-31-00, 6-4	Satisfactory / Unsatisfactory -(Rectification Ref.....)		 	15/8/23
6.	05-21-01 - 55/20/00/000/000/030 STABILIZER - Upper and lower fin. Check of skin. GVI MOD: - Condition: - AMM 55-20-00, 6-1	Satisfactory / Unsatisfactory -(Rectification Ref.....)		 	15/8/23

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JABETHESOI	 	15/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
7.	05-21-01 - 62/10/00/000/000/005 ROTOR (S) - Skin. Check the skin in the area between 900 mm and the blade tip. GVI MOD: - Condition: - AMM 62-11-00, 6-3	Satisfactory / Unsatisfactory . (Rectification Ref.....)	 8265	 	16/8/23
8.	05-21-01 - 62/10/20/601/000/040 ROTOR (S) - Stainless steel leading edge. Perform a sound check (tapping) to check bonding. DI MOD: PRE MOD 075058 Condition: - 355A11-0020-00 (-) 355A11-0020-01 (-) 355A11-0020-02 (-) 355A11-0020-03 (-) 355A11-0020-04 (-) 355A11-0020-06 (-) 355A11-0020-07 (-) AMM 62-11-00, 6-1	Satisfactory / Unsatisfactory . (Rectification Ref.....)	 8265	 	16/8/23

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JAGATHESAN	 	16/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
9.	04-20-00 - 62/30/00/000/000/160 ROTOR (S) - Non-rotating and rotating washplates. Greasing the bearing. LUB MOD: POST MOD 076187 // POST MOD 076188 Condition: - AMM 62-32-00, 3-1	Satisfactory / Unsatisfactory (Rectification Ref.....)	 8351	 	16/8/23
10.	05-21-01 - 62/30/00/000/000/205 ROTOR (S) - Rotating washplate – 4 contacts bearing. Inspection of free rotation. Operation to be performed from 5100 FH to 6600 FH of the OTL. DI MOD: - Condition: - Y51BB10843S2M74 (704A33651158) AMM 62-32-00, 6-8	Satisfactory / Unsatisfactory (Rectification Ref.....) <div style="border: 1px solid red; padding: 5px; margin-top: 5px;"> The Independent Inspection carried out for: <input checked="" type="checkbox"/> Correct Assy / Inspection <input checked="" type="checkbox"/> Locking <input checked="" type="checkbox"/> Correct sense of movement, range, operation On Areas / Components: Carried out in accordance with CAD 8601 Para 5.8 (b) 1st Insp Sign & Stamp 2nd Insp Sign & Stamp Date: 25/8/23 Date: 25/8/23 </div>	 8730	 	16/8/23
The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.				 	25/8/23

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JAGATHESON	 	25/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7600	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
11.	05-21-01 - 63/20/00/000/000/038 ROTOR DRIVE (S) - Oil filter - Filter element. Cleaning. CLN MOD: PRE MOD 077162 & PRE MOD 077175 Condition: - AMM 63-21-00, 3-1	Satisfactory / Unsatisfactory. (Rectification Ref.....) NOT APPLICABLE DUE TO POST MOD 077162 & POST MOD 077175	-	-	-
12.	05-21-01 - 63/20/00/000/000/065 ROTOR DRIVE (S) - Spectrometric Oil Analysis Program (SOAP). The sample must be taken during the inspection nearest to each due time. Oil monitoring using SOAP is optional. SDI MOD: - Condition: - AMM 60-00-00, 6-1	Satisfactory / Unsatisfactory. (Rectification Ref.....) OPTIONAL	-	-	-

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

Handwritten signatures and stamps

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT

"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"

NAME	SIGNATURE & STAMP	DATE
JAGATHESON	<i>Handwritten signature</i> and	15/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE: AS 350 B2	AIRCRAFT REG. 9M-TBL	SERIAL NO 4295	HOURS 5437.6	LDG/CYCLES 7650	TASK CARD NO HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
13.	05-21-01 – 63/30/00/000/000/100 ROTOR DRIVE (S) – MGB suspension cross bar. Check of laminated stops without removal. GVI MOD: - Condition: - AMM 63-31-00, 6-5	Satisfactory / Unsatisfactory . (Rectification Ref.....)		 	16/8/23
14.	05-21-01 - 65/10/00/000/000/003 TAIL ROTOR DRIVE - Tail rotor drive shaft. Condition check. GVI MOD: - Condition: - AMM 65-11-00, 6-11 AMM 65-11-00, 6-13 AMM 65-11-00, 6-14 AMM 65-21-00, 6-20	Satisfactory / Unsatisfactory . (Rectification Ref.....)		 	16/8/23

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
	 	16/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
15.	04-20-00 - 65/10/00/000/000/006 TAIL ROTOR DRIVE - Tail rotor drive shaft – Greasable bearing. Check without removal. GVI MOD: - Condition: - S93404 (704A33651181) AMM 65-11-00, 6-15	Satisfactory / Unsatisfactory: (Rectification Ref.....)	 8351	 	16/8/23
16.	05-21-01 - 65/20/00/000/000/055 TAIL ROTOR DRIVE - Spectrometric Oil Analysis Program (SOAP). The sample must be taken during the inspection nearest to each due time. Oil monitoring using SOAP is optional. SDI MOD: - Condition: - AMM 60-00-00, 6-1	Satisfactory / Unsatisfactory: (Rectification Ref.....) OPTIONAL	-	-	-

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JABETHSON	 	16/8/23


*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.


TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
17.	05-21-01 - 65/20/00/000/000/270 TAIL ROTOR DRIVE - Pitch change unit - Swivel bearing. Check. DI MOD: - Condition: - 350A33-2004-03 (-) 350A33-2004-05 (-) 350A33-2004-06 (-) 350A33-2030-00 (-) 350A33-2167-01 (-) AMM 65-21-00, 6-16	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>John</i> 8026	<i>[Signature]</i> 	25/8/23
18.	05-21-01 - 65/20/00/000/000/370 TAIL ROTOR DRIVE - TRH pitch change unit - Labyrinth seal - Lock washer. Check. GVI MOD: PRE MOD 076550 Condition: - AMM 65-21-00, 6-15	Satisfactory / Unsatisfactory . (Rectification Ref.....) NOT APPLICABLE DUE TO POST MOD 076550			

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.
END BALL	350A33-2150-01	MA116779	MA126432	20172636/22	01

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
<i>JAGATHESON</i>	<i>[Signature]</i> 	25/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (885650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/061
WORK DESCRIPTION: TO PERFORM 150H INSPECTION (MSM 05-21-01 & MSM 05-31-01)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
19.	05-21-01 - 65/20/00/601/000/060 TAIL ROTOR DRIVE - Pitch control lever - Yoke lugs. Check. DI MOD: - Condition: - AMM 65-21-00, 6-24	Satisfactory / Unsatisfactory . (Rectification Ref:.....) <div style="border: 1px solid red; padding: 5px;"> The independent inspection carried out for: <input checked="" type="checkbox"/> Correct Assy / inspection <input checked="" type="checkbox"/> Locking <input checked="" type="checkbox"/> Correct sense of movement, range, operation On Areas / Components: Carried out in accordance with CAD 8601 Para 5 B (b) <div style="display: flex; justify-content: space-around;"> <div style="border: 1px solid red; padding: 2px;"> 1st Insp Sign & Stamp Date: 23/8/23 </div> <div style="border: 1px solid red; padding: 2px;"> 2nd Insp Sign & Stamp Date: 25/8/23 </div> </div> </div>	<i>AA</i>		17/8/23
20.	05-31-01 - 47/50/10/000/000/030 WEAPONS ELECTRONICS - Flir - Turret - QDM. STAR SAFIRE II Cleaning CLN MOD: - Condition: - AMM 47-50-10, 2-1	Satisfactory / Unsatisfactory . (Rectification Ref:.....) NOT APPLICABLE DUE TO PART NOT INSTALLED			

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT

"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"

NAME	SIGNATURE & STAMP	DATE
JAGATHESON		17/8/23


*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.




HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5435.6	7660	HRSB/TBL/TC/2023/062
WORK DESCRIPTION: TO PERFORM 150H//12M INSPECTION (MSM 05-21-00 & MSM 05-31-00)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
1.	05-31-00 - 21/51/20/000/000/025 AIR CONDITIONING - Freon air conditioning system. Visual inspection of the system. GVI MOD: - Condition: - AMM 21-51-10, 6-1	Satisfactory / Unsatisfactory. (Rectification Ref.....) NOT APPLICABLE DUE TO SYSTEM NOT INSTALLED			
2.	05-21-00 - 62/20/00/000/000/205 ROTOR (S) - Starflex star. Checking B/C/D/F areas. GVI MOD: - Condition: - AMM 62-21-00, 6-1	Satisfactory / Unsatisfactory. (Rectification Ref.....)	<i>[Signature]</i> 8350	<i>[Signature]</i> 	16/8/23

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted. *[Signature]*  16/8/23

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JAGETHESOM	<i>[Signature]</i> 	16/8/23

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE: AS 350 B2	AIRCRAFT REG. 9M-TBL	SERIAL NO 4295	HOURS 5437.6	LDG/CYCLES 7680	TASK CARD NO HRSB/TBL/TC/2023/062
WORK DESCRIPTION: TO PERFORM 150H//12M INSPECTION (MSM 05-21-00 & MSM 05-31-00)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
3.	05-21-00 - 62/20/00/000/000/207 ROTOR (S) - Starflex star - Swivel bearing. Visual check and play check. GVI MOD: - Condition: - AMM 62-21-00, 6-2	Satisfactory / Unsatisfactory . (Rectification Ref.....)		 	16/8/23
4.	05-21-00 - 63/10/00/000/000/060 ROTOR DRIVE (S) - Flexible coupling. Visual check. VC MOD: - Condition: - AMM 63-11-00, 6-18	Satisfactory / Unsatisfactory . (Rectification Ref.....)		 	16/8/23

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

 16/8/23

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JAGGHEWSON	 	16/8/23



*Any signature appended at approval holder column constitutes as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/062
WORK DESCRIPTION: TO PERFORM 150H//12M INSPECTION (MSM 05-21-00 & MSM 05-31-00)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
5.	05-21-00 - 63/10/00/000/000/065 ROTOR DRIVE (S) - Hydraulic pump - Drive-belt and bearing. Check. VC MOD: - Condition: - AMM 63-11-00, 6-2 AMM 63-11-00, 6-15	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>Jin</i> P026	<i>Jin</i> 	17/8/23
6.	05-21-00 - 63/10/00/000/000/200 ROTOR DRIVE (S) - Hydraulic pump - Belt drive. Splines greasing. LUB POST MOD: PRE MOD 079561 & PRE MOD 079566 Condition: - AMM 63-11-00, 3-2	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>Jin</i> P026	<i>Jin</i> 	17/8/23

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
<i>JABERHESAW</i>	<i>Jin</i> 	17/8/23



*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/062
WORK DESCRIPTION: TO PERFORM 150H//12M INSPECTION (MSM 05-21-00 & MSM 05-31-00)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
7.	05-21-00 - 65/10/00/000/000/200 TAIL ROTOR DRIVE - Rubber sleeve. Visual check. VC MOD: POST MOD 079059 Condition: - AMM 65-11-00, 6-13	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>[Signature]</i>	<i>[Signature]</i> 	16/8/23
8.	05-21-00 - 21/21/00/000/000/000 AIR CONDITIONING - Heating pipe.P2 installation. Check of the condition of the heat insulation and to make sure that there is no corrosion on the visible parts. If necessary, replace the pipes in accordance with task 21-21-00, 4-2 (AMM). DI MOD: PRE MOD 074765//PRE MOD 074866 Condition: - AMM 21-21-00, 6-1	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>[Signature]</i>	<i>[Signature]</i> 	17/8/23

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
JAGATHESON	<i>[Signature]</i> 	17/8/23


*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.




HELISTAR RESOURCES SDN. BHD (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/062
WORK DESCRIPTION: TO PERFORM 150H//12M INSPECTION (MSM 05-21-00 & MSM 05-31-00)			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
9.	05-21-00 - 52/30/00/000/000/030 CARGO DOOR - Lateral cargo door. Functional test - Indicating system. FT MOD: - Condition: - AMM 52-31-00, 5-2	Satisfactory / Unsatisfactory . (Rectification Ref.....)	<i>Hjmi</i>	<i>Hjmi</i> 	17/08/2023
10.	05-21-01 - 62/30/00/000/000/320 ROTOR (S) - Scissors bushings and attachment bolts. Greasing. LUB MOD: - Condition: Sand-laden and/or dust-laden atmosphere REF.: AMM 62-33-00, 3-1	Satisfactory / Unsatisfactory . (Rectification Ref.....) NOT APPLICABLE DUE TO CLIMATIC CONDITION	-	-	-

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted. *Hjmi*  17/08/2023

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
MOHD HUZAIRI	<i>Hjmi</i> 	17/08/2023


*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.




HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/063
WORK DESCRIPTION: TO PERFORM 1M INSPECTION & 1M SIN 2740-S-25 KANNAD ELT STRAP CHECK			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
1.	05-35-00 - 21/51/20/000/000/040 AIR CONDITIONING - Freon air conditioning system. Check for correct operation if not used during 1 month. FT MOD: - Condition: - AMM 21-51-10, 5-1	Satisfactory / Unsatisfactory. (Rectification Ref.....) NOT APPLICABLE DUE TO NOT FITTED.	-	-	-
2.	05-25-00 - 25/66/20/000/000/010 EQUIPMENTS AND FURNISHINGS - Emergency locator transmitter. KANNAD INTEGRA AP-H (ER). Emergency Locator Transmitter Autotest. FT MOD: - Condition: - S1854501-01 (704A45737078) AMM 25-66-20, 5-1	Satisfactory / Unsatisfactory. (Rectification Ref.....) NOT APPLICABLE DUE TO NOT FITTED	-	-	-
The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.			<i>Hyami</i>	<i>Hyami</i> 	22/08/2023

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
MOHD HUZAIKI	<i>Hyami</i> 	22/08/2023



*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD (845650-K)
 c/o LOT 10, HELICOPTER CENTRE
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.


TASK CARD

AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	3680	HRSB/TBL/TC/2023/063
WORK DESCRIPTION: TO PERFORM 1M INSPECTION & 1M SIN 2740-5-25 KANNAD ELT STRAP CHECK			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
3.	05-25-00 - 25/66/34/000/000/020 EQUIPMENTS AND FURNISHINGS - Emergency locator transmitter. KANNAD 406 AF- KANNAD 121 AF-H- KANNAD 406 AF-H. Emergency Locator Transmitter Autotest. FT MOD: - Condition: - AMM 25-66-02, 5-1	Satisfactory / Unsatisfactory . (Rectification Ref.....)	A. 8459	Hjmm 	22/08/2023
4.	05-35-00 - 25/81/12/000/000/020 EQUIPMENTS AND FURNISHINGS - Onboard load release unit. Clean and check. CLN GVI MOD: - Condition: Salt-laden atmosphere AMM 25-92-00, 6-2	Satisfactory / Unsatisfactory . (Rectification Ref.....) NOT APPLICABLE DUE TO CLIMATIC CONDITION AND PART NOT FITTED	-	- 	-

The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
MOHD HUZAIRI	Hjmm 	22/08/2023



*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.



HELISTAR RESOURCES SDN. BHD. (845650-K)
 c/o LOT 10, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 (MIAC)
 SULTAN ABDUL AZIZ SHAH AIRPORT, 47200 SUBANG,
 SELANGOR, MALAYSIA.

TASK CARD



AIRCRAFT TYPE:	AIRCRAFT REG.	SERIAL NO	HOURS	LDG/CYCLES	TASK CARD NO
AS 350 B2	9M-TBL	4295	5437.6	7680	HRSB/TBL/TC/2023/063
WORK DESCRIPTION: TO PERFORM 1M INSPECTION & 1M SIN 2740-S-25 KANNAD ELT STRAP CHECK			MAINT. DATA / SOURCE REF.: HRSB/AMP/AS350B2/ISS.1/REV.3/DATED 11.03.2019 ALS/REV.13/DATED 05.04.2021, MSM/REV.23/DATED 23.05.2022, EMM/REV.27/DATED 28.02.2023		RAISED BY AND DATE: KUMARAN 08.08.2023

ITEM	TASK/DEFECT DESCRIPTION	TASK/RECTIFICATION CARRIED OUT	TECHNICIAN	APPROVAL HOLDER	DATE
5.	05-35-00 - 47/50/10/000/000/020 WEAPONS ELECTRONICS - Flir. Star SAFIRE II. Turret desiccant cartridge check. VC MOD: - Condition: - AMM 47-50-10, 3-1	Satisfactory / Unsatisfactory (Rectification Ref.....) NOT APPLICABLE DUE TO PART NOT FITTED	-	-	-
6.	Check of the KANNAD emergency locator transmitter attachment straps i.a.w. SIN 2740-S-25 REV.0	Satisfactory / Unsatisfactory (Rectification Ref.....)	<i>[Signature]</i> 8459	<i>[Signature]</i> 	22/08/2023
The aircraft or component is clear of all tools, equipment and any extraneous parts or material, and that all access panels removed have been refitted.			<i>[Signature]</i>	<i>[Signature]</i> 	22/08/2023

PART/S / COMPONENT/S / MATERIAL USED					
DESCRIPTION	PART NO.	SERIAL NO. OFF	SERIAL NO. ON	RELEASE DOC.	QTY.

MAINTENANCE RELEASE STATEMENT		
"Certifies that the work specified, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft/aircraft component is considered ready for release to service"		
NAME	SIGNATURE & STAMP	DATE
MOHD HUZAIRI	<i>[Signature]</i> 	22/08/2023

*Any signature appended at approval holder column constitute as maintenance release for that particular item/ task.

1. Approving Competent Authority / Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 20172636/22	
4. Organisation Name and Address AIRBUS HELICOPTERS Aéroport International Marseille Provence 13725 Marignane, France			5. Work Order / Contract / Invoice  ICU F021010120972309		
6. Item 001		7. Description END,BALL	8. Part No 350A33215001	9. Qty 1	10. Serial No MA126432
11. Status / Work NEW					
12. Remarks: THIS DOCUMENT HAS BEEN PRINTED FROM ELECTRONIC FILE. See ICU label for expiration date if applicable.					
13a. Certifies that the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> approved design data and are in a condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12		14a. <input type="checkbox"/> Part-145.A.50 Release to Service <input type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature  Electronic Signature on File		13c. Approval / Authorisation Number EASA.21G.0070	14b. Authorised Signature Electronic Signature on File	14c. Certificate / Approval Ref. No	14e. Date (dd mmm yyyy) 14. Feb. 2022
13d. Name LACOGNATA Francoise					
User / Installer Responsibilities					
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					