

Audit Report					
Report No.	SA/2021-001				
Area / Scope	GAM-PGU				
Date of audit	15/03/2021				

Α	AUDIT DETAILS					
		Tick where applicable				
1.	Audit Type / Category	<ul><li>□ Scheduled</li><li>⊠ Surveillance</li></ul>		Vendor Product Variation to approval		
		Specify: Surveillance audit on G	AM-PGU fa	acility		
2.	Audit Reference	Maintenance Organisation Exposition issue 2 revision 04 Airworthiness Notice 6501 AMO Audit Checklist				
3.	Auditor(s)	Luqman Hakim bin Mohd Aroff ( Mohamad Shafiq Ihsanudin bin		or)		
4.	Auditee(s)	Wan Muhd Faizal Rizza bin Moh	nd Rahim			
5.	Location	Pasukan Gerakan Udara Suban Semenanjung, Lapangan Terba				
В						
	A surveillance audit was carried out at GAM-PGU AW 139 facility to ensure compliance towards company procedures, as well as regulations published by the authority,.  Audit methodology was through observation at the workplace, and interview with personnel working during the shift.					
	The surveillance	llance covered the following elements:				
8	Tools     Facility					

No	Item		Compliance		Remark
INO			No	N/A	Kemark
	Facility				
1	Housekeeping – Cleanliness of hangar floor, Condition during and after maintenance	1			
2	Adequate lighting – Adequate to carry out task			1	
3	Noise – Ensure noise does not distract personnel from carrying out task			1	
4	Environment control – Schedule and general waste			1	
5	Hangar floor racks – unserviceable, holding rack, Item labeling for items placed on racks (Serviceable, U/S, holding label)	1			,
6	Storage of POL				
6.1	Availability of POL storage facility	1			
6.2	Control of POL – Labeling, POL control list (Total POL items available)		/		-Several contact cleane uncontrolled, without



Audit Report					
Report No.	SA/2021-001				
Area / Scope GAM-PGU					
Date of audit	15/03/2021				

					any label NCR 06 raised -Improper storage NCR 03 raised
6.3	Shelf life – Control of due date, de-can items,		/		-No due date recorded on several contact cleaners.
6.4	Availability of MSDS at the POL storage area for each item				
1	GSE Tools and Equipr	nent	Carlo Michigan		
1.1	Serviceability of equipment - Label and condition		1		- Unserviceable aircra tyre found stored on racking without any label. NCR 01 raised
1.2	Proper storage of GSE		1		- Several equipment were found to not be stored at their proper place when maintenance is not currently taking place NCR 07 raised
1.3	Performance of GSE preventive maintenance			/	
1.4	Availability of safety equipment on GSE, if required i.e – fire extinguisher on tow truck			/	
2	Tools and Equipment				
2.1	Tools Store conditions – General housekeeping in the tool store		/		Several tools were found improperly store NCR 05 raised
2.2	Availability of tools – Labeling, control number, Tool listing	1			
2.3	Control of in and out of tools– The usage of tools in and out register book, secure storage of tools		/		Keys to tool store four placed onto the table, without anyone's supervision. NCR 04 raised
2.4	Proper storage of tools – In store / during maintenance		/		Several tools were found improperly store Refer para 2.1.
2.5	Condition of tool – Serviceability (label, general condition)	1			
2.6	Calibrated tools – Control of calibrated tools, calibration information (sticker, etc.)			/	
2.7	Control of personnel tool – Registered, List of tools			/	
3	Material and consumable – Storage of materials at maintenance base.				
3.1	List of materials stored at maintenance base			/	
3.2	Storage condition and labeling			1	
3.3	Control of materials and consumables at maintenance base			1	



Audit Report					
Report No.	SA/2021-001				
Area / Scope	GAM-PGU				
Date of audit	15/03/2021				

	,				
1.1	Publication Master List – up to date			/	
1.2	Access to current maintenance data			1	
1.3 Registered PC – availability of current				/	
1.3	maintenance data				
2	Maintenance record – if available			/	
2.1	Control of maintenance record – Condition of			/	
2.1	storage				
2.2	Completeness of maintenance record – sample			1	
2.3	Backup of maintenance record – Hard drive			1	
2.4	Storage of worksheet, AJL etc in use, inside a			/	
2.4	secure environment.				
2.5	AJL, Work order and worksheet register at			/	
2.5	maintenance base				
	General				
1	Daily handover logbook				
1.1	Utilization of daily handover logbook –			/	
1.1	completeness, correct use of logbook.				
1.2	Record of FOD walk			/	
2	Aircraft				A E ではれ、C を 中国 A E A A E A E A E A E A E A E A E A E
2.1	Cleanliness			/	
2.2	Parking condition – shroud, covering, choke			/	
2.3	Storage condition			/	
3	Performance of maintenance		De la la		District Co.
3.1	Grounding of aircraft during maintenance	1			
3.2	Use of proper tools, equipment, etc.			/	
3.3	Maintenance data availability			/	
3.4	Proper carry out of maintenance		/		Cowling removed from aircraft without any holding label. NCR 02 raised.

## Findings and observations

- 1. Aircraft tyre stored at PGU AW139 hangar unserviceable rack was without any label.
- 2. Aircraft component removed from 9M-PMB was not tagged.
- 3. Several flammable fluids (contact cleaners) were stored improperly inside a consumable rack as inside the tool store.
- 4. Tool store key was not properly taken care of as it was found inside the tool store itself, without anyone attending to it.
- 5. Several tools were found improperly stored inside the tool store during the surveillance. They were stored onto a movable tray, in the middle of the store.
- 6. Several contact cleaners were not labeled.
- 7. Several equipments were found not properly stored at their designated place even when maintenance is not currently taking place.



Audit Report					
Report No. SA/2021-001					
Area / Scope	GAM-PGU				
Date of audit 15/03/2021					

С	PREPARATION AND APPROVAL
1.	Prepared by Signature:  Date: 06/09/2021.  Name: LUQMAN HAKIM 13. MOHD AROFF
2.	Approved by Signature:  Date: 06.69.20  Name:  Date: 06.69.20



Audit Report					
Report No. IAR-YYYY/0XX					
Area / Scope GAM-XXXX					
Date of audit DD/MM/YYYY					

## INSTRUCTION FOR COMPLETING GAM/Q-009, INTERNAL AUDIT REPORT

Report No.		Fill in audit report number, in accordance with quality department internal audit report register		
Area / Scope	Fill in the department / operation that Options are as follows:			
	GAM-CAMO GA	M-APMM		
	GAM-145 GA	M-FENNEC		
	GAM-VENDOR			
Date of audit	Fill in date of audit. If the audit takes each audit dates.	more than one day, specify		
	E.g.:			
	01/04/2021 - 03/04/2021 <b>OR</b>			
6 4/4)	01/04/2021, 03/04/2021 – 05/04/202			
Section A (1)	Select audit type/category as applical			
	restricted to only one type/category of			
	Specify the audit type/category select	ted in the space provided,		
	e.g.:			
	Tick where applicable			
	□ Scheduled □	Vendor		
	□ Surveillance □	Product		
		Variation to approval		
	Specify: Compliance audit for additional A maintenance	MO capability on Bell 429 aircraf		
Section A (2)	Fill in the audit reference inclusive of	regulation referred to.		
The state of the s	documents used during audit as well	1 N		
	referred to during the audit			
Section A (3)	Fill in names of auditors involved in tl	ne audit. Specify the lead		
	auditor with a label beside the name,	e.g.:		
	Omar bin Ahmad (Lead Auditor)			
Section A (4)	Fill in names of auditees involved in t	Fill in names of auditees involved in the audit		
Section A (5)	Fill in the address of the audit locatio	Fill in the address of the audit location.		
Section B		Fill in the summary of the audit, which could include audit		
	methodology, audit elements, observ	methodology, audit elements, observation, and finding.		
Section C (1)	Fill in signature and name of personn			
	report, as well as the date audit report was prepared			
Section C (2)	Fill in signature and name of personn			
	report, and the date of report approv	al.		