

 <p>Galaxy Aerospace maintenance . repair . overhaul</p>	Audit Report	
	Report No.	IAR-2023/050
	Area / Scope	GAM-AMO
	Date of audit	10-11/07/2023

Appendix 5



Tool ID No. CTE/177 (60640) torque wrench was sampled and found calibration sticker pasted on the tool was for CTE/30.



Tool ID No. CTE/30 torque wrench was sampled and found calibration sticker pasted on the tool was CTE/177.