

MODIFICATION

MODIFICATION STATUS LIST

Aircraft Registration:	9M-PST	Serial No:	172S9524	Date: 05/10/2023	Page No:	1
Aircraft Hours:	2112:07	Landings:	5590.00	Engine 1: 1595:13	Engine 2:	0:00

Туре	Maintenance Required	Reference	Life At Install	Period	Last Done	Next Due	Remaining
MOTOROLA ASTRO X	TL 5000 EQUIPMENT MODIFICATION		<u>'</u>	<u> </u>		<u>'</u>	
Modifications (Inspection)	INSTALLATION OF MOTOROLA ASTRO XTL 5000	MD 1010032, CAAM SC/2018/082/1		0 On Condition	-	-	-
FM SYSTEM ON CESSNA 172S							
Modifications (Inspection)	50H FM MOTOROLA INSPECTION	ICA 1010032 ISSUE 3, CAAM SC/2018/082/1		50 Airframe Hours	2074:31	2124:31	12:25 Hours
Modifications (Inspection)	100H//12M FM MOTOROLA INSPECTION	ICA 1010032, CAAM SC/2018/082/1		1 Years	06/06/2023	06/06/2024	242 Days
Modifications (Inspection)	100H//12M FM MOTOROLA INSPECTION	ICA 1010032, CAAM SC/2018/082/1		100 Airframe Hours	2066:52	2166:52	54:45 Hours
Modifications (Inspection)	PRE-FLIGHT - MOTOROLA ASTRO XTL 5000	ICA 1010032, CAAM SC/2018/082/1		0 On Condition	-	-	-
ı	EQUIPMENT						
ELT KANNAD INTEGRA MODIFICATION		Reference	Life At Install	Period	Last Done	Next Due	Remaining
Modifications (Inspection)	INSTALLATION OF EMERGENCY LOCATOR	MC1010071 (JANUARY 30,2015)	<u> </u>	1 On Condition	-	-	-
	TRANSMITTER ELT KANNAD AF INTEGRA ON						
	CESSNA 172S						
Modifications (Inspection)	1M INSPECTION - INSTALLATION OF	MD 1010071, ICA 1010038 REV. 1		1 Months	04/08/2023	04/10/2023	-5 Days
	EMERGENCY LOCATOR TRANSMITTER ELT						
	KANNAD AF INTEGRA ON CESSNA 172S.						
Modifications (Inspection)	12M INSPECTION - INSTALLATION OF	MD 1010071		12 Months	18/01/2023	18/01/2024	102 Days
	EMERGENCY LOCATOR TRANSMITTER ELT						
	KANNAD AF INTEGRA ON CESSNA 172S.						
,	100H INSPECTION - INSTALLATION OF MD 1010071		100 Airframe Hours	2094:17	2194:17	82:11 Hours	
	EMERGENCY LOCATOR TRANSMITTER ELT						
	KANNAD AF INTEGRA ON CESSNA 172S.						
Modifications (Inspection)	6Y ELT BATTERY REPLACEMENT SN	ACEMENT SN 432870		6 Years	31/05/2021	31/05/2027	1331 Days
	LX1100110869						
MODIFICATION FOR INSTALLATION FM SYSTEM OBSERVER		Reference	Life At Install	Period	Last Done	Next Due	Remaining
MIC/PHONE JACK PO	INT						
Modifications (Inspection)	INSTALLATION OF SYSTEM OBSERVER	MD 1010060 (DECEMBER 15, 2014)		0 On Condition	-	-	-
, , ,	MIC/JACK POINT ON CESSNA 172S						