

GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia

International Aerospace Centre, SAAS Airport,

Subang Malaysia

Attention: Mr. Syafrul Yamani

Engineering Manager

FURTHER EVALUATION OF SB 189-375

syafrul@galaxyaerospace.my

Work Order Number:	2023-16115
Work Pack Reference:	9M-BOF-16115
Date Issued:	17/06/2023
A/C Registration / SN:	9M-BOF/49053
-	

of

Description:

 Item
 Description/Task/Inspection

 1
 PHYSICAL CHECK TO VERIFY PN OF MR

 SWASHPLATE BOOT INSTALLED FOR

APPLICABILITY

Reference TIC-AW189-23-0074, SB NO. 189-375, NEW ISSUE

Sheet:

Man Hours
_____ (PLEASE ADVISE)

Remark/Notes:

- 1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards,

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



GALAXY AEROSPACE (M) SDN, BHD, [1040262-D] SALANT AEMOSTACE (m) SDIT. SRID.: [104U262-U] Suite 11-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my l nal Aerospace Centre,

WORKPACK

CLIENT/OWNER: JABATAN BOMBA DAN SERIAL NO. HOURS LDG/CYCLE WORKPACK NO: 9M-BOF-16115 PENYELAMAT MALAYSIA 49053 WORK/INSP/DESC: PHYSICAL CHECK **AIRCRAFT** AIRCRAFT TYPE: AW189 AERONET JOB NO.: 2023-16115 780225 REGISTRATION: 9M-BOF #1 ENGINE: BASE/FACILITY: MIAT AJL REF NO.: #2 ENGINE: 780234 1 OF 1 DATE IN: SHEET: OUT: NF/N2 NG/N1 Other requirements/information: Reason for raising: Raised by and date: CAMO: Husnina PHYSICAL CHECK TO VERIFY PN OF MR SWASHPLATE BOOT INSTALLED FOR SB NII 17/06/2023 189-375 APPLICABILITY I.A.W. SB NO. 189-375, NEW ISSUE DATED 14-JUNE-2023 & IETP A109E, 34TH ISSUE: 2023-06-06 List of scheduled inspection and all work carried out under this workpack Master Signature Schedule DATE including individual reference INSPECTION COMPLETED NO. INSPECTION / WORK WORKSHEET REF NAME SIGNATURE APP/STAMP PHYSICAL CHECK TO VERIFY PN OF MR 16115-001 SWASHPLATE BOOT INSTALLED FOR **FURTHER EVALUATION OF SB 189-375** APPLICABILITY NAME PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND SIGN & APPROVAL * OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE *IF DIFFERENT FROM ABOVE. OEM PUBLICATION/REVISION..... FIRM DATE * TICK WHERE APPLICABLE PART M - CAMO ACCEPTANCE STATEMENT NAME SIGN & APPROVAL THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE.



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7526
www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORKSHEET

CLIENT/OWNER: JABATAN BOMBA DAN SERIAL NO. **HOURS** LDG/CYCLE WORKSHEET NO: PENYELAMAT MALAYSIA REFER WORKPACK **AIRCRAFT** 49053 WORK/INSP/DESC: PHYSICAL CHECK AIRCRAFT TYPE: AW189 780225 REFER WORKPACK 9M-BOF-16115 #1 ENGINE: REGISTRATION: 9M-BOF WORKPACK REF: REFER WORKPACK 780234 REFER WORKPACK AJL REF NO.: #2 FNGINE BASE/FACILITY: REFER WORKPACK SHEET: 1 DATE IN: REFER WORKPACK OUT: REFER WORKPACK OF NG/N1 NF/N2 Reason for raising: Raised by and date: Other requirements/information: PHYSICAL CHECK TO VERIFY PN OF MR SWASHPLATE BOOT INSTALLED FOR SB CAMO; Husnina NIL 189-375 APPLICABILITY I.A.W. SB NO. 189-375. NEW ISSUE DATED 14-JUNE-2023 & 17/06/2023 IETP A109E, 34TH ISSUE: 2023-06-06 Technician * Eng. CRS Item Description Date 1 TO PERFORM PHYSICAL CHECK OF THE PN OF MR SWASHPLATE BOOT INSTALLED FOR FURTHER EVALUATION OF SB 189-725 APPLICABILITY REFERENCE: SB NO. 189-375, NEW ISSUE DATED 14-JUNE-2023 NOTE: PLEASE PROVIDE PHOTO AS EVIDENCE REMARK: The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the for the time being in force and in that respect the aircraft / equipment is considered fit for release to service. ☐ TICK ✓ WHERE APPLICABLE GROUND TORQUE MONITORED PLANNING AIRCRAFT ENGINE LOG OEM/COMP MOD RECORD LABELED & RETURNED INSP RUN LOG BOOK LOG CARD



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] SALDAT AEROSTACE (m) SDIT. SRIL: [104U252-U] Suite 11-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Fax: +603 7734 7526 www.galaxyaerospace.my| enquiry@galaxyaerospace.my nal Aerospace Centre.



CLIENT/OWNER: JABATAN BOMBA DAN SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 16115-001 PENYELAMAT MALAYSIA 49053 REFER WORKPACK WORK/INSP/DESC: PHYSICAL CHECK AIRCRAFT AIRCRAFT TYPE: AW189 780225 REFER WORKPACK WORKPACK REF: 9M-BOF-16115 #1 ENGINE: REGISTRATION: 9M-BOF REFER WORKPACK 780234 BASE/FACILITY: REFER WORKPACK #2 ENGINE: REFER WORKPACK AJL REF NO.: DATE IN: REFER WORKPACK OUT: REFER WORKPACK SHEET: OF NG/N1 NF/N2 REASON FOR RAISING: Raised by and date: CAMO; Husnina Other requirements/information: PHYSICAL CHECK TO VERIEY PN OF MR SWASHPI ATE BOOT INSTALLED FOR SB 189-375 NIL APPLICABILITY I.A.W. SB NO. 189-375, NEW ISSUE DATED 14-JUNE-2023 & IETP A109E, 34TH ISSUE: 17/06/2023 2023-06-06 Serial Number Lifed Item Information Item Part No. Description Qty Position Reason Release Reference TSN/TSO/DUE/TIMEX Off On NAME FIRM SIGN & APPROVAL DATE *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with _ and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK ✓ WHERE APPLICABLE



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7256 [Fax: +603 7734 7526]
www.galaxyaerospace.my | enquiry@galaxyaerospace.my

Tools Report



ircraft Serial No: 49053		Work Pack No: 9M-BOF-16115			15	
Aircraft Type:	AW189	DESC:	PHY	SICAL	CHECK T	О
Aircraft Reg:	9M-BOF	PAGE:	1	Of	1	

Aircraft Reg:			9M-BOF PAGE	: 1 Ot 1
Description	Part No	Serial Number	Worksheet Ref No. / Item No.	Calibration Due Date