



# LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

## Section 4

ATA Chapter 95

### AIRWORTHINESS DIRECTIVES AND BULLETINS COMPLIANCE

ASSY P/N (52)		3G9560V02131			ASSY S/N (53)		182				
AIRWORTHINESS DIRECTIVE AND MANDATORY BULLETINS					OPTIONAL BULLETINS						
AIRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)		ORGANIZATION (58)	STAMP AND SIGNATURE (59)	OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)		ORGANIZATION (58)	STAMP AND SIGNATURE (59)
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	ASSY TOTAL LIFTS/CYCLES (57)			ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	ASSY TOTAL LIFTS/CYCLES (57)		



# LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

## Section 1

ATA Chapter 95

DESCRIPTION (1)	P/N (2)	S/N (3)	MANUFACTURER NAME (4)	ASSEMBLY DATE (5)	RETIREMENT LIFE / TIME LIMITS (6)
FWD FLOAT LEFT ASSY	3G9560V02131	182	AERAZUR	03/2018	15 YEARS M/D
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

### ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL							
DATE (12)	A/C		ASSY			ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C		ASSY		REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
	R. MARKS (13)	TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)	TOTAL FLIGHT HOURS (20)			ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)			
	S/N (14)	TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS SINCE OH (17)	TOTAL LANDINGS (20)			ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)			
04/2020	9M-Pmf 31913	00.00	00.00	NEW	Leonardo Helicopters 	10 JUL 2020	9:50	9:50	-	NEW	DISASSEMBLED TO TRANSPORT BY AIR	GAM 	
		0	0	NEW			20	20	-	NEW			
12 JAN 2021	9M-PME 31855	390:55	9:50	NEW	GAM 	31 MAR 2021	495:55	144:50	-	NEW	OPERATION REQUIREMENT DUE FOR ANNUAL INSPECTION	GAM 	
		567	20	NEW			755	208	-	NEW			

### COMPONENTS INSTALLED ON ASSY

ASSY P/N (26)			3G9560V02131				ASSY S/N (27)		182		
COMPONENT DATA			INSTALLATION				REMOVAL				
DESCRIPTION (28)	P/N (29)	MANUFACTURING DATE (31)	ASSY		COMPONENT		ASSY		COMPONENT		
	S/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL HOURS (33)	TOTAL HOURS (34)	TIME SINCE OH (35)	DATE (36)	TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)
			TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)
			TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)		TOTAL LIFTS/CYCLES SINCE OH (41)	

FWD FLOAT LEFT BAG	3G9560V01651	03/2018	00.00	00.00	NEW	04/2020					
	163	ON CONDITION									

### ASSEMBLY ACTIVITY HISTORY

ASSY P/N (44)			3G9560V02131				ASSY S/N (45)		182		
DATE (46)	TOTAL HOURS (47)		TASKS (48)	ACTIVITIES (49)	ORGANIZATION (50)	STAMP AND SIGNATURE (51)					
	TOTAL LANDINGS (47)										
	TOTAL LIFTS/CYCLES (47)										
19/4/21	534:50	776	ANNUAL FLOAT INSPECTION	EMERGENCY FLOAT SERVICING DUE TO ANNUAL INSPECTION.	GAM						