



# LOG CARD

Section 1

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n° ..... 63  
Part n° .....

DESCRIPTION (1) <b>MAIN GEARBOX ASSY.</b>  C063-01	P/N (2) <b>3G6320A00134</b>	S/N (3) <b>R293</b>	MANUFACTURER NAME (4) <b>AGUSTA</b>	ASSEMBLY DATE (5) <b>NOVEMBER 09</b>	RETIREMENT LIFE (6) <b>5000 FH OH</b>
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

NOTES (12) DUE: 5000 HRS

## ASSEMBLY HISTORICAL RECORD

INSTALLATION							REMOVAL							
DATE (13)	A/C		ASSY			ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)					TOTAL TIME (23)	TIME SINCE OH (24)			
DEC. 09		31289	00.00	00.00	NEW	AGUSTA	A1 262							



AGUSTAWESTLAND

# LOG CARD

## Section 2

Chapter n° ..... 63

Part n° .....

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

REF. P/N: 3G6320A00134 S/N: R293

### LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
PUMP, LUBRICATION C063-05	3G6320V04252	0756	<del>2500</del> OH 5000	00.00	00.00	NEW	A1 262				
UPPER FITTING ASSY R024	3G6330A00232	R1699	95800 Land	00.00	00.00	NEW	A1 262				
FWR SERVO BRACKET ASSY	3G6230A02231	Q331	On Condition	00.00	00.00	NEW	A1 262				
MODULE INPUT SHAFT R024	3K6320A00136	KHI-650	On Condition	00.00	00.00	NEW	A1 262				
UPPER FITTING ASSY R024	3G6330A00232	R1691	95800 Land	00.00	00.00	NEW	A1 262				
UPPER FITTING ASSY R024	3G6330A00232	R1687	95800 Land	00.00	00.00	NEW	A1 262				
UPPER FITTING ASSY R024	3G6330A00232	R1709	95800 Land	00.00	00.00	NEW	A1 262				
PUMP, LUBRICATION C063-05	3G6320V04252	0733	<del>2500</del> OH 5000	00.00	00.00	NEW	A1 262				
MODULE INPUT SHAFT	3K6320A00136	KHI-643	On Condition	00.00	00.00	NEW	A1 262				
ANTITORQUE BEAM ASSY	3G6330A00532	Q471	20000FH/ 63000 Land	00.00	00.00	NEW	A1 262				
TOP CASE ASSY R021	3G6320A01035	Q263	120,000 LDG 17000 FH	00.00	00.00	NEW	A1 262				
MAIN CASE ASSY R023	3G6320A02738	Q254	5000 FH / 270 00 LDG 10000 FH/ 77500 Land.	00.00	00.00	NEW	A1 262				





# AGUSTA

AGUSTA WESTLAND

## LOG CARD

### Section 2

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

REF. P/N: 3G6320A00134 S/N: R293

Chapter n° ..... 63

Part n° .....

### LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
MAIN ROTOR SHAFT <i>RL022</i>	3G6320A01853	Q340	15300 FH/ 54000 Land	00.00	00.00	NEW	A1 262				
AFT SERVO BRACKET ASSY	3G6230A02331	Q662	On Condition	00.00	00.00	NEW	A1 262				
AFT SERVO BRACKET ASSY	3G6230A02331	Q661	On Condition	00.00	00.00	NEW	A1 262				