



LOG CARD

Section 1

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n° 63
Part n°

DESCRIPTION (1) MAIN GEARBOX ASSY. C063-01	P/N (2) 3G6320A00134	S/N (3) R297	MANUFACTURER NAME (4) AGUSTA	ASSEMBLY DATE (5) DECEMBER 09	RETIREMENT LIFE (6) 5000 FH OH
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

NOTES (12)

ASSEMBLY HISTORICAL RECORD

INSTALLATION								REMOVAL						
DATE (13)	A/C			ASSY		ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)					TOTAL TIME (23)	TIME SINCE OH (24)			
JAN. 10		31291	00.00	00.00	NEW	AGUSTA								



LENA SOCIETA' DI AGUSTAWESTLAND

LOG CARD

Section 2

Chapter n° 63

Part n°

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

REF. P/N: 3G6320A00134 S/N: R297

LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
PUMP, LUBRICATION C063-05	3G6320V04252	0754	2500 OH 5000 OH	00.00	00.00	NEW	A1 264				
PUMP, LUBRICATION C063-05	3G6320V04252	0753	2500 OH 5000 OH	00.00	00.00	NEW	A1 264				
FWR SERVO BRACKET ASSY	3G6230A02231	Q335	On Condition	00.00	00.00	NEW	A1 264				
MODULE INPUT SHAFT	3K6320A00136	KHI-654	On Condition	00.00	00.00	NEW	A1 264				
UPPER FITTING ASSY RL024	3G6330A00232	R1704	95800 Land 95600	00.00	00.00	NEW	A1 264				
UPPER FITTING ASSY RL024	3G6330A00232	R1696	95800 Land 95600	00.00	00.00	NEW	A1 264				
UPPER FITTING ASSY RL024	3G6330A00232	R1694	95800 Land 95600	00.00	00.00	NEW	A1 264				
MODULE INPUT SHAFT	3K6320A00136	KHI-655	On Condition	00.00	00.00	NEW	A1 264				
ANTITORQUE BEAM ASSY RL025	3G6330A00532	Q494	20000FH/ 63000 Land 120000 LDG	00.00	00.00	NEW	A1 264				
TOP CASE ASSY RL021	3G6320A01035	R270	17000 FH	00.00	00.00	NEW	A1 264				
MAIN CASE ASSY RL023	3G6320A02738	Q296	5000FH/27000 LDG 10000 FH/ 77500 Land	00.00	00.00	NEW	A1 264				
MAIN ROTOR SHAFT RL022	3G6320A01853	Q350	15300 FH/ 54000 Land.	00.00	00.00	NEW	A1 264				



LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Section 3

Chapter n°

Part n°

ACTIVITY RECORD

DATE (40)	ASSY TOTAL TIME (41)	TASK (42)	ACTIVITY (43)	DATE (44)	ORGANIZATION (45)	STAMP AND SIGNATURE (46)



LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Section 4

Chapter n° 63
Part n°

DIRECTIVES COMPLIANCE

MANDATORY DIRECTIVES

OPTIONAL DIRECTIVES

DIRECTIVE NUMBER (47)	ISSUE (48)	DATE OF COMPLIANCE (49)	ORGANIZATION (50)	STAMP SIGNATURE (51)	DIRECTIVE NUMBER (47)	ISSUE (48)	DATE OF COMPLIANCE (49)	ORGANIZATION (50)	STAMP SIGNATURE (51)